

South Bay Salt Pond Restoration Project



Levee Assessment

Submitted to:
California State Coastal Conservancy
U.S. Fish & Wildlife Service
California Department of Fish and Game

Prepared by:
Geomatrix Consultants

October 2006

TABLE OF CONTENTS

	Page
1.0 EXECUTIVE SUMMARY	1
2.0 INTRODUCTION	3
2.1 BACKGROUND	3
2.2 PURPOSE AND SCOPE OF WORK	3
2.3 PROJECT PERSONNEL	4
2.4 ORGANIZATION OF REPORT	5
3.0 DATA COMPILATION AND REVIEW	6
3.1 EXISTING REPORTS	6
3.1.1 Levee Assessment Reports	6
3.1.2 Subsurface Borings and Bay Mud Thickness	7
3.1.3 Cargill Maintenance Reports	7
3.2 REVIEW OF AERIAL PHOTOGRAPHS	8
3.3 FIELD RECONNAISSANCE	9
4.0 BASELINE LEVEE MODEL	11
4.1 SUBSURFACE CONDITIONS	11
4.2 LEVEE CONDITIONS	12
4.3 MAINTENANCE	14
5.0 LEVEE ASSESSMENT / GEOTECHNICAL CONSIDERATIONS	15
5.1 GENERAL	15
5.2 EXISTING OUTBOARD POND LEVEES	16
5.2.1 Subsidence	16
5.2.1.1 Subsidence From Consolidation of Bay Mud Within And Below Recent Pond Levee Fills	17
5.2.1.2 Subsidence From Consolidation of Bay Mud From Regional Groundwater Depletion	21
5.2.1.3 Subsidence From Liquefaction Of Loose Saturated Granular Deposits During An Earthquake	21
5.2.1.4 Subsidence From Consolidation of Deeper Santa Clara Valley Formation from Regional Groundwater Depletion	22
5.2.2 Stability	23
5.2.2.1 Static Stability of Levee Slopes	23
5.2.2.2 Seismic Stability of Levee Slopes	23
5.2.3 Erosion	23
5.3 PROPOSED INBOARD FLOOD LEVEES	27
5.3.1 Evaluations Performed By Moffatt & Nichol, 2005	27
5.3.2 Current Configurations of Proposed New Levees	27
5.3.3 Subsidence	28
5.3.3.1 General	28
5.3.3.2 Alviso	32
5.3.3.3 Ravenswood	32

**TABLE OF CONTENTS
(Continued)**

	Page
5.3.3.4 Eden Landing.....	33
5.3.4 Stability.....	33
5.3.4.1 Static Stability of Levee Slopes.....	33
5.3.4.2 Seismic Stability of Levee Slopes	34
5.3.5 Erosion.....	34
6.0 LIMITATIONS	35
7.0 REFERENCES	36

TABLES

Table 1	Maintenance Summary – Pond Complexes
Table 2	Maintenance Summary – Ponds
Table 3	Levee Conditions

FIGURES

Figure 1	Site Location Map
Figure 2	Bay Mud Thickness and Borings
Figure 3a	Levee Alignment Conditions - Alviso
Figure 3e	Levee Alignment Conditions - Eden Landing
Figure 3r	Levee Alignment Conditions - Ravenswood
Figure 4a	Levee Protection Type and Conditions - Alviso
Figure 4e	Levee Protection Type and Conditions - Eden Landing
Figure 4r	Levee Protection Type and Conditions- Ravenswood
Figure 5a	Observed Levee Distress- Alviso
Figure 5e	Observed Levee Distress - Eden Landing
Figure 5r	Observed Levee Distress- Ravenswood
Figure 6a	Levee Maintenance Summaries - Alviso
Figure 6e	Levee Maintenance Summaries - Eden Landing
Figure 6r	Levee Maintenance Summaries- Ravenswood
Figure 7	Proposed Levee Alignments

TABLE OF CONTENTS (Continued)

PHOTOGRAPHS

Photograph 1	Example of levee without slope protection (Pond R3 Northeast)
Photograph 2	Example of levee with vegetation slope protection (Pond B2 Northwest)
Photograph 3	Example of levee with broken concrete slope protection (Pond B10 West)
Photograph 4	Example of levee with engineered riprap slope protection (Pond SF2 Southeast)
Photograph 5	Example of levee with wood shoring slope protection (Pond B10 North)
Photograph 6	Example of cracking distress of levee crest (Pond A12 East)
Photograph 7	Example of previous breach and overtopping distress of levee with subsequent poor repair (Pond B2 West)
Photograph 8	Example of undercutting and severe erosion distress of levee slope (Pond BT1 Southwestern point)
Photograph 9	Example of gullying and severe erosion distress of unprotected levee slope (Pond B2 South)
Photograph 10	Example of severe erosion distress of levee slope and crest (Pond BT2 North)

PLATE

Plate 1	Boring logs compiled within and proximal to the SBSP Project study area
---------	---

APPENDIXES

Appendix A	Summary of Boring Logs
Appendix B	USACE 1988 Levee Survey Summary
Appendix C	Moffat & Nichol, 2005 Levee Survey Summary
Appendix D	Levee Maintenance Summary

LEVEE ASSESSMENT

South Bay Salt Pond Restoration Project

Bay Area, California

1.0 EXECUTIVE SUMMARY

This report summarizes Geomatrix's assessment of existing levees for the South Bay Salt Pond Restoration Project. The focus of the assessment is program level evaluation of geologic and geotechnical factors contributing to:

- the conditions of outboard pond levees as described during the 1984 reconnaissance surveys performed by the Army Corp of Engineers in support of the reports entitled "Office Report, San Francisco Bay Shoreline Study, Southern Alameda and Santa Clara Counties Interim", dated October 1988, and "Office Report, San Francisco Bay Shoreline Study, San Mateo and Northern Alameda Counties Interim", dated September 1989.
- the observed and documented changes in conditions of outboard pond levees since the 1984 reconnaissance surveys performed by the Army Corp of Engineers, and
- the planning of proposed new inboard flood control levees.

The assessment includes development of a baseline levee model which compiles readily available existing data from multiple sources including multiple geotechnical reports, maintenance records, aerial photos, and field reconnaissance surveys. Significant reports referenced in the baseline levee model include:

- "Baylands Salt Water Flood Control Planning Study", prepared by Tudor Engineering Company, dated January, 1973.
- "Urban Levee Flood Management Requirements South Bay Salt Pond Restoration Project", prepared by Moffatt & Nichol Engineers, dated January, 2005.
- "Office Report, San Francisco Bay Shoreline Study, Southern Alameda and Santa Clara Counties Interim", prepared by the U.S. Army Corps of Engineers, dated October 1988.
- "Office Report, San Francisco Bay Shoreline Study, San Mateo and Northern Alameda Counties Interim", prepared by the U.S. Army Corps of Engineers, dated September 1989.

Two years of aerial photographs were reviewed (1988/1989, 1999). The 1999 interval was selected based on photo completeness and quality, to represent relatively recent conditions. The 1988/1989 interval was selected based on photo completeness and quality, to represent post heavy precipitation and flooding conditions experienced during the winter of 1986-87.

Limited field reconnaissance was performed by Geomatrix personnel in September 2006 to observe current conditions and verify, by observation and simple field measurement, existing features of select SBSP levees identified during the review and compilation of previous reports, maintenance records, and aerial photo review.

The baseline levee model consists of a geospatial database that describes the subsurface, levee and maintenance conditions across the study area. The baseline levee model is used to describe and visualize levee conditions in support the levee assessment.

For existing outboard pond levees, the levee assessment discusses the following general mechanisms of observed and documented levee degradation:

- subsidence,
- stability, and
- erosion.

The approximate quantity and size of past levee grading and erosion maintenance activities are summarized for each pond complex. Approximate return rates for past levee grading and erosion maintenance activities are presented. These return rates can be extrapolated to estimate future levee maintenance needs.

For proposed inboard flood control levees, significant quantities of new fill are anticipated to substantially raise levee crest elevations for increased flood protection. The levee assessment discusses the following additional mechanisms of levee degradation and considerations anticipated from the new fill placement planned:

- subsidence, and
- stability.

The locations and alignments of proposed inboard flood control levees currently being considered by the SBSP Restoration Project team are similar to those previously evaluated by Moffat & Nichol, 2005. Relevant findings from the Moffat & Nichol, 2005 report are incorporated into the assessment of proposed inboard flood control levees.

2.0 INTRODUCTION

The overarching goal of the SBSP Restoration project is the restoration and enhancement of wetlands in the South San Francisco Bay while providing for flood management and wildlife-oriented public access and recreation. In achieving this goal, the project is committed to maintaining or improving existing levels of flood protection in the South Bay area. The condition and projected performance of existing and proposed new levees are therefore critical considerations. Understanding the geologic and geotechnical framework of the SBSP Restoration project area, and the geologic and geotechnical conditions contributing to the current performance of the existing levees, is integral to the success of assessing flood control, project planning, and future levee design.

2.1 BACKGROUND

The SBSP Restoration project area includes the Ravenswood and Eden Landing pond complexes shown on Figure 1. With authorization of the concurrent Shoreline Study project, the SBSP Restoration project also includes the Alviso pond complex shown in Figure 1.

The SBSP restoration alternatives are described in the SBSP Restoration Project Final Alternatives Report (PWA and others, 2006). The report identifies three restoration alternatives: 1) No Action; 2) the Tidal Habitat Emphasis Alternative; and 3) the Managed Pond Emphasis Alternative; plus the Adaptive Management process for implementing the restoration.

The evaluations and assessments performed for the SBSP Restoration project are generally at a program, broad planning scale, level of detail.

2.2 PURPOSE AND SCOPE OF WORK

The purpose of this study was to develop a geotechnical/geological assessment of existing levees within the SBSP Restoration project area. The assessment includes existing outboard pond levees within the SBSP Restoration project area, as well as proposed new inboard flood control levees.

To achieve this goal, Geomatrix first developed a baseline levee model to characterize the conditions of existing levees within the project area. The baseline levee model includes various readily available data sets (aerial photos, subsurface explorations, reconnaissance surveys, maintenance records, etc.) gathered from numerous sources, compiled into a single GIS

database. No new field geotechnical investigations were performed for this study. The existing data gathered, spans decades and is used to present snapshot portrayals of various levee conditions on select dates, as well as to illustrate general levee progression, or regression, over time. The baseline levee model captures geotechnical information valuable for future project design and planning efforts.

The baseline levee model was then used to describe and visualize levee conditions to support the levee assessment. The information compiled in the baseline levee model was organized to illustrate changes in conditions of the project levees, and maintenance requirements, over the past 20 years. Levee erosion, and subsidence, as well as Cargill maintenance operations from 1995 through 2005 were evaluated and are discussed. Specific seismic deformation and stability evaluations were beyond the scope of this assessment.

The results of this assessment will be used in subsequent SBSP Restoration project tasks and subtasks to estimate program level project impacts related to geology and soils, as well as to estimate the scope and cost of potential levee improvements as they pertain to the various restoration alternatives under consideration.

This programmatic-level geologic and geotechnical assessment was prepared in accordance with the Professional Services Consulting Agreement between PWA Consultant, Inc. (PWA) and Geomatrix, dated June 2006. This agreement contains a detailed description, by task, of the scope of work described above.

2.3 PROJECT PERSONNEL

The work described in this report was coordinated with the following individuals:

- Michele Orr, Project Manager, PWA
- Steve Ritchie, Program Manager

Key Geomatrix personnel who participated in the study included:

- Meghan Koch – Staff Engineer
- Kevin Burlingham – Staff Engineer
- Ron Rubin – Staff Geologist
- Robert Wright, Ph.D., CEG – Senior Geologist

- Chris Coutu, P.E. – Senior Engineer
- Timothy I. Mote, Ph.D., CEG, GISP - Project Manager/Senior Geologist
- Faiz Makdisi, Ph.D., P.E. – Principal-in-Charge

2.4 ORGANIZATION OF REPORT

A brief project description and background information was given in Sections 2.0 and 2.1. A review of the existing geologic/geotechnical data prepared by other consultants in the SBSP Restoration project area is described in Section 3.1. The review of aerial photographs and historic topographic maps and the field reconnaissance conducted in the SBSP Restoration project area are described in Sections 3.2 and 3.3. Section 4.0 describes the baseline levee model developed to assist in Levee Assessment. Section 5.0 discusses Geotechnical Considerations and Levee Assessment. References used in this study are presented in Section 7.0.

This report includes four appendixes that correspond to the Baseline Levee Model. Appendix A includes existing subsurface data that was compiled and reviewed as part of our geotechnical/geologic evaluation and characterization. Appendix B is a summary of the USACE 1984 Levee Reconnaissance Survey. Appendix C is a summary of the Moffat and Nichol Engineers, 2005, Levee Reconnaissance Survey. Appendix D is a summary of Cargill 1995 to 2005 Levee Maintenance Reports.

3.0 DATA COMPILATION AND REVIEW

Levee conditions and subsurface data for the South Bay and the SBSP Restoration Project area were evaluated using existing published data. Sources of data included the following:

3.1 EXISTING REPORTS

Geomatrix reviewed existing geologic/geotechnical data of several private and public agencies. Subsurface information that was judged to be pertinent to the characterization of levee and subsurface conditions within and proximal to the SBSP Restoration project area was collected and summarized.

3.1.1 Levee Assessment Reports

Files from four major reports prepared by Tudor Engineering company (Tudor, 1973), the U.S. Army Corps of Engineers, San Francisco District (Corps, 1988 and 1989), and Moffatt & Nichol Engineers (Moffatt & Nichol, 2005).

The Tudor (1973) report describes a compilation of known existing geotechnical exploration data collected within the Baylands (southern Alviso) area through 1972. Contours of thickness of Bay Mud were developed from the existing exploration data.

The Corps (1988) report describes a levee and shoreline condition survey that was performed between March and May 1984. The information collected for each levee segment included: the width and condition of the levee crest; the lengths, angles, and condition of the embankment slopes; the type and condition of slope protection; the embankment soil type; and other pertinent information including evidence of slumping, cracking, erosion, or seepage. This data is summarized in Appendix B.

In 2005, Moffatt & Nichol prepared a report for the California State Coastal Conservancy to summarize evaluations performed for then current configurations of new inboard flood control levees throughout the SBSP Restoration Project area, which could function as perimeter (Bayfront) levees after implementation of the proposed restoration project. The alignments of the new inboard flood control levees, evaluated by Moffat & Nichol, are similar to those currently being considered by the SBSP Restoration Project team. Evaluations performed by Moffatt & Nichol, 2005 are incorporated into the discussion of proposed inboard flood control levees (Section 5.3). Limited field reconnaissance data gathered by Moffat & Nichol in support of their 2005 report are summarized in Appendix C.

3.1.2 Subsurface Borings and Bay Mud Thickness

587 boring logs compiled within and proximal to the SBSP Project study area (Plate 1) were interpreted by a geologist to identify and summarize key geologic units essential to engineering evaluation including thickness and depth of stratigraphic units (i.e. fill, alluvium, Bay Mud, etc.), thickness of liquefiable layers, and depth to bedrock. The geologic data was integrated into a geotechnical database (Appendix A). Where borehole (or well) collar coordinates was not provided, locations were digitized from historic maps in order to link to the GIS. Borehole header information (data source, driller, drill type, date, etc.) was included when available.

We suspect that more geotechnical data exists. We have made many attempts to contact private and public land owners, utility operators, agencies, etc. The data presented in Plate 1 and Appendix A represents all data that we've been able to access and specifically locate.

A map of bedrock outcrops was extracted from the general distribution of geologic materials in the San Francisco Bay Region (Wentworth, 1997).

Liquefaction susceptibility (Knudsen and others, 2006) was based on sub-surface conditions including soil type, soil thickness and depth to groundwater.

3.1.3 Cargill Maintenance Reports

A summary of Cargill maintenance reports was compiled for the years 1995-2005. This data is summarized in Appendix D. The total number and amount of repairs completed for each pond complex is presented in Table 1 and the summations of events and amount of material used for each pond are included in Table 2.

The reports obtained summarized maintenance activities requiring permits from the San Francisco District Corps of Engineers and the San Francisco Bay Conservation and Development Commission such as: grading of the levees, discing of material, maintaining rip rap, and construction of new levees. The data typically included a general description, approximate duration, and general amount of materials required for each activity.

Grading activities included: routine grading of the levee top to provide vehicle access, building up low spots, and placing dirt fill to raise the levees. These activities were carried out using both dredging and land-based equipment.

Discing activities consisted of discing dredged material placed on the top of the levees.

Erosion related activities included widening eroded areas, and placing/replacing riprap to sustain the effectiveness of slope protection in those areas.

Levee construction included the construction of division levees inside the existing ponds. This was completed to improve the overall system of ponds.

The maintenance records were edited and simplified to summarize activities relevant to this assessment. Operational activities (e.g. gate maintenance) were not considered relevant to this study and therefore were not included.

There were some limitations in the maintenance data. The descriptions of the activities often did not fully explain the type and quantity of work performed. Sometimes the descriptions were too general to differentiate between maintenance activities. Quantities of materials (riprap, fill, etc) used during maintenance were inconsistently reported, sometimes quantified as footage, sometimes as volumes, sometimes not quantified. Thus the values for the amount of material placed should not be used in comparisons of the ponds. Other problems with the data include the conflict between discing and grading. In the description for discing, the reports state that dredged material was placed on top of the levee, but no entry for that placement of material could be correlated with the discing entry. Another example of the limitations of the data include an entry on the placing of pilings and sheet piles that does not state whether they are being used temporarily to assist in the installation of other equipment or if they are permanent.

We have edited the data such that these limitations of the data are minimized so that useful information can still be taken from the maintenance report data.

3.2 REVIEW OF AERIAL PHOTOGRAPHS

Two sets of stereo-paired, black and white aerial photographs were examined with a stereoscope to assist in the evaluation and identification of levee conditions, and other potential geologic/geotechnical hazards within the project area. The sets reviewed include:

Year	Scale
1988/1989	1:12,000
1999	1:12,000

The photographs document conditions along the levees at the time the photographs were taken. Comparison of landform features observed in the photographs and other data sources (i.e.

USACE 1988), allow for interpretations of changes in conditions over time (i.e., between 1984 to 1999). Conditions/features identified on the photographs include general levee condition, protection type/condition and evidence of distress. Examples of distress include erosion, undercutting/gullying, cracking, seepage, breaching, over-topping, and slumping.

The observed conditions/features were noted on maps of the study area and integrated into the baseline levee model to support engineering evaluations.

3.3 FIELD RECONNAISSANCE

Geomatrix personnel performed a field reconnaissance of the SBSP Restoration Project area on September 20, 21, and 22, 2006. Geomatrix's field reconnaissance consisted of observing current conditions and verifying, by observation and simple field measurements, existing features of select SBSP levees identified during the review and compilation of previous reports, maintenance records, and aerial photograph review.

The majority of the levees surrounding ponds within the Alviso, Eden Landing, and Ravenswood complexes were accessed and observed during Geomatrix's reconnaissance. Entry onto the Don Edwards San Francisco Bay Wildlife Refuge (Alviso and Ravenswood Pond Complexes) were coordinated with representatives of the US Fish and Wildlife Service. Entry onto the Eden Landing Pond Complex was coordinated with representatives of California Department of Fish and Game. Many of the levees were accessed by Geomatrix personnel traveling in vehicles. Several of the levees were accessed by Geomatrix personnel traveling on foot.

Conditions observed by Geomatrix field personnel during the field reconnaissance were digitized into the baseline levee model, and are summarized in Table 3. Levees were generally referenced by their position (north, south, east, west) relative to adjacent ponds. Digital photographs were taken along the levees to document typical and significant levee conditions/features relevant to the assessment. Select photographs are presented in the attached Photographs Section of this report to exemplify levee conditions.

Conditions/features identified during Geomatrix's field reconnaissance were categorized in a manner that was generally consistent with previous reconnaissance efforts by the USACE (1989) and Moffatt & Nichol Engineers (2005). Features observed and summarized include general levee condition, evidence of distress, and slope protection type/condition. Levee conditions of interest include crest condition, slope condition, toe condition, visually apparent

signs of distress, slope protection type, and slope protection condition. Signs of distress observed by Geomatrix included erosion, undercutting/gullyng, cracking, seepage, breaching, over-topping, and slumping. An examples of cracking distress is presented as photograph 6 in the attached Photos Section of this report. An example of poorly repaired breaching, and over-topping distress is presented as photograph 7 in the attached Photos Section of this report. An example of undercutting distress is presented as photograph 8 in the attached Photos Section of this report. An examples of gullyng distress is presented as photograph 9 in the attached Photos Section of this report. Example of erosion distress are presented as photographs 8, 9, and 10 in the attached Photos Section of this report.

4.0 BASELINE LEVEE MODEL

A baseline levee model was developed to document the conditions and performance of the levees over the last 20 years. The model describes subsurface conditions, levee conditions, and maintenance activities. Maps generated from the baseline levee model are used to support evaluation of geotechnical considerations and evaluate the specific pond complexes within the context of the three project alternatives. The implementation of the baseline levee model in the execution of the levee assessment is discussed in the geotechnical considerations sections. Description of the subsurface conditions, levee conditions, and maintenance activities components of the baseline levee model are presented below.

4.1 SUBSURFACE CONDITIONS

The occurrence, thickness, consistency, and engineering properties of Bay Mud, and loose saturated granular (potentially liquefiable) soils are expected to heavily influence the future performance of existing outboard pond levees, as well as the design of new or improved inboard flood control levees. The subsurface conditions component of the baseline levee model consists of a Bay Mud thickness map (isopach) from compiled geotechnical exploration data, and a liquefaction potential map.

The Bay Mud thickness map is derived from observed contacts from historic geotechnical exploration data. Tudor (1973) presents a map for Bay Mud thickness contour map for the South Bay compiled from several hundred borings. This contour map was digitized and updated with data from borings drilled subsequent to the Tudor report. Surface mapping of bedrock outcroppings by Wentworth (1997) helped define the limits where the Bay Mud pinches out.

Liquefaction susceptibility (Knudsen and others, 2006) is based on subsurface conditions including soil type, soil thickness and depth to groundwater. This is a generalized map developed for the nine county San Francisco Bay Area. To support future design and detailed assessments the boring data, which includes thicknesses of liquefiable units, will be used.

Figure 2 summarizes subsurface conditions in terms of liquefaction potential and Bay Mud thickness for the project area.

4.2 LEVEE CONDITIONS

The levee conditions component of the baseline levee model characterizes the levee alignment, levee protection, and catalogs evidence of distress. The sources of this data are the USACE, 1988, 1989 and Moffatt & Nichol, 2005 reports integrated with the aerial photograph review and field reconnaissance of this study (Geomatrix 2006).

Observations of levee alignment, levee protection, and evidence of distress are compiled in a database georeferenced to levee stretches. The database is a subset of key fields from the USCAE, 1988, survey methodology where the alignment, distress, and protection are parameterized in specific database fields.

Levee condition parameters include (database fields are shown in *bold italics* font):

<i>Complex</i>	Alviso, Eden Landing, Ravenswood
<i>Pond ID</i>	Unique identifier for Ponds
<i>Levee Orientation</i>	The orientation of the levee relative to the pond
<i>Crest, Slope, and Toe Condition</i>	Good, Fair, Poor
<i>Evidence of Distress</i>	
<i>Cracking</i>	= CR
<i>Seepage</i>	= SE
<i>Overtopping</i>	= OV
<i>Slumping</i>	= SL
<i>Breach</i>	= BR
<i>Undercutting/Gullying</i>	= UN
<i>Erosion</i>	= ER
<i>Erosion Intensity</i>	Severe, Intense, Moderate, Slight
<i>Protection Condition</i>	Good, Fair, Poor
<i>Protection Type</i>	Vegetation, riprap, broken concrete, other.
<i>Data Source</i>	USACE (1988), M&N (2005), GMX (2006)

The descriptive values for the levee and protection condition fields are qualitative in nature. The numerous reports and professional assessments of the levees over the years proved difficult to enforce consistency. For this study we consider “Good” to imply that the “Levee is performing”, “Fair” implies that the “Levee is performing, but there are slight signs of distress”, and “Poor” implies that “Levee shows significant signs of distress and/or failure”.

The levee conditions component of the baseline levee model is presented in Table 3.

A series of maps for the pond complexes were generated from the baseline levee model to describe the levee conditions where data was available. The maps present the general levee condition, type/condition of levee protection, and evidence of distress, by graphically presenting a number of appropriate model fields. The parameters presented in these maps are a subset of fields describing the data which summarizes the critical features of the levees. The complete baseline levee model (Table 3) contains more detail than presented on the figures of this draft report. Other combinations of data, including comparisons, can be presented using the baseline levee model. Baseline data, not specifically presented in the figures of this draft report may also assist in future project specific detailed geotechnical evaluations.

Figures 3a, 3e, and 3r are a series of maps for each respective pond complex (Alviso (a), Eden Landing (e), Ravenswood (r)) showing summarized levee alignment conditions for the crest, slope and toe. These figures include data compiled from multiple sources. Where overlapping data exists, that from the most recent source is presented. Levee conditions in Figures 3a, 3e, and 3r are labeled and color coded good (blue), fair (yellow) and poor (red).

Figures 4a, 4e, and 4r are a series of maps for each respective pond complex showing summarized levee protection type and conditions. These figures include data compiled from multiple sources. Where overlapping data exists, that from the most recent source is presented. Slope protection types (broken concrete, riprap, vegetation, other) for each levee are indicated on Figures 4a, 4e, and 4r by symbols. Examples of the various slope protection types are illustrated in photographs 1 through 5 in the Photograph Section of this report. Slope protection conditions in Figures 4a, 4e, and 4r are color coded: good (blue), fair (yellow), and poor (red).

Figures 5a, 5e, and 5r are a series of maps for each respective pond complex summarizing observed levee distresses. These figures include data compiled from multiple sources. Where overlapping data exists, that from the most recent source is presented. The types of observed levee distress are labeled on Figures 5a, 5e, and 5r. Examples of the various levee distress

types observed by Geomatrix during recent reconnaissance are illustrated in photographs 6 through 11 in the Photograph section of this report. Erosion intensity presented on Figures 5a, 5e, and 5r is color coded: severe (magenta), intense (red), moderate (brown), and slight (green).

4.3 MAINTENANCE

The maintenance component of the baseline levee model characterizes the levee maintenance over the last decade in terms of type of maintenance, repair and volume (when reported). Refer to section 3.1.3 for details on the compilation of the maintenance records (Table 1, Table 2, and Appendix D).

Figures 6a, 6e, and 6r are a series of maps for each respective pond complex showing maintenance efforts to repair erosion and subsidence for the time period 1995 to 2005. Since the volume of material used in the repairs was not consistently reported, these figures present both the number of repair events and the volume. The type of repair has been broken into two components: grading events to repair subsidence and riprap placement to address erosion. Both of these events are shown as a bar chart for each pond. A summary table also is included on each figure.

The frequency and type of repair are further discussed in the Section 5.0.

5.0 LEVEE ASSESSMENT / GEOTECHNICAL CONSIDERATIONS

5.1 GENERAL

The major geotechnical issues for levees within the SBSP Restoration project are:

- Relatively low strength and high compressibility of Bay Mud that exists within and below most of the existing levees;
- Potential liquefaction, and related hazards (lateral spreading), of loose saturated granular soils within and below many of the existing levees.

Almost all of the levees within the SBSP Restoration Project area are underlain by very soft, highly compressible, unconsolidated Bay Mud, and moderate to high (and in some locations very high) liquefiable susceptibility granular deposits. The specific locations thicknesses, and characteristics of these weak deposits should be considered while evaluating the lifespan and performance of existing outboard pond levees as well as while evaluating and designing proposed new inboard flood control levees. Contours of thickness of Bay Mud in the SBSP Restoration Project area are presented in Figure 2. Liquefaction susceptibility for the SBSP Restoration Project area (Knudsen and others, 2006) based on soil type, soil thickness and depth to groundwater is also presented in Figure 2.

The existing outboard pond levees were primarily constructed by excavating materials from within the ponds with the use of a dragline or clamshell and casting the excavated material to the side to form the levees. Periodically the levees were raised and widened using the same approach. Most of the salt pond levees consist predominantly of “cast-up” Bay Mud (Moffatt & Nichol, 2005).

Existing outboard pond levees within the SBSP Restoration Project area have been subject to the following mechanisms of levee degradation:

- subsidence resulting from ongoing consolidation of Bay Mud within recent pond levee fills;
- subsidence resulting from ongoing consolidation of Bay Mud beneath recent pond levee fills;
- subsidence resulting from ongoing consolidation of Bay Mud from regional groundwater depletion;

- subsidence resulting from liquefaction of loose saturated granular deposits during an earthquake;
- subsidence from consolidation of deeper Santa Clara Valley formation from regional groundwater depletion;
- slope failure resulting from liquefaction of loose saturated granular deposits during an earthquake;
- erosion.

Levee subsidence and erosion are expected to continue into the future. The rate and degree of existing pond levee degradation has in the past, and can in the future, be controlled with periodic levee maintenance. From Cargill maintenance records, we can quantify select maintenance activities performed between 1995 and 2005. These maintenance data are reasonably complete and allow for the most direct interpretation of levee maintenance required over a specified timeframe. This data can then be extrapolated as a means of estimating future maintenance needs for the SBSP Restoration project.

Proposed inboard flood control levees within the SBSP Restoration Project area will be designed for a certain lifespan and will account for the mechanisms of levee degradation discussed above. Proposed inboard flood levees are however expected to be subject to the following additional mechanisms of degradation which should also be considered during evaluation and design:

- subsidence resulting from additional consolidation of Bay Mud under the weight of new flood levee fills;
- slope failure resulting from overstressing (adding significant thicknesses of new fill) existing weak levee materials and underlying foundations;

More specific discussions of subsidence, stability, and erosion for each of the pond complexes within the SBSP Restoration Project area are presented in Sections 5.2 and 5.3, below.

5.2 EXISTING OUTBOARD POND LEVEES

5.2.1 Subsidence

Ongoing subsidence of the outboard pond levees can be attributed to: consolidation of Bay Mud within recent pond levee fills; consolidation of Bay Mud beneath recent pond levee fills; consolidation of Bay Mud from regional groundwater depletion; subsidence resulting from

liquefaction of loose saturated granular deposits during an earthquake; and subsidence from consolidation of deeper Santa Clara Valley Formation from regional groundwater depletion.

5.2.1.1 Subsidence From Consolidation of Bay Mud Within And Below Recent Pond Levee Fills

The main component of levee subsidence in the SBSP Restoration Project area is consolidation of Bay Mud within and below recent pond levee fills. Consolidation of Bay Mud occurs over time. Typically with soft clays like Bay Mud, a large portion of settlement occurs over a period of weeks or months, with the remainder occurring over a period of years, sometimes decades. The thickness of the Bay Mud layer strongly affects the time of consolidation. Thin layers consolidate more rapidly than thicker layers.

The degree and rate of subsidence caused by consolidation of Bay Mud within and below recent pond levee fills varies depending on:

- the weight and density of recently added fill,
- the thickness and engineering characteristics of underlying Bay Mud, and
- the time since recent fill placement.

Because of these variables, and limited record keeping during pond levee construction, the degree and rate of past subsidence caused by consolidation of Bay Mud within and below recent pond levee fills is not well defined. From the Cargill maintenance records, we can infer a generalized rate and degree of levee subsidence between 1995 and 2005 for each pond complex as indicated in the table below.

Cargill Maintenance Records 1995 - 2005			
	Ravenswood	Eden Landing	Alviso
Number of ponds	7	23	29
Total number of grading events per pond complex	103	283	397
Total quantity of new fill placed per pond complex (CY/LF)	1,780 / 116,723	5,730 / 139,165	3,780 / 413,179
Average number of grading events per pond	15	12	14
Average quantity of new fill placed per pond (CY/LF)	254 / 16,675	249 / 6,051	130 / 14,248
Estimated average subsidence per pond (inches/year)	1.8	0.6	1.1
Maximum number of grading events for individual pond (pond ID)	25 (R1)	31 (B1C)	26 (A15)
Maximum quantity of new fill placed for individual pond (CY/LF) (pond ID)	3,970(R2)/33,245(R1)	2,100(B1)/28,400(B2)	1,020(A15)/79,700(A10)

Notes:

1. Values in the table correspond to maintenance activities described in Cargill records as “grading”. In some cases, quantity of fill placed is reported as volume (CY). In other cases, quantity of fill placed is reported as distance (LF). Not enough information is provided to convert LF to CY or to convert CY to LF. In some cases, a grading event is described, but no corresponding fill quantity is provided.
2. CY = cubic yards
3. LF = linear feet
4. Estimated average subsidence is very rough, and assumes:
 - Average crest width 15 feet,
 - New fill spread out over entire perimeter of pond,
 - Average pond perimeter at Ravenswood ~ 11,200 feet,
 - Average pond perimeter at Eden Landing ~ 13,400 feet,
 - Average pond perimeter at Alviso ~ 16,500 feet.

Though appropriate for programmatic-level evaluations, the quantities presented in the Table above should be considered approximate. Limitations of the Cargill data are discussed in Section 3.1.3.

The degree and rate of future subsidence caused by consolidation of Bay Mud within and below recent pond levee fills will likewise vary. From the Cargill maintenance records, we can develop generalized return rates for levee subsidence maintenance activities between 1995 and 2005 for each pond complex as indicated in the table below.

Cargill Maintenance Records 1995 - 2005			
	Ravenswood	Eden Landing	Alviso
Number of ponds	7	23	29
Total number of grading events per pond complex	103	283	397
Total return rate (years per event) of pond complex levee subsidence maintenance	0.10	0.04	0.03
Average number of grading events per pond	15	12	14
Average return rate (years per event) of pond levee subsidence maintenance (events per year)	0.7	0.8	0.7
Maximum number of grading events for individual pond (pond ID)	25 (R1)	31 (B1C)	26 (A15)
Minimum return rate (years per event) of levee subsidence maintenance for individual pond (pond ID)	0.4 (R1)	0.3 (B1C)	0.4 (A15)

Notes:

1. Values in the table correspond to maintenance activities described in Cargill records as “grading”. In some cases, quantity of fill placed is reported as volume (CY). In other cases, quantity of fill placed is reported as distance (LF). Not enough information is provided to convert LF to CY or to convert CY to LF. In some cases, a grading event is described, but no corresponding fill quantity is provided.
2. CY = cubic yards
3. LF = linear feet

These return rates can be extrapolated to estimate future subsidence and/or maintenance requirements.

Though appropriate for programmatic-level evaluations, the quantities presented in the Table above should be considered approximate. Limitations of the Cargill data are discussed in Section 3.1.3. In assessing need for future levee maintenance, it is important to point out that the Cargill data spans only a 10 year period.

Cargill grading maintenance events per pond complex between 1995 and 2005 are also summarized in Table 1 and illustrated on Figures 6r, 6e, and 6r. Cargill grading maintenance events per pond between 1995 and 2005 are summarized in Table 2 and illustrated on Figures 6r, 6e, and 6r. Individual Cargill maintenance events between 1995 and 2005 are summarized in Appendix D.

Generally, the thickness and consistency of the Bay Mud is expected to vary gradually within the pond complexes and along existing levees within the pond complexes. Future levee subsidence from consolidation of Bay Mud is therefore also expected to vary gradually across existing levees within the pond complexes. The amount of future consolidation may cause portions of certain existing outboard pond levees to settle to, or below, minimum elevations required to prevent overtopping.

5.2.1.2 Subsidence From Consolidation of Bay Mud From Regional Groundwater Depletion

Lowering the groundwater elevation in areas that contain significant thicknesses of Bay Mud can cause consolidation of Bay Mud and ground subsidence. As much as 13 feet of surface settlement occurred in Santa Clara and San Mateo counties between about 1912 and 1969. This settlement is mainly attributed to regional groundwater depletion. Lowered groundwater elevations through this period increased effective stresses within local Bay Mud deposits, which caused consolidation and ground subsidence. Since 1969, the implementation of groundwater replenishment programs has slowed or stopped the consolidation and ground subsidence (USACE, 1989).

5.2.1.3 Subsidence From Liquefaction Of Loose Saturated Granular Deposits During An Earthquake

Saturated loose granular soils exist within, and below, sediments of the San Francisco Bay throughout the SBSP Restoration Project area. These soils are potentially liquefiable. During and immediately after ground shaking from a moderate to strong earthquake, saturated loose

granular soils may lose strength, and may experience relatively rapid volumetric change. The expression of liquefaction and the corresponding volumetric change is often ground subsidence.

The severity of the liquefaction hazard depends on:

- density of the saturated granular soils,
- depth and thickness of potentially liquefiable layers,
- magnitude and duration of the ground shaking, and
- distance to the nearby free face or ground slope.

Generally, looser deposits have the potential to densify more as a result of ground shaking and are subject to larger volumetric changes. Generally thicker deposits will accumulate more volumetric change than thinner deposits.

Liquefaction evaluations were beyond the scope of this study. However, saturated loose granular soils exist within, and below, sediments of the San Francisco Bay throughout the SBSP Restoration Project area. These soils are potentially liquefiable. The amount of liquefaction is expected to vary within a given pond complex based on density, depth, and thickness of potentially liquefiable soil layers. A liquefaction susceptibility map for the SBSP Restoration Project area (Knudsen and others, 2006) based on soil type, soil thickness and depth to groundwater is presented in Figure 2.

Generally, the thickness and consistency of loose saturated granular deposits within the SBSP Restoration Project area are expected to be discontinuous and may vary more abruptly along any given levee. Future subsidence from liquefaction of loose saturated granular soils may therefore vary more abruptly, potentially differentially, along any given levee. The amount of liquefaction may cause portions of existing outboard pond levees to settle to, or below, minimum elevations required to prevent overtopping. Differential settlements can be detrimental to corresponding infrastructure improvements like roads, railways, underground utilities, etc.

5.2.1.4 Subsidence From Consolidation of Deeper Santa Clara Valley Formation from Regional Groundwater Depletion

Moffatt & Nichols, 2005 reports that an additional foot of subsidence due to consolidation of deeper Santa Clara Valley formation from regional groundwater depletion can be expected over

a period of 30 years along portions of the inboard levees within the SBSP Restoration Project area.

5.2.2 Stability

5.2.2.1 Static Stability of Levee Slopes

Except for eroding levee faces, the existing salt pond levees are typically low to moderate in height and have fairly flat slopes. This configuration results in stable levees (M&N, 2005).

Periodic maintenance of the outboard pond levees that includes adding relatively small thicknesses of new fill (like that conducted by Cargill between 1995 through 2005) is not expected to have a significant impact on static stability of existing outboard pond levee slopes. Bay mud however is generally too weak to support large thicknesses of new fill placed at steep slopes in a single stage of construction.

5.2.2.2 Seismic Stability of Levee Slopes

When liquefaction occurs within an embankment at or near the surface of a slope (cut slope, fill slope, existing shoreline, existing river channel, etc.) strength loss within saturated granular soils during liquefaction may result in slope failure and lateral deformation (lateral spreading).

Liquefaction evaluations were beyond the scope of this study. However, saturated loose granular soils exist within, and below, sediments of the San Francisco Bay throughout the SBSP Restoration Project area. These soils are potentially liquefiable. During and immediately after ground shaking from a moderate to strong earthquake, saturated loose granular soils may lose strength, and may experience relatively rapid volumetric change. Liquefaction occurring near the surface of a levee slope may cause that slope to fail and deform.

It is possible to design and construct measures to reduce the risk of liquefaction and seismic slope failure. However, for the existing outboard pond levees, the cost of implementing such mitigation(s) likely is not cost feasible.

5.2.3 Erosion

The majority of the embankment slopes along existing outboard pond levees are vegetated. Some are protected with riprap. These slopes are subject to erosion caused by rain and wave action. The type and condition of levee slope protection per pond are summarized in Table 3 and illustrated on Figures 4r, 4e, and 4r.

From the Cargill maintenance records, we can infer a generalized rate and degree of levee erosion between 1995 and 2005 for each pond complex as indicated in the table below.

Cargill Maintenance Records 1995 - 2005			
	Ravenswood	Eden Landing	Alviso
Number of ponds	7	23	29
Total number of pond complex levee erosion maintenance	29	50	66
Total quantity of new fill placed per pond complex (CY/LF)	12,910 / 18,988	19,525 / 23,756	13,465 / 20,970
Average number of erosion events per pond	4	2	2
Average quantity of new fill placed per pond (CY/LF)	1,844 / 2,713	849 / 1,033	464 / 723
Maximum number of erosion events for individual pond (pond ID)	9 (R1)	11 (B2)	14 (A2W)
Maximum quantity of new fill placed for individual pond (CY/LF) (pond ID)	9,755 / 15,218 (R1)	6,745 / 7,010 (B2)	3,750 / 4,848 (A2W)

Notes:

1. Values in the table correspond to maintenance activities described in Cargill records as “erosion”, “riprap”, “slope repair”. In some cases, quantity of fill placed is reported as volume (CY). In other cases, quantity of fill placed is reported as distance (LF). Not enough information is provided to convert LF to CY or to convert CY to LF. In some cases, a grading event is described, but no corresponding fill quantity is provided.
2. CY = cubic yards
3. LF = linear feet

Though appropriate for programmatic-level evaluations, the quantities presented in the Table above should be considered approximate. Limitations of the Cargill data are discussed in Section 3.1.3. In assessing need for future levee maintenance, it is important to point out that the Cargill data spans only a 10 year period.

Cargill erosion maintenance events per pond complex between 1995 and 2005 are also summarized in Table 1 and illustrated on Figures 6r, 6e, and 6r. Cargill erosion maintenance

events for each pond between 1995 and 2005 are summarized in Table 2 and illustrated on Figures 6r, 6e, and 6r. Individual Cargill maintenance events between 1995 and 2005 are summarized in Appendix D.

The degree and rate of future erosion will vary. From the Cargill maintenance records, we can develop generalized return rates for levee erosion maintenance activities between 1995 and 2005 for each pond complex as indicated in the table below.

Cargill Maintenance Records 1995 - 2005			
	Ravenswood	Eden Landing	Alviso
Number of ponds	7	23	29
Total number of erosion events per pond complex	29	50	66
Total return rate (years per event) of pond complex levee erosion maintenance	0.3	0.2	0.2
Average number of erosion events per pond	4	2	2
Average return rate (years per event) of pond levee erosion maintenance	3	5	5
Maximum number of grading events for individual pond (pond ID)	9 (R1)	11 (B2)	14 (A2W)
Minimum return rate (years per event) of levee erosion maintenance for individual pond (pond ID)	1.1 (R1)	0.9 (B2)	0.7 (A2W)

Notes:

1. Values in the table correspond to maintenance activities described in Cargill records as “erosion”, “riprap”, “slope repair”. In some cases, quantity of fill placed is reported as volume (CY). In other cases, quantity of fill placed is reported as distance (LF). Not enough information is provided to convert LF to CY or to convert CY to LF. In some cases, a grading event is described, but no corresponding fill quantity is provided.
2. CY = cubic yards
3. LF = linear feet

These return rates can be extrapolated to estimate future erosion and/or maintenance requirements.

Though appropriate for programmatic-level evaluations, the quantities presented in the Table above should be considered approximate. Limitations of the Cargill data are discussed in

Section 3.1.3. In assessing need for future levee maintenance, it is important to point out that the Cargill data spans only a 10 year period. In assessing need for future levee maintenance, it is important to point out that the Cargill data spans only a 10 year period.

5.3 PROPOSED INBOARD FLOOD LEVEES

5.3.1 Evaluations Performed By Moffatt & Nichol, 2005

In 2005, Moffatt & Nichol prepared a report for the California State Coastal Conservancy to summarize evaluations performed for the then current configurations of new inboard flood control levees throughout the SBSP Restoration Project area, which could function as perimeter (Bayfront) levees after implementation of the proposed restoration project. The alignments of the new inboard flood control levees, evaluated by Moffat & Nichol, are similar to those currently being considered by the SBSP Restoration Project team.

Generally, new inboard levee configurations considered in Moffatt & Nichol 2005 included the following generalized sections of proposed conditions:

Location	Thickness of New Fill (feet)	Width of New Crest (feet)	Pondside Inclination of New Waterside Embankment Slope (Horiz:Vert)
Alviso - Charleston Slough & Pond A1	6.5	20	3:1 and 8:1
Alviso - Pond A1	5.5 to 10.5	20	3:1 and 8:1
Alviso - Pond A2W	11 to 16	20	3:1 and 8:1
Alviso - Pond A2E	12 to 13	20	3:1 and 8:1
Alviso - Pond A3W	10	20	3:1 and 8:1
West Bay (Ravenswood) – Pond S	8 to 11	20	3:1 and 8:1
West Bay (Ravenswood) – Pond 3	7 to 8	20	3:1 and 8:1

3:1 and 8:1 (horizontal:vertical) represent two separate cases for inclination of the new waterside slope. It appears that the landslide slope was assumed to be inclined at approximately 2:1 (horizontal:vertical). Moffatt & Nichol 2005 did not consider generalized sections of proposed conditions at Eden Landing.

5.3.2 Current Configurations of Proposed New Levees

Generally, new inboard levee configurations currently being considered include the following generalized sections of proposed conditions (PWA Draft Flood Assessment Report, 2006):

Location	Thickness of New Fill (feet)	Width of New Crest (feet)	Pondside Inclination of New Embankment Slope (Horiz:Vert)
Ravenswood – Alternative A	4.5 to 9.5	15	3:1 to 5:1
Ravenswood – Alternative B	4.5 to 7.5	15	3:1 to 30:1
Ravenswood – Alternative C	4.5 to 5.5	15	3:1
Eden Landing – Alternative A	1.5 to 6.5	15	3:1 to 5:1
Eden Landing – Alternative B	1.5 to 4.5	15	3:1 to 30:1
Eden Landing – Alternative C	1.5 to 3.5	15	3:1
Alviso – Alternative A	5.5 to 11.5	15	3:1 to 5:1
Alviso – Alternative B	5.5 to 9.5	15	3:1 to 30:1
Alviso – Alternative C	5.5 to 8.5	15	3:1

Locations of proposed inboard flood control levees are indicated in Figure 7. Alternative A represents “No Outboard Marsh” conditions, and includes an inboard “stability berm” (approximately 30 feet wide, plus 3H:1V slope), and an outboard “tidal bench” (approximately 30 feet wide, plus 5H:1V slope). Alternative B represents “With Outboard Marsh” conditions, and includes an inboard “stability berm” (approximately 30 feet wide, plus 3H:1V slope), and an outboard “upland transition area” (approximately 100 feet wide, plus 30H:1V slope). Alternative C represents “With Outboard Managed Pond” conditions, and includes an inboard “stability berm” (approximately 30 feet wide, plus 3H:1V slope), and an outboard “stability berm” (approximately 30 feet wide, plus 3H:1V slope).

5.3.3 Subsidence

5.3.3.1 General

In addition to the ongoing subsidence expected throughout the SBSP Restoration Project area, (discussed in section 5.2 above), construction of new inboard flood control levees will require adding significant thicknesses of new fill. The weight of the new fill will cause additional consolidation settlement of underlying soft Bay Mud. Consolidation of the Bay Mud from new fill is expected to occur over the course of years, in some cases decades. The degree and rate of additional subsidence caused by consolidation of Bay Mud within and below new inboard flood levee fills will vary depending on:

- the weight and density of recently added fill,
- the thickness and engineering characteristics of underlying Bay Mud, and
- schedule and sequence of new fill placement.

For longterm flood protection, design of new inboard levees will need to adequately account for the ongoing subsidence from previous fill placement activities (discussed in section 5.2 above) as well as for additional subsidence from new fill placement. During project-level design of new inboard flood protection levees, the team should consider the following three design approach alternatives:

- Design Approach Alternative 1 – Construct new inboard flood control levees in single stage to sufficient height without ground improvement that the new crests will not subside below required flood protection elevations throughout the levee’s anticipated lifespan.
- Design Approach Alternative 2 – Construct new inboard flood control levees in single stage to sufficient height with ground improvement that the new crests will not subside below required flood protection elevations throughout the levee’s anticipated lifespan.
- Design Approach Alternative 3 – Construct new inboard flood control levees in multiple stages. When levee crests subside below required flood protection elevations, raise and relevel them to extend the levee’s anticipated lifespan.

Understanding which design approach best meets the owner’s short term and long term project objectives, and costs will be important to help identify and focus future needs for supplemental geotechnical data and design. These design approach alternatives are discussed briefly below.

Design Approach Alternative 1 – Final crest elevations will incorporate:

- minimum required flood protection elevation (assume includes considerations for sea level rise, freeboard, wave run up, etc.),
- additional thickness for anticipated total long term ongoing subsidence of existing levee fill and underlying soft Bay Mud,
- additional thickness for anticipated total long term subsidence of new level fill and underlying soft Bay Mud.,
- additional thickness for anticipated total deformation (vertical and lateral) from liquefaction of loose saturated granular deposits during a large earthquake.

Alternative Advantages:

- design levee crest width can be the optimized minimum (future levee raising is not anticipated),
- single design effort,

- single construction effort,
- likely minimum overall project cost,
- frees the owner from logistical considerations for future levee access/reconstruction.

Alternative Disadvantages:

- design levee crest elevation will be the optimized maximum,
- for short term stability, levee embankment slopes will be flatter (broader), generally requiring more fill,
- initial design and construction costs will be higher.

Design Approach Alternative 2 – Final crest elevations will be based on the minimum required flood protection elevation (assume includes considerations for sea level rise, freeboard, wave run up, etc.). Subsidence from ongoing and new consolidation of soft Bay Mud, as well as from deformation (vertical and lateral) from liquefaction of loose saturated granular deposits during a large earthquake, will be mitigated through ground improvement.

Alternative Advantages:

- design levee crest width can be the optimized minimum,
- design levee crest elevation will be the optimized minimum,
- steepest levee embankment slopes are possible, generally limiting quantities of new fill,
- single design effort,
- improved resistance to deformation during/after large earthquake,
- single construction effort,
- frees the owner from logistical considerations for future levee access/reconstruction,

Alternative Disadvantages:

- ground improvement requires specialized design and construction,
- ground improvement is expensive and may not be cost feasible.

Design Approach Alternative 3 – Final crest elevations will incorporate:

- minimum required flood protection elevation (assume includes considerations for sea level rise, freeboard, wave run up, etc.),
- additional thickness for anticipated partial long term ongoing subsidence of existing levee fill and underlying soft Bay Mud,
- additional thickness for anticipated partial long term subsidence of new level fill and underlying soft Bay Mud,
- additional thickness for anticipated partial total deformation (vertical and lateral) from liquefaction of loose saturated granular deposits during a large earthquake.

Advantages:

- for short term stability, levee embankment slopes can be steeper, generally requiring less fill than in Alternative 1 (though not as steep as in Alternative 2),
- initial design and construction costs will be lower.

Alternative Disadvantages:

- design levee crest width will be larger to accommodate future levee crest raising(s),
- multiple design efforts,
- multiple construction efforts,
- overall design and construction costs will be higher,
- commits the owner to logistical considerations for future levee access/reconstruction.

Selection of a specific design approach will be based on the owner's short term and long term project objectives, and costs.

The geotechnical data included in this baseline levee model is of sufficient quantity and detail to perform regional, program level assessments. Subsequent project level levee design will require additional characterization (geotechnical investigation) and evaluation of site specific levee and subsurface conditions.

5.3.3.2 *Alviso*

The alignment of the new inboard flood control levees proposed within the Alviso pond complex are presented on Figure 7. Current contours of Bay Mud thickness (Figure 2) within the Alviso pond complex are fairly well defined. Figure 2 indicates new inboard flood control levees proposed within the Alviso pond complex will be constructed over as much as 15 feet of Bay Mud.

Evaluations from Moffatt & Nichol, 2005 indicate, for their inboard levee configurations, that up to 5 feet of subsidence may result from placement of up to 16 feet of new levee fill. This estimate does not include subsidence from potential liquefaction of loose saturated granular soils during an earthquake. The current inboard flood control levee configurations being considered by the SBSP Restoration project team for the Alviso pond complex (Alternatives A, B, and C, see Table above) generally involve placing less than 16 feet (about 6 to 12 feet) of new fill. These configurations then are generally expected to experience less subsidence from consolidation of Bay Mud under the weight of the new fill. The current inboard flood control levee configurations being considered by the SBSP Restoration project team for the Alviso pond complex (Alternatives A and C) generally involve constructing levees that have similar widths to those considered by Moffatt & Nichol, 2005. The current inboard flood control levee configuration being considered by the SBSP Restoration project team for the Alviso pond complex Alternative B generally involves constructing levees that are substantially wider than those considered by Moffatt & Nichol, 2005. The Alternative B levee configuration is generally expected to experience more subsidence than that of Alternatives A and C.

5.3.3.3 *Ravenswood*

The alignment of the new inboard flood control levees proposed within the Ravenswood pond complex are presented on Figure 7. Current contours of Bay Mud thickness (Figure 2) within the Ravenswood pond complex are not well defined. Figure 2 indicates new inboard flood control levees proposed within the Ravenswood pond complex will be constructed over as much as 15 feet of Bay Mud.

Evaluations from Moffatt & Nichol, 2005 indicate, for their inboard levee configurations that up to 4 feet of settlement may result from placement of up to 11 feet of new levee fill. This estimate does not include subsidence from liquefaction of loose saturated granular soils during an earthquake. The current inboard flood control levee configurations being considered by the SBSP Restoration project team for the Ravenswood pond complex (Alternatives A, B, and C) generally involve placing less than 11 feet (about 5 to 10 feet) of new fill. These configurations

then are generally expected to experience less subsidence from consolidation of Bay Mud under the weight of the new fill. The current inboard flood control levee configurations being considered by the SBSP Restoration project team for the Ravenswood pond complex (Alternatives A and C) generally involve constructing levees that have similar widths to those considered by Moffatt & Nichol, 2005. The current inboard flood control levee configuration being considered by the SBSP Restoration project team for the Ravenswood pond complex Alternative B generally involves constructing levees that are substantially wider than those considered by Moffatt & Nichol, 2005. The Alternative B levee configuration is generally expected to experience more subsidence than that of Alternatives A and C.

5.3.3.4 *Eden Landing*

The alignment of the new inboard flood control levees proposed within the Eden Landing pond complex are presented on Figure 7. Current contours of Bay Mud thickness (Figure 2) within the Eden Landing pond complex are not well defined. Figure 2 indicates new inboard flood control levees proposed within the Eden Landing pond complex will be constructed over as much as 10 feet of Bay Mud. Moffatt & Nichol, 2005 did not include settlement evaluations for proposed new inboard flood protection levees at Eden Landing.

5.3.4 Stability

5.3.4.1 *Static Stability of Levee Slopes*

Where new inboard flood protection levees are planned, raising existing levees to reach specified elevations to provide tidal flood protection will be required. Bay Mud, the prominent component of the existing inboard levees, is relatively weak, which may limit the height, or otherwise dictate the width, to which the new inboard flood protection levee improvements can be constructed. For design approach alternative 1 discussed in Section 5.3.3.1 above, the levees may need to be constructed with relatively flat embankment slopes. For design approach alternative 3 discussed in Section 5.3.3.1 above, the levees would be constructed in at least two stages. The time between construction stages (years, perhaps one decade) will allow the underlying clays to consolidate and gain strength. The levees would continue to settle after they are constructed to their designed crest elevations, and the levee crests would need to be designed with sufficient width to accommodate placing additional fill required to maintain the ultimate levee crest design elevation(s).

Static slope stability evaluations performed by Moffat & Nichol, 2005 indicate:

- levee embankment slopes of 8:1 (horizontal:vertical) are not stable to marginally stable for significant thicknesses of new fill constructed over a 15 foot layer of Bay Mud (strength ~ 200 psf),
- levee embankment slopes of 3:1 (horizontal:vertical) are marginally stable for significant thicknesses of new fill constructed over a 15 foot layer of Bay Mud (strength ~ 400 psf), and
- levee embankment slopes of 8:1 (horizontal:vertical) are generally stable for significant thicknesses of new fill constructed over a 15 foot layer of Bay Mud (strength ~ 400 psf).

5.3.4.2 Seismic Stability of Levee Slopes

Liquefaction evaluations were beyond the scope of this study. However, potentially liquefiable granular deposits exist throughout the SBSP Restoration Project area. The breadth and freeboard of the final levee configurations may be designed to accommodate expected vertical and lateral deformations due to liquefaction and lateral spreading. Alternatively ground improvement or modified levee alignments could be considered as possible mitigations.

Site specific geotechnical investigations and evaluations would be required to assess the occurrence and severity of liquefaction, as well as to support design of possible liquefaction mitigations.

5.3.5 Erosion

The outboard embankment slope along new inboard flood control levees will be subject to erosion caused by rain runoff and wave action. The inboard embankment slope along new inboard flood control levees will subject to erosion caused by rain runoff. The design of levee embankment slope protection will be an integral part of the flood control levee design(s).

6.0 LIMITATIONS

This report was prepared for the exclusive use of PWA Consultants, Inc. for the SBSP Restoration project, program-level assessment of existing levees. The findings presented in this report are based on the assumption that geologic conditions within the study area described herein and vicinity do not deviate appreciably from those depicted on available reports, maps, logs of explorations, historic photos, maintenance records, field notes, and observed during our reconnaissance. Future research or additional information may invalidate this report's findings. Additional work will be necessary to investigate and evaluate subsurface conditions in support of specific project-level levee design. Site-specific information may change the findings, and professional judgments presented in this report.

In the performance of our professional services, Geomatrix, its employees, and its agents comply with the standards of care and skill ordinarily exercised by members of our profession practicing in the same or similar localities. No warranty, either express or implied, is made or intended in connection with the work performed by us, or by the proposal for consulting or other services, or by the furnishing of oral or written reports or findings. We are responsible for the findings contained in this report, which are based on available data. In the event conclusions or recommendations based on these data are made by others, such conclusions are not our responsibility unless we have been given an opportunity to review and concur with such conclusions in writing.

7.0 REFERENCES

- Gribaldo, Jacobs, Jones and Associates, 1963, Soil Investigation for the Guadalupe River Project, Reach No. 1, Preliminary Study of the West Bank of Alviso Slough, and Proposed S.P.R.R. Retaining Wall, Santa Clara County, California, January.
- Habitat Restoration Group, 1990, Lower Coyote Creek Flood Control Project In-Stream Water Quality Monitoring Program for Reaches 1B and 2A.
- Habitat Restoration Group, 1990, Lower Coyote Flood Control Project Groundwater Monitoring Program for Reaches 1B and 2A.
- John V. Lowney and Associates, 1978, Geotechnical Reconnaissance Stevens Creek Comprehensive Use and Management Plan Study.
- John V. Lowney and Associates, 1969, Soil Mechanics Investigation S.P.R.R. Bridge and Embankment Raising over Guadalupe River, Alviso/San Jose, California, September.
- Knudsen and others, 2006, Liquefaction Susceptibility Map San Francisco Bay Area.
- Lowney-Kaldveer Associates, 1975, Geotechnical Investigation for Water Pollution Control Plant.
- Moffatt & Nichol Engineers, 2005, Urban Levee Flood Management Requirements South Bay Salt Pond Restoration Project, January.
- Phillip Williams & Associates, Ltd., EDAW, H.T. Harvey & Associates, Brown & Caldwell, 2006, Final Alternatives Report, South Bay Salt Pond Restoration Project, January.
- Phillip Williams & Associates, Ltd., 2006, Flood Assessment Administrative Draft, South Bay Salt Pond Restoration Project, June.
- Santa Clara Valley Water District, 1992, Calabazas Creek Planning Study, Engineer's Report and Final Environmental Impact Report.
- Santa Clara Valley Water District, 1980, Stevens Creek Planning Study, Engineer's Report and Negative Declaration.
- Santa Clara Valley Water District, 1984, Coyote Creek Planning Study, Engineer's Report and Final Environmental Impact Report.
- Santa Clara Valley Water District, 1988, Matadero and Barron Creeks Planning Study, Engineer's Report and Final Negative Declaration.
- Terratech, Inc., 1978, Geotechnical Investigation Calabazas Creek and Sunnyvale East Outfall, Santa Clara County, California, October.

- Tudor Engineering Company, 1973, Baylands Salt Water Flood Control Planning Study, January.
- US Army Corps of Engineers, 1989, Office Report, San Francisco Bay Shoreline Study, San Mateo and Northern Alameda Counties Interim, September.
- US Army Corps of Engineers, 1988a, Office Report, San Francisco Bay Shoreline Study, Southern Alameda and Santa Clara Counties Interim, October.
- US Army Corps of Engineers, 1988b, Coyote Creek and Berryessa Creek Interim Feasibility Report and Final Environmental Impact Statement.
- US Army Corps of Engineers, 1987, Coyote Creek Flood Control Final Environmental Impact Statement.
- US Army Corps of Engineers, 1985, Unpublished Field Notes Levee Condition Survey – San Mateo County (Reaches 24-36), Box 1246663.
- US Army Corps of Engineers, 1985, Unpublished Field Notes Levee Condition Survey, Box 1246665.
- US Army Corps of Engineers, 1985, Unpublished Field Notes Levee Condition Survey – Section 1 thru 63, Box 1246665.
- US Army Corps of Engineers, 1985, Unpublished Field Notes Levee Condition Survey – Section 64 thru 90, Box 1246665.
- US Army Corps of Engineers, 1985, Unpublished Field Notes Levee Condition Survey – Section 91 thru 108, Box 1246665.
- Wentworth CM. 1997. General distribution of geologic materials in the San Francisco Bay region, California: a digital database, <http://geopubs.wr.usgs.gov/open-file/of97-744/>.
- Woodward-Clyde Consultants, 1985, Geotechnical Investigation Flood Control Improvements on Coyote Creek.
- Woodward-Clyde Consultants, 1983a, Geotechnical Investigation, Guadalupe River Flood Control Improvements, Southern Pacific Railroad to the County Marina in Alviso, San Jose, California, Project No. 15482V.
- Woodward-Clyde Consultants, 1983b, Geotechnical Study, South Bay Yacht Club Relocation Alviso, California, Project No. 15482W.
- Woodward-Clyde Consultants, 1961, Soil Investigation for the Proposed Southern Pacific Company, Guadalupe River Railroad Bridge, Alviso, California, January.

TABLES

TABLE 1
MAINTENANCE SUMMARY - POND COMPLEXES
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Eden Landing

	Total Number of Events	Total Linear Feet	Total Cubic Yards
Subsidence Repair	283	139,165	5,730
Erosion Repair	50	23,756	19,525
All Repairs	333	162,921	25,255

Alviso

	Total Number of Events	Total Linear Feet	Total Cubic Yards
Subsidence Repair	397	413,179	3,780
Erosion Repair	66	20,970	13,465
All Repairs	463	434,149	17,245

Ravenswood

	Total Number of Events	Total Linear Feet	Total Cubic Yards
Subsidence Repair	103	116,723	1,780
Erosion Repair	29	18,988	12,910
All Repairs	132	129,333	21,068

TABLE 2
MAINTENANCE SUMMARY - PONDS
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Pond	Unit	Discing	Dredge	Grading Events	Grading (lf)	Grading (cy)	Construction	Rip rap Events	Rip rap (lf)	Rip rap (cy)	Piles
A1	Alviso			20	10,900	0					
A10	Alviso	2		24	79,700	0		2	73	105	
A11	Alviso			19	29,600	450		4	213	273	
A12	Alviso	1		21	13,512	450		5	1,426	976	
A13	Alviso			25	25,010	0		7	1,947	1,174	
A14	Alviso			12	10,000	0					
A15	Alviso			26	6,947	1,020		8	2,640	675	
A16	Alviso	1		21	40,300	800		2	225	270	
A17	Alviso	2		17	20,700	0					
A19	Alviso			10	25,600	0					
A20	Alviso			8	0	0					
A21	Alviso			8	0	0					
A22	Alviso			17	14,380	100		6	4,200	750	
A23	Alviso	6		12	6,050	80					
A2E	Alviso	2		8	0	0					
A2W	Alviso	2		17	900	480		14	4,848	3,750	
A3N	Alviso	1		12	3,080	0		2	240	265	
A3W	Alviso			17	15,000	0		3	340	207	
A5	Alviso			15	26,800	100		2	1,040	350	
A6	Alviso			11	2,700	0		1	2,700	3,500	
A7	Alviso	5	1	14	16,900	200					
A8	Alviso			25	33,100	100					
A9	Alviso	1		16	20,000	0		2	73	105	
AB1	Alviso	6		13	12,000	0		8	1,005	1,065	
AB2	Alviso	5		9	0	0					
B1	Eden Landing	2		25	13,550	2,100	1	7	3,745	2,615	
B10	Eden Landing	1	2	14	1,300	1,035	2	9	2,197	2,515	
B11	Eden Landing			10	0	0					
B13	Eden Landing			10	750	0					

TABLE 2
MAINTENANCE SUMMARY - PONDS
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Pond	Unit	Discing	Dredge	Grading Events	Grading (lf)	Grading (cy)	Construction	Rip rap Events	Rip rap (lf)	Rip rap (cy)	Piles
B14	Eden Landing			11	0	2,000					
B1C	Eden Landing		4	31	18,240	160		2	2,475	1,165	
B2	Eden Landing	2	1	16	28,400	0		11	7,010	6,745	1
B2C	Eden Landing			16	0	70					
B4	Eden Landing			12	5,050	0					
B4C	Eden Landing			9	0	0					
B5	Eden Landing			12	5,250	0		5	200	250	
B5C	Eden Landing			16	22,400	0		4	3,825	3,160	
B6	Eden Landing			12	5,725	0					
B6A	Eden Landing			17	21,000	300		4	3,480	1,925	
B6B	Eden Landing			15	8,500	0					
B6C	Eden Landing			10	0	0					
B7	Eden Landing	1		13	5,800	55					
B8	Eden Landing			11	0	10		4	254	435	
B8A	Eden Landing			9	0	0	3				
B9	Eden Landing			14	3,200	0		4	570	715	
R1	Ravenswood	4		25	33,245	510		9	15,218	9,755	
R2	Ravenswood			15	0	3,970		3	2,320	1,360	
R3	Ravenswood			13	29,600	1,758					
R4	Ravenswood	5		16	20,800	300		8	550	715	
R5	Ravenswood	5		13	6,800	639					
S5	Ravenswood	5		10	12,100	981	2				
SF2	Ravenswood	1		11	7,800	0		9	900	1,080	

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:							Protection:			Source
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type	
Alviso	A1	E	Poor	Poor	Poor							ER	Slight	Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A1	E										ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A1	E	Poor	Fair	Fair					SL		ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A1	E		Poor	Poor	CR						ER	Moderate	Poor	Vegetation	USACE 1988, 1989
Alviso	A1	N	Good-Fair	Good-Fair								ER	Slight	Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A1	N										ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A1	N	Fair	Fair	Fair					SL		ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A1	N	Fair	Fair-Poor	Fair-Poor	CR					UN			Fair	Vegetation	USACE 1988, 1989
Alviso	A1	S	Fair-Poor	Fair-Poor	Fair-Poor							ER	Slight	Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A1	S	Good	Good	Good											GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A1	S	Good	Fair	Poor							ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A1	S	Good	Good	Fair									Good		M&N 2005
Alviso	A1	S										ER	Slight	Good	Vegetation	USACE 1988, 1989
Alviso	A1	W	Poor	Poor	Poor							ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A1	W	Fair-Poor	Fair-Poor	Fair-Poor					SL		ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A1	W	Fair	Poor	Fair					SL		ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A1	W	Fair	Good	Fair									Good		M&N 2005
Alviso	A1	W														USACE 1988, 1989
Alviso	A10	E	Fair-Poor	Fair-Poor	Fair-Poor				OV			ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A10	E	Fair-Poor	Fair-Poor	Fair-Poor							ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A10	E	Poor	Poor	Poor				OV	SL		ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Alviso	A10	NE-E	Fair-Poor	Fair-Poor	Fair-Poor				OV			ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A10	NE-E	Fair-Poor	Fair-Poor	Fair-Poor							ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A10	S	Good-Fair	Good								ER	Moderate	Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A10	S	Fair-Poor	Fair-Poor	Fair-Poor							ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A10	S	Fair-Poor	Fair-Poor	Poor					SL		ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A10	W	Good-Fair	Good								ER	Moderate	Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A10	W	Fair-Poor	Fair-Poor	Fair-Poor							ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A10	W	Fair-Poor	Poor	Poor					SL		ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A11	E	Fair-Poor	Fair-Poor	Fair-Poor				OV			ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A11	E	Fair-Poor	Fair-Poor	Fair-Poor						UN					GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A11	E	Poor	Poor	Poor	CR	SE		OV	SL		ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Alviso	A11	S	Fair-Poor	Fair-Poor	Fair-Poor				OV			ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A11	S	Fair-Poor	Fair-Poor	Fair-Poor						UN					GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A11	S	Fair-Poor	Poor						SL		ER	Intense	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A11	W-N	Fair-Poor	Fair-Poor	Fair-Poor				OV			ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A11	W-N	Fair-Poor	Fair-Poor	Fair-Poor							ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A12	E	Good-Fair	Fair-Poor	Fair-Poor							ER	Slight	Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A12	E	Fair-Poor	Fair-Poor	Fair-Poor							ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A12	E	Fair	Fair-Poor	Fair-Poor	CR			OV	SL	UN	ER	Severe	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A12	E														M&N 2005
Alviso	A12	N	Fair-Poor	Fair-Poor	Fair-Poor							ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A12	N	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A12	N	Poor	Poor	Poor				OV	SL		ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Alviso	A12	W	Fair-Poor	Fair-Poor	Fair-Poor						UN					GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A12	W	Fair-Poor	Fair-Poor	Poor					SL		ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A12	W-S	Good-Fair	Fair-Poor	Fair-Poor							ER	Slight	Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:								Protection:		Source	
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type		
Alviso	A12	W-S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A12	W-S	Fair-Poor	Fair-Poor	Poor					SL			ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A12	W-S															M&N 2005
Alviso	A13	E	Good-Fair	Good-Fair									ER	Slight			GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A13	E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A13	E	Fair	Fair-Poor	Fair-Poor	CR			OV				ER	Severe	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A13	N	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A13	N															GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A13	N	Fair-Poor	Poor	Poor					SL			ER	Severe	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A13	SW	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A13	SW	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A13	W	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A13	W	Fair-Poor	Fair-Poor	Fair-Poor						UN						GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A14	E	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A14	E	Fair-Poor	Fair-Poor	Fair-Poor						UN						GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A14	E	Fair	Poor	Poor								ER	Moderate	Poor	None	GMX 2006 (Field Reconnaissance)
Alviso	A14	N	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A14	N															GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A14	N	Fair	Poor	Poor					SL			ER	Intense	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A14	N-E	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A14	N-E															GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A14	S	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A14	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A14	S	Poor	Poor	Poor				OV	SL			ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Alviso	A14	W	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A14	W	Fair-Poor	Fair-Poor	Fair-Poor								ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A14	W	Poor	Poor	Poor	CR				SL			ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Alviso	A15	E	Good-Fair	Good-Fair									ER	Slight			GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A15	E											ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A15	E	Fair-Poor	Fair-Poor	Fair-Poor					SL	UN		ER	Severe	Poor	Concrete	GMX 2006 (Field Reconnaissance)
Alviso	A15	N-E	Fair-Poor	Fair-Poor	Fair-Poor											None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A15	N-E															GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A15	N-E	Fair	Fair-Poor	Fair					SL			ER	Moderate	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A15	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A15	S															GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A15	S	Poor	Poor	Poor				OV	SL			ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Alviso	A16	E	Fair-Poor	Good-Fair	Fair-Poor											None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A16	E															GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A16	E	Fair	Fair	Fair-Poor					SL	UN		ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A16	E	Good	Good									ER	Slight	Good		M&N 2005
Alviso	A16	S	Fair-Poor	Good-Fair	Fair-Poor											None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A16	S															GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A16	S	Fair	Fair	Fair					SL			ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A16	S	Good	Good									ER	Slight	Good		M&N 2005
Alviso	A16	W	Fair-Poor	Good-Fair	Fair-Poor											None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A16	W															GMX 2006 (1999 Aerial Photo Interpretation)

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:							Protection:		Source	
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition		Protection Type
Alviso	A16	W	Fair	Fair-Poor	Fair-Poor						UN	ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A16	W	Good	Good								ER	Slight	Good		M&N 2005
Alviso	A17	E	Poor	Fair-Poor	Poor									Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A17	E														GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A17	E	Fair-Poor	Fair	Fair-Poor						UN	ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A17	N	Poor	Fair-Poor	Poor									Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A17	N														GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A17	N	Fair	Fair	Fair							ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A17	W	Poor	Fair-Poor	Poor									Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A17	W														GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A17	W	Fair	Fair-Poor	Fair-Poor							ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A19	E	Poor	Fair-Poor								ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A19	NW	Poor	Fair-Poor										Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A19	S	Poor	Fair-Poor								ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A19	W	Poor	Fair-Poor										Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A20		Poor	Fair-Poor										Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A20															GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A21		Poor	Fair-Poor										Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A21															GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A22	E	Poor	Poor	Poor							ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A22	E	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A22	E	Fair-Poor	Fair-Poor	Fair-Poor							ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A22	E	Fair	Fair-Poor	Poor							ER	Intense	Fair-Poor	Vegetation	M&N 2005
Alviso	A22	E	Poor	Poor	Poor											USACE 1988, 1989
Alviso	A22	N	Poor	Poor	Poor							ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A22	N	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A22	N	Poor	Fair-Poor	Fair-Poor							ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A22	N	Fair	Fair-Poor	Poor							ER	Intense	Poor	Vegetation	M&N 2005
Alviso	A22	N	Poor	Poor	Poor											USACE 1988, 1989
Alviso	A22	N-C	Poor	Poor	Poor							ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A22	N-C	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A22	N-C	Fair-Poor	Fair-Poor	Poor							ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A22	N-C	Fair	Fair-Poor	Poor							ER	Intense	Poor	Vegetation	M&N 2005
Alviso	A22	N-C	Poor	Poor	Poor											USACE 1988, 1989
Alviso	A22	N-W	Poor	Poor	Poor							ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A22	N-W	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A22	N-W	Poor	Fair-Poor	Poor							ER	Intense	Poor	Vegetation	M&N 2005
Alviso	A22	N-W	Poor	Poor	Poor											USACE 1988, 1989
Alviso	A22	S-SE	Fair-Poor	Fair-Poor	Fair-Poor									Poor	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A22	S-SE														GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A22	S-SE	Poor	Poor	Poor											USACE 1988, 1989
Alviso	A22	W-C	Poor	Poor	Poor							ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A22	W-C	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A22	W-C	Fair-Poor	Fair-Poor	Poor							ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A22	W-C	Poor	Fair-Poor	Poor							ER	Intense	Poor	Vegetation	M&N 2005
Alviso	A22	W-C	Poor	Poor	Poor											USACE 1988, 1989

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:								Protection:		Source	
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type		
Alviso	A22	W-N	Poor	Poor	Poor								ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A22	W-N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A22	W-N	Fair-Poor	Poor	Poor				OV				ER	Severe	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A22	W-N	Poor	Fair-Poor	Poor								ER	Intense	Poor	Vegetation	M&N 2005
Alviso	A22	W-N	Poor	Poor	Poor												USACE 1988, 1989
Alviso	A22	W-S	Poor	Poor	Poor								ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A22	W-S	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A22	W-S	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A22	W-S	Poor	Fair-Poor	Poor								ER	Intense	Poor	Vegetation	M&N 2005
Alviso	A22	W-S	Poor	Poor	Poor												USACE 1988, 1989
Alviso	A23	E	Good	Good	Good										Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A23	E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A23	E	Poor	Poor	Poor	CR							ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A23	E	Poor	Poor	Poor												USACE 1988, 1989
Alviso	A23	N-NW	Fair-Poor	Fair-Poor	Fair-Poor										Poor	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A23	N-NW															GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A23	N-NW	Poor	Poor	Poor												USACE 1988, 1989
Alviso	A23	S	Good	Good	Good										Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A23	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A23	S	Poor	Poor	Poor	CR							ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A23	S	Poor	Poor	Poor												USACE 1988, 1989
Alviso	A23	W	Good	Good	Good										Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A23	W	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A23	W	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Severe	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A23	W	Poor	Poor	Poor												USACE 1988, 1989
Alviso	A2E	E	Poor	Poor	Poor								ER	Severe	Poor	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A2E	E	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A2E	E	Fair	Good	Good								ER	Slight	Fair	Vegetation	USACE 1988, 1989
Alviso	A2E	N-NW	Poor	Poor	Poor					SL			ER	Intense			GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A2E	N-NW	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A2E	N-NW	Poor	Poor	Poor	CR							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Alviso	A2E	S-C	Fair-Poor	Fair-Poor	Fair-Poor										Poor	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A2E	S-C	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A2E	S-C	Poor	Fair	Poor					SL			ER	Moderate	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A2E	S-C	Poor	Fair-Poor	Fair								ER	Intense	Fair-Poor	Vegetation	M&N 2005
Alviso	A2E	S-C	Poor	Poor	Poor	CR							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Alviso	A2E	S-E	Fair-Poor	Fair-Poor	Fair-Poor										Poor	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A2E	S-E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A2E	S-E	Poor	Fair-Poor	Poor					SL			ER	Intense	Fair-Poor	None	GMX 2006 (Field Reconnaissance)
Alviso	A2E	S-E	Poor	Fair-Poor	Fair								ER	Intense	Fair-Poor	Vegetation	M&N 2005
Alviso	A2E	S-E	Poor	Poor	Poor	CR							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Alviso	A2E	S-W	Fair-Poor	Fair-Poor	Fair-Poor										Poor	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A2E	S-W	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A2E	S-W	Fair	Fair-Poor	Fair								ER	Slight	Fair	Concrete	GMX 2006 (Field Reconnaissance)
Alviso	A2E	S-W	Poor	Fair-Poor	Fair								ER	Intense	Fair-Poor	Vegetation	M&N 2005
Alviso	A2E	S-W	Poor	Poor	Poor	CR							ER	Intense	Poor	Vegetation	USACE 1988, 1989

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:							Protection:				
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type	Source	
Alviso	A2E	W	Good	Fair-Poor	Good						SL		ER	Moderate	Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A2E	W									SL						GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A2E	W	Good-Fair	Fair	Fair						SL		ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A2E	W	Poor	Poor	Poor	CR							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Alviso	A2W	E	Good	Fair-Poor	Fair-Poor								ER	Slight	Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A2W	E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A2W	E	Fair	Poor	Poor						SL		ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A2W	E	Good	Good	Good										Good	Vegetation	USACE 1988, 1989
Alviso	A2W	N	Fair-Poor	Fair-Poor	Fair-Poor								ER	Intense	Good-Fair	Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A2W	N	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A2W	N	Fair	Poor	Poor								ER	Moderate	Poor	Concrete	GMX 2006 (Field Reconnaissance)
Alviso	A2W	N	Poor	Fair	Fair	CR							ER	Moderate	Fair	Vegetation	USACE 1988, 1989
Alviso	A2W	N-E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Intense	Good-Fair	Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A2W	N-E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A2W	N-E	Fair	Poor	Poor								ER	Intense	Fair	Riprap	GMX 2006 (Field Reconnaissance)
Alviso	A2W	N-E	Poor	Fair	Fair	CR							ER	Moderate	Fair	Vegetation	USACE 1988, 1989
Alviso	A2W	N-W	Fair-Poor	Fair-Poor	Fair-Poor								ER	Intense	Good-Fair	Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A2W	N-W	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A2W	N-W	Fair	Poor	Poor								ER	Moderate	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A2W	N-W	Poor	Fair	Fair	CR							ER	Moderate	Fair	Vegetation	USACE 1988, 1989
Alviso	A2W	S	Good	Good	Good								ER	Slight			GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A2W	S	Good	Good	Good												GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A2W	S	Good								SL		ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A2W	S	Good	Fair-Poor	Fair								ER	Intense	Fair-Poor	Riprap	M&N 2005
Alviso	A2W	S	Good	Fair	Fair								ER	Slight	Good	Vegetation	USACE 1988, 1989
Alviso	A2W	W-N	Good	Good	Good										Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A2W	W-N	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A2W	W-N	Poor	Fair-Poor	Poor						SL		ER	Intense	Poor	Riprap	GMX 2006 (Field Reconnaissance)
Alviso	A2W	W-N	Good	Fair	Fair								ER	Slight	Good	Vegetation	USACE 1988, 1989
Alviso	A2W	W-S	Good	Good	Good										Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A2W	W-S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A2W	W-S	Poor	Poor	Poor	CR			OV	SL			ER	Severe	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A2W	W-S	Good	Fair	Fair								ER	Slight	Good	Vegetation	USACE 1988, 1989
Alviso	A3N	N	Good	Good	Good										Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A3N	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A3N	N	Fair-Poor	Fair	Fair						SL		ER	Intense	Poor	Concrete	GMX 2006 (Field Reconnaissance)
Alviso	A3N	S	Good	Good	Good										Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A3N	S															GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A3N	S	Fair-Poor	Fair	Fair-Poor						SL		ER	Intense	Poor	None	GMX 2006 (Field Reconnaissance)
Alviso	A3W	E	Good	Good	Good										Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A3W	E											ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A3W	E	Poor	Good	Good										Good	Riprap	M&N 2005
Alviso	A3W	N	Good	Good	Good										Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A3W	N	Fair-Poor	Fair-Poor	Fair-Poor						SL						GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A3W	N	Good-Fair	Fair	Fair								ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A3W	NW	Poor	Poor	Poor						SL		ER	Slight	Poor	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:							Protection:			
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type	Source
Alviso	A3W	NW	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A3W	S	Good	Good	Good							ER	Slight	Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A3W	S	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A3W	S	Good-Fair	Good-Fair	Good-Fair							ER	Slight	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A3W	S	Good	Poor	Fair							ER	Severe	Poor		M&N 2005
Alviso	A5	E	Good	Fair-Poor										Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A5	E										ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A5	E	Poor	Poor	Poor	CR					UN	ER	Intense	Poor	Vegetation	USACE 1988, 1989
Alviso	A5	N	Good	Good	Good									Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A5	N														GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A5	N	Good	Good								ER	Slight	Good	Vegetation	USACE 1988, 1989
Alviso	A5	NE	Poor	Poor	Poor				OV			ER	Intense		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A5	NE	Poor	Poor	Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A5	NE	Good	Good								ER	Slight	Good	Vegetation	USACE 1988, 1989
Alviso	A5	S-W-N	Good	Good	Good									Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A5	S-W-N	Fair-Poor	Fair-Poor	Fair-Poor							ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A5	S-W-N	Poor	Poor	Poor	CR					UN	ER	Intense	Poor	Vegetation	USACE 1988, 1989
Alviso	A6E	E	Poor	Poor	Poor			BR	OV			ER	Intense		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A6E	N	Poor	Poor	Poor			BR	OV			ER	Intense		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A6E	S	Poor	Poor	Poor			BR	OV			ER	Intense		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A6E	W	Poor	Poor	Poor			BR	OV			ER	Intense		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A6N	NE	Fair-Poor	Fair-Poor	Fair-Poor									Poor	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A6N	S	Poor	Poor	Poor			BR	OV			ER	Intense		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A6N	SW	Poor	Poor	Poor			BR	OV			ER	Intense		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A6W	E	Poor	Poor	Poor			BR	OV			ER	Intense		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A6W	NW	Fair-Poor	Fair-Poor	Fair-Poor									Poor	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A6W	S	Poor	Poor	Poor			BR	OV			ER	Intense		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A6W	SW	Good	Good	Good									Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A7	E	Good	Fair-Poor										Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A7	E														GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A7	E										ER	Moderate			USACE 1988, 1989
Alviso	A7	N-NE	Poor	Fair-Poor								ER	Slight	Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A7	N-NE														GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A7	N-NE										ER	Moderate			USACE 1988, 1989
Alviso	A7	SW	Poor	Poor	Poor				OV			ER	Intense		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A7	SW														GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A7	SW	Good	Good								ER	Slight	Good	Vegetation	USACE 1988, 1989
Alviso	A8N	NE	Fair-Poor	Fair-Poor	Fair-Poor									Good	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A8N	NE														GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A8N	NE										ER	Moderate			USACE 1988, 1989
Alviso	A8N	S	Poor	Poor	Poor							ER	Severe		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A8N	S										ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A8N	S	Good	Good								ER	Slight	Fair	Vegetation	USACE 1988, 1989
Alviso	A8N	W	Good	Fair-Poor										Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A8N	W										ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A8N	W	Good	Good								ER	Slight	Fair	Vegetation	USACE 1988, 1989

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:							Protection:			Source	
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type		
Alviso	A8Sn	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A8Sn	S															M&N 2005
Alviso	A8Sn	S	Fair	Fair	Fair	CR							ER	Slight	Fair	Vegetation	USACE 1988, 1989
Alviso	A8Sn	W-N-E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A8Sn	W-N-E	Good	Good									ER	Slight	Fair	Vegetation	USACE 1988, 1989
Alviso	A8Ss	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A8Ss	N	Fair	Fair	Fair	CR							ER	Slight	Fair	Vegetation	USACE 1988, 1989
Alviso	A8Ss	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A8Ss	S															M&N 2005
Alviso	A8Ss	S	Fair	Fair	Fair	CR							ER	Slight	Fair	Vegetation	USACE 1988, 1989
Alviso	A9	E	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A9	E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A9	N	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate	Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A9	N											ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A9	N	Fair	Poor	Poor					SL			ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	A9	S	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Moderate		None	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A9	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A9	S	Poor	Poor	Poor				OV	SL			ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Alviso	A9	W	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate	Good-Fair	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	A9	W											ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	A9	W	Fair-Poor	Poor	Poor					SL			ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	AB1	N	Good-Fair	Fair-Poor	Fair-Poor								ER	Intense	Good-Fair	Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	AB1	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	AB1	N	Fair	Fair	Fair-Poor								ER	Intense	Fair-Poor	Concrete	GMX 2006 (Field Reconnaissance)
Alviso	AB1	N	Poor	Poor	Poor	CR							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Alviso	AB1	S-E-SE	Poor	Poor	Poor					SL			ER	Intense			GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	AB1	S-E-SE	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	AB1	W	Good-Fair	Fair-Poor	Fair-Poor								ER	Intense	Good-Fair	Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	AB1	W	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	AB1	W	Good-Fair	Fair	Fair-Poor					SL			ER	Severe	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	AB1	W	Poor	Poor	Poor	CR							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Alviso	AB2	E	Poor	Poor	Poor					SL			ER	Slight	Poor	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	AB2	E	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	AB2	E	Fair	Fair	Poor								ER	Moderate	Fair-Poor	None	GMX 2006 (Field Reconnaissance)
Alviso	AB2	E	Fair	Good	Good								ER	Slight	Fair	Vegetation	USACE 1988, 1989
Alviso	AB2	N	Fair-Poor	Fair-Poor	Fair-Poor								ER	Intense	Good-Fair	Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	AB2	N															GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	AB2	N	Fair-Poor	Fair-Poor	Fair-Poor					SL			ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Alviso	AB2	W	Poor	Poor	Poor								ER	Severe	Poor	Vegetation	GMX 2006 (1988 Aerial Photo Interpretation)
Alviso	AB2	W	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Alviso	AB2	W	Fair	Good	Good								ER	Slight	Fair	Vegetation	USACE 1988, 1989
Eden Landing	B1	E	Poor	Poor	Poor												GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B1	E	Poor	Poor	Poor											Riprap	GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B1	E	Poor	Fair-Poor	Fair					SL			ER	Severe	Poor	Concrete	GMX 2006 (Field Reconnaissance)
Eden Landing	B1	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B1	N															GMX 2006 (1999 Aerial Photo Interpretation)

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:							Protection:				
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type	Source	
Eden Landing	B1	N	Fair	Fair	Fair							SL	ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B1	N	Fair	Fair									ER	Slight	Fair	Vegetation	USACE 1988, 1989
Eden Landing	B1	S	Fair-Poor	Fair-Poor	Fair-Poor			BR				UN					GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B1	S	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B1	S	Poor	Poor	Poor			BR			SL		ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B1	S	Fair	Fair									ER	Slight	Fair	Vegetation	USACE 1988, 1989
Eden Landing	B1	W											ER	Slight			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B1	W															GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B1	W	Poor	Poor	Poor		SE		OV				ER	Intense	Poor	Vegetation	USACE 1988, 1989
Eden Landing	B10	E														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B10	E	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B10	E	Poor	Fair	Poor										Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B10	E	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Slight	Poor	Vegetation	USACE 1988, 1989
Eden Landing	B10	N											ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B10	N											ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B10	N	Poor	Poor	Poor						SL		ER	Intense	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B10	N	Poor	Poor	Poor				OV						Poor		USACE 1988, 1989
Eden Landing	B10	N-E														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B10	N-E	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B10	N-E	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Slight	Poor	Vegetation	USACE 1988, 1989
Eden Landing	B10	N-W											ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B10	N-W											ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B10	N-W	Poor								SL		ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B10	N-W	Poor	Poor	Poor				OV						Poor		USACE 1988, 1989
Eden Landing	B10	S	Fair-Poor	Fair-Poor	Fair-Poor						SL						GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B10	S	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B10	S	Fair	Good-Fair	Fair										Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B10	S	Poor	Poor	Poor				OV				ER	Intense	Poor		USACE 1988, 1989
Eden Landing	B10	S-E	Fair-Poor	Fair-Poor	Fair-Poor						SL						GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B10	S-E	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B10	S-E	Poor	Poor	Poor				OV				ER	Intense	Poor		USACE 1988, 1989
Eden Landing	B10	W														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B10	W	Fair-Poor	Fair-Poor	Fair-Poor						SL						GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B10	W	Poor	Fair	Fair						SL		ER	Moderate	Fair	Concrete	GMX 2006 (Field Reconnaissance)
Eden Landing	B10	W	Poor	Poor	Poor				OV						Poor		USACE 1988, 1989
Eden Landing	B11	E														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B11	E	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B11	E	Poor	Fair	Fair						SL		ER	Severe	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B11	E	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Slight	Poor	Vegetation	USACE 1988, 1989
Eden Landing	B11	N														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B11	N	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B11	N	Poor	Fair	Fair						SL		ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B11	N	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Slight	Poor	Vegetation	USACE 1988, 1989
Eden Landing	B11	S														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B11	S	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B11	S	Poor	Poor	Poor				OV	SL			ER	Severe	Poor	Vegetation	GMX 2006 (Field Reconnaissance)

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:								Protection:		Source	
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type		
Eden Landing	B11	S	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Slight	Poor	Vegetation	USACE 1988, 1989
Eden Landing	B11	S-E														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B11	S-E	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B11	S-E	Good-Fair	Fair	Poor								ER	Moderate	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B11	S-E	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Slight	Poor	Vegetation	USACE 1988, 1989
Eden Landing	B11	W														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B11	W	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B11	W	Poor	Fair	Fair					SL			ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B11	W	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER	Slight	Poor	Vegetation	USACE 1988, 1989
Eden Landing	B12	N											ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B12	N											ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B12	N	Fair-Poor	Poor	Fair								ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B12	N	Fair	Fair	Fair				OV				ER	Intense	Fair	Vegetation	USACE 1988, 1989
Eden Landing	B12	S															GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B12	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Slight	Poor	Vegetation	USACE 1988, 1989
Eden Landing	B12	W											ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B12	W											ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B12	W	Good-Fair	Fair	Poor					SL			ER	Moderate	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B12	W	Fair	Fair	Fair				OV				ER	Intense	Fair	Vegetation	USACE 1988, 1989
Eden Landing	B13	E											ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B13	E											ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B13	E	Fair-Poor	Fair-Poor	Fair								ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B13	E	Fair	Fair	Fair				OV				ER	Intense	Fair	Vegetation	USACE 1988, 1989
Eden Landing	B13	N-1	Good-Fair	Fair-Poor	Fair					SL			ER	Intense	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B13	N-2														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B13	N-2	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B13	N-2	Poor	Poor	Fair	CR			OV	SL			ER	Severe	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B13	N-2	Fair	Fair	Fair				OV				ER	Intense	Fair	Vegetation	USACE 1988, 1989
Eden Landing	B13	S											ER			Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B13	S	Poor	Poor	Poor			BR									GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B13	S	Poor	Poor	Fair	CR		BR	OV	SL			ER	Severe	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B13	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Slight	Poor	Vegetation	USACE 1988, 1989
Eden Landing	B13	W														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B13	W	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B13	W	Good-Fair	Fair	Fair					SL			ER	Moderate		Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B13	W	Fair	Fair	Fair				OV				ER	Intense	Fair	Vegetation	USACE 1988, 1989
Eden Landing	B14	E-1	Fair-Poor	Fair-Poor	Fair-Poor								ER				GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B14	E-1	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B14	E-1	Poor	Fair-Poor	Fair				OV	SL			ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B14	E-1	Fair	Poor	Poor				OV				ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989
Eden Landing	B14	E-2	Fair-Poor	Fair	Fair				OV	SL			ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B14	N											ER			Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B14	N	Poor	Poor	Poor			BR									GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B14	N	Fair	Poor	Poor				OV				ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989
Eden Landing	B14	S														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B14	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:							Protection:			Source
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type	
Eden Landing	B14	S	Poor	Poor	Poor	CR		BR	OV	SL		ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B14	S														USACE 1988, 1989
Eden Landing	B14	W													Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B14	W	Fair-Poor	Fair-Poor	Fair-Poor							ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B14	W	Fair	Fair	Fair					SL		ER	Intense	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B14	W														USACE 1988, 1989
Eden Landing	B1C	E	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B1C	E	Good	Good	Good									Good	Vegetation	USACE 1988, 1989
Eden Landing	B1C	W														GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B1C	W	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B1C	W	Fair-Poor	Fair-Poor	Fair-Poor	CR						ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B1C	W	Good	Good	Good									Good	Vegetation	USACE 1988, 1989
Eden Landing	B2	E	Fair-Poor	Fair-Poor	Fair-Poor							ER				GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B2	E	Fair-Poor	Fair-Poor	Fair-Poor							ER	Slight		Riprap	GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B2	E	Poor	Fair-Poor	Fair-Poor			BR						Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B2	E		Good	Good									Good	Vegetation	USACE 1988, 1989
Eden Landing	B2	NE	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B2	NE													Riprap	GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B2	NE	Poor	Poor	Poor					SL		ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B2	N-E	Fair-Poor	Fair-Poor	Fair-Poor			BR			UN					GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B2	N-E	Poor	Poor	Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B2	N-E	Poor	Poor	Poor					SL		ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B2	N-E	Fair	Fair	Fair							ER	Slight	Fair	Vegetation	USACE 1988, 1989
Eden Landing	B2	N-W	Fair-Poor	Fair-Poor	Fair-Poor			BR			UN					GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B2	N-W														GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B2	N-W	Fair-Poor	Poor	Poor					SL		ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B2	N-W	Poor	Poor	Poor		SE		OV			ER	Intense	Poor	Vegetation	USACE 1988, 1989
Eden Landing	B2	S	Fair-Poor	Fair-Poor	Fair-Poor						UN	ER	Slight			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B2	S	Fair-Poor	Fair-Poor	Fair-Poor							ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B2	S	Poor	Fair-Poor	Fair-Poor					SL		ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B2	S		Good	Good									Good	Vegetation	USACE 1988, 1989
Eden Landing	B2	W-N	Fair-Poor	Fair-Poor	Fair-Poor			BR			UN					GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B2	W-N														GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B2	W-N	Poor	Poor	Poor	CR				SL		ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B2	W-N	Poor	Poor	Poor		SE		OV			ER	Intense	Poor	Vegetation	USACE 1988, 1989
Eden Landing	B2	W-S	Fair-Poor	Fair-Poor	Fair-Poor							ER	Slight			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B2	W-S	Fair-Poor	Fair-Poor	Fair-Poor					SL		ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B2	W-S	Fair-Poor	Poor	Poor					SL	UN	ER	Intense	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B2	W-S	Poor	Poor	Poor	CR						ER	Intense	Poor	Vegetation	USACE 1988, 1989
Eden Landing	B2C	E	Poor	Poor	Poor							ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B2C	E	Fair-Poor	Fair-Poor	Fair-Poor							ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B2C	E	Fair-Poor	Fair-Poor	Fair-Poor							ER	Severe	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B2C	E	Good	Good	Good									Good	Vegetation	USACE 1988, 1989
Eden Landing	B2C	N								SL		ER				GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B2C	N														GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B2C	N	Fair	Fair-Poor	Fair-Poor					SL		ER	Moderate	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:								Protection:		Source	
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type		
Eden Landing	B2C	N	Good	Good	Good									Good	Vegetation	USACE 1988, 1989	
Eden Landing	B2C	S								SL			ER			GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B2C	S														GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B2C	S	Good	Good-Fair	Good-Fair								ER	Moderate	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B2C	S	Good	Good	Good									Good	Vegetation	USACE 1988, 1989	
Eden Landing	B4	E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B4	E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B4	E	Poor	Fair-Poor	Fair-Poor					SL			ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B4	E		Good	Good									Good	Vegetation	USACE 1988, 1989	
Eden Landing	B4	N	Poor	Poor	Poor								ER			Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B4	N	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B4	N		Good	Good									Good	Vegetation	USACE 1988, 1989	
Eden Landing	B4	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B4	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B4	S	Poor	Fair-Poor	Fair-Poor								ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B4	S		Good	Good									Good	Vegetation	USACE 1988, 1989	
Eden Landing	B4	W	Fair-Poor	Fair-Poor	Fair-Poor								ER				GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B4	W	Fair-Poor	Fair-Poor	Fair-Poor								ER	Slight		Riprap	GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B4	W	Poor	Fair-Poor	Fair-Poor										Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B4	W		Good	Good									Good	Vegetation	USACE 1988, 1989	
Eden Landing	B4C	NW-N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B4C	NW-N	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B4C	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B4C	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B4C	S	Fair	Fair-Poor	Fair-Poor					SL			ER	Moderate	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B4C	SW	Fair-Poor	Fair-Poor	Fair-Poor								ER				GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B4C	SW	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B5	E	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B5	E	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B5	E	Good-Fair	Good-Fair	Good-Fair								ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B5	E	Good	Good	Good									Good	Vegetation	USACE 1988, 1989	
Eden Landing	B5	NW-W	Poor	Poor	Poor								ER			Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B5	NW-W	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B5	NW-W	Good	Good	Good									Good	Vegetation	USACE 1988, 1989	
Eden Landing	B5	SE-E	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B5	SE-E	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B5	SE-E	Fair	Fair-Poor	Fair-Poor	CR				SL			ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B5	SE-E	Good	Good	Good									Good	Vegetation	USACE 1988, 1989	
Eden Landing	B5	SE-W	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B5	SE-W	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B5	SE-W	Good	Good	Good									Good	Vegetation	USACE 1988, 1989	
Eden Landing	B5C	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B5C	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B5C	NE	Poor	Poor	Poor								ER				GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B5C	NE	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B5C	S	Fair-Poor	Fair-Poor	Fair-Poor								ER				GMX 2006 (1988 Aerial Photo Interpretation)

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:								Protection:		Source	
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type		
Eden Landing	B5C	S	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B5C	S	Fair	Fair-Poor	Fair-Poor					SL			ER	Moderate	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B5C	S	Good	Good	Good										Good	Vegetation	USACE 1988, 1989
Eden Landing	B5C	SE	Fair-Poor	Fair-Poor	Fair-Poor								ER				GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B5C	SE	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B5C	SE	Good	Good	Good										Good	Vegetation	USACE 1988, 1989
Eden Landing	B5C	SW-NW	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B5C	SW-NW	Good	Good	Good										Good	Vegetation	USACE 1988, 1989
Eden Landing	B6	E	Fair-Poor	Fair-Poor	Fair-Poor						UN		ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B6	E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B6	E	Good-Fair	Good-Fair	Good-Fair								ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B6	E	Good	Good	Good										Good	Vegetation	USACE 1988, 1989
Eden Landing	B6	N	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER				GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B6	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B6	N	Fair	Poor	Fair								ER	Intense	Fair	Concrete	GMX 2006 (Field Reconnaissance)
Eden Landing	B6	N	Good	Good	Good										Good	Vegetation	USACE 1988, 1989
Eden Landing	B6	S	Poor	Poor	Poor								ER				GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B6	S	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B6	S	Poor	Poor	Poor					SL			ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B6	S	Good	Good	Good										Good	Vegetation	USACE 1988, 1989
Eden Landing	B6	W	Fair-Poor	Fair-Poor	Fair-Poor				OV				ER				GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B6	W	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B6	W	Fair	Fair	Fair					SL			ER		Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B6	W	Good	Good	Good										Good	Vegetation	USACE 1988, 1989
Eden Landing	B6A	E	Fair-Poor	Fair-Poor	Fair-Poor						UN		ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B6A	E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate		Riprap	GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B6A	E	Fair	Fair	Fair								ER	Intense	Fair	Concrete	GMX 2006 (Field Reconnaissance)
Eden Landing	B6A	E	Fair	Fair	Fair				OV				ER	Intense	Fair	Vegetation	USACE 1988, 1989
Eden Landing	B6A	N	Fair-Poor	Fair-Poor	Fair-Poor								ER				GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B6A	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B6A	N	Fair	Fair	Fair					SL			ER	Moderate	Fair	Riprap	GMX 2006 (Field Reconnaissance)
Eden Landing	B6A	S	Fair-Poor	Fair-Poor	Fair-Poor						UN		ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B6A	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate		Riprap	GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B6A	S	Fair-Poor	Fair	Fair								ER	Severe	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B6A	S	Fair	Fair	Fair				OV				ER	Intense	Fair	Vegetation	USACE 1988, 1989
Eden Landing	B6A	W-NW	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B6A	W-NW											ER	Moderate		Riprap	GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B6A	W-NW	Fair	Fair	Fair				OV				ER	Intense	Fair	Vegetation	USACE 1988, 1989
Eden Landing	B6B	E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B6B	E											ER	Moderate		Riprap	GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B6B	E	Poor	Poor	Poor				OV	SL			ER	Severe	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B6B	N	Fair-Poor	Fair-Poor	Fair-Poor								ER				GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B6B	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B6B	N	Fair-Poor	Fair	Fair								ER	Moderate	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B6B	N	Fair	Poor	Poor				OV				ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989
Eden Landing	B6B	W											ER				GMX 2006 (1988 Aerial Photo Interpretation)

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:							Protection:		Source			
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition		Protection Type		
Eden Landing	B6B	W	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B6B	W	Fair-Poor	Poor	Poor					SL			ER	Intense	Poor	Vegetation	GMX 2006 (Field Reconnaissance)	
Eden Landing	B6B	W	Fair	Poor	Poor								ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989	
Eden Landing	B6B	W-SW															GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B6B	W-SW	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B6B	W-SW	Fair	Poor	Poor					OV			ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989	
Eden Landing	B6C	E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B6C	E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B6C	E	Fair-Poor	Fair-Poor	Fair-Poor					OV	SL		ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)	
Eden Landing	B6C	E		Good	Good										Good	Vegetation	USACE 1988, 1989	
Eden Landing	B6C	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B6C	N															GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B6C	N	Fair-Poor	Fair-Poor	Fair-Poor	CR							ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)	
Eden Landing	B6C	N		Good	Good										Good	Vegetation	USACE 1988, 1989	
Eden Landing	B6C	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B6C	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B6C	S	Fair-Poor	Fair-Poor	Fair-Poor					SL			ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)	
Eden Landing	B6C	S		Good	Good										Good	Vegetation	USACE 1988, 1989	
Eden Landing	B6C	W	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B6C	W	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B6C	W	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B6C	W		Good	Good										Good	Vegetation	USACE 1988, 1989	
Eden Landing	B6C	W															GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B6C	W	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (Field Reconnaissance)	
Eden Landing	B6C	W		Good	Good										Good	Vegetation	USACE 1988, 1989	
Eden Landing	B7	E	Poor	Poor	Poor								ER				GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B7	E	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B7	E	Poor	Poor	Poor												GMX 2006 (Field Reconnaissance)	
Eden Landing	B7	E	Poor	Poor	Poor			BR		SL			ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)	
Eden Landing	B7	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B7	N															GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B7	N	Fair	Fair	Fair					SL			ER	Intense	Fair	Vegetation	GMX 2006 (Field Reconnaissance)	
Eden Landing	B7	NW-SW	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B7	NW-SW														Riprap	GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B7	SE-S	Poor	Poor	Poor								ER				GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B7	SE-S	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B8	E															GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B8	E	Fair-Poor	Fair-Poor	Fair-Poor								UN	ER			GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B8	E	Fair	Fair	Fair												GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B8	E	Fair	Fair	Fair				OV				ER	Intense	Fair	Vegetation	USACE 1988, 1989	
Eden Landing	B8	N	Poor	Poor	Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B8	N	Fair-Poor	Fair	Poor								SL	ER	Intense	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B8	N	Fair	Poor	Poor												USACE 1988, 1989	
Eden Landing	B8	N															GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B8	NE														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B8	NE	Poor	Poor	Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B8	NE	Fair	Poor	Poor					OV	SL		ER	Severe	Poor	Vegetation	GMX 2006 (Field Reconnaissance)	
Eden Landing	B8	S															GMX 2006 (1988 Aerial Photo Interpretation)	
Eden Landing	B8	S	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)	
Eden Landing	B8	S	Fair-Poor	Poor	Fair								SL	ER	Intense	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B8	S	Fair	Fair	Fair												USACE 1988, 1989	
Eden Landing	B8	W															GMX 2006 (1988 Aerial Photo Interpretation)	

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:								Protection:		Source	
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type		
Eden Landing	B8	W	Fair-Poor	Fair-Poor	Fair-Poor						SL						GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B8	W	Fair-Poor	Fair	Fair	CR					SL		ER	Intense	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B8	W	Fair	Poor	Poor								ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989
Eden Landing	B8A	E														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B8A	E	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B8A	E	Fair-Poor	Poor	Poor						SL		ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	B8A	E	Fair	Poor	Poor								ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989
Eden Landing	B8A	N														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B8A	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B8A	N	Fair	Poor	Poor								ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989
Eden Landing	B8A	S	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B8A	S	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B8A	S	Fair	Poor	Poor						SL		ER	Severe	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B8A	S	Fair	Fair	Fair								ER	Intense	Fair	Vegetation	USACE 1988, 1989
Eden Landing	B8A	W														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B8A	W	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B8A	W	Fair-Poor	Fair	Fair						SL		ER	Severe	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B8A	W	Fair	Poor	Poor								ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989
Eden Landing	B8N	E											ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B8N	E											ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B8N	E	Fair	Poor	Poor						SL		ER	Severe	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B8N	E	Fair	Poor	Poor								ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989
Eden Landing	B8N	N	Poor	Poor	Poor								ER				GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B8N	N	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B8N	N	Fair	Poor	Poor								ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989
Eden Landing	B8N	S											ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B8N	S											ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B8N	S	Fair-Poor	Poor	Fair						SL		ER	Intense	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B8N	S	Fair	Poor	Poor								ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989
Eden Landing	B8N	W														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B8N	W	Poor	Poor	Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B8N	W	Fair	Poor	Poor								ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989
Eden Landing	B9	E														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B9	E	Poor	Poor	Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B9	E	Poor	Poor	Fair						OV	SL	ER	Severe	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B9	E	Fair	Poor	Poor								ER	Intense	Fair-Poor	Vegetation	USACE 1988, 1989
Eden Landing	B9	N														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B9	N															GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B9	N	Fair	Fair	Fair							SL	ER	Intense	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B9	N															USACE 1988, 1989
Eden Landing	B9	N-E														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B9	N-E	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B9	N-E															USACE 1988, 1989
Eden Landing	B9	S														Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B9	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B9	S	Fair	Poor	Fair							SL	ER	Severe	Poor	Vegetation	GMX 2006 (Field Reconnaissance)

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:								Protection:		Source
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type	
Eden Landing	B9	S														USACE 1988, 1989
Eden Landing	B9	W													Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	B9	W	Poor	Poor	Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	B9	W	Fair-Poor	Fair	Fair					SL		ER	Intense	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	B9	W														USACE 1988, 1989
Eden Landing	BT1	E													Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	BT1	E	Poor	Poor	Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	BT1	E	Poor	Poor	Poor				OV			ER	Intense	Poor		USACE 1988, 1989
Eden Landing	BT1	N													Riprap	GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	BT1	N	Poor	Poor	Poor	CR	SE	BR	OV	SL		ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	BT1	N	Poor	Poor	Poor				OV			ER	Intense	Poor		USACE 1988, 1989
Eden Landing	BT1	S	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	BT1	S	Fair-Poor	Fair-Poor	Fair-Poor					SL						GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	BT1	S	Poor	Poor	Poor					SL	UN	ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	BT1	S	Fair	Fair	Fair				OV			ER	Intense	Fair	Vegetation	USACE 1988, 1989
Eden Landing	BT1	W	Poor	Poor	Poor											GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	BT1	W	Poor	Poor	Poor	CR	SE	BR	OV	SL	UN	ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Eden Landing	BT1	W	Poor	Poor	Poor				OV			ER	Intense	Poor	Vegetation	USACE 1988, 1989
Eden Landing	BT2	E										ER	Slight			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	BT2	E	Poor	Poor	Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	BT2	E	Poor	Poor	Poor					SL		ER	Severe	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	BT2	E	Poor	Poor	Poor		SE		OV			ER	Intense	Poor	Vegetation	USACE 1988, 1989
Eden Landing	BT2	N										ER	Moderate			GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	BT2	N	Fair-Poor	Fair-Poor	Fair-Poor						UN	ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Eden Landing	BT2	N	Poor	Fair	Fair					SL		ER	Severe	Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Eden Landing	BT2	SW	Poor	Poor	Poor			BR								GMX 2006 (1988 Aerial Photo Interpretation)
Eden Landing	BT2	SW														GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R1	E													Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R1	E														GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R1	E	Good-Fair	Good	Good							ER	Slight	Good	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R1	E	Poor	Poor	Poor							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R1	N													Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R1	N	Fair-Poor	Fair-Poor	Fair-Poor					SL		ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R1	N	Poor	Fair	Fair-Poor	CR			OV	SL		ER	Intense	Fair-Poor	Concrete	GMX 2006 (Field Reconnaissance)
Ravenswood	R1	NE													Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R1	NE	Fair-Poor	Fair-Poor	Fair-Poor					SL		ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R1	NE	Good-Fair	Fair-Poor	Fair					SL		ER	Moderate	Good-Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R1	NE	Fair-Poor	Fair	Good					SL		ER	Moderate	Good-Fair	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R1	N-E													Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R1	N-E	Fair-Poor	Fair-Poor	Fair-Poor					SL		ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R1	N-W													Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R1	N-W	Fair-Poor	Fair-Poor	Fair-Poor					SL		ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R1	N-W	Fair	Poor	Poor							ER	Intense	Fair-Poor	Concrete	GMX 2006 (Field Reconnaissance)
Ravenswood	R1	Out-E	Poor	Poor	Poor							ER	Severe	Poor	Concrete	GMX 2006 (Field Reconnaissance)

**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:								Protection:		Source	
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullying	Erosion	Erosion Intensity	Protection Condition	Protection Type		
Ravenswood	R1	S	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R1	S	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R1	S	Fair	Fair	Fair								ER	Slight	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R1	S	Poor	Poor	Poor								ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R1	S-W											ER	Moderate		Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R1	S-W											ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R1	S-W	Fair	Fair	Fair								ER	Moderate	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R1	S-W	Poor	Poor	Poor								ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R1	W-N														Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R1	W-N	Fair-Poor	Fair-Poor	Fair-Poor					SL			ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R1	W-N	Fair	Good-Fair	Good-Fair								ER	Slight	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R1	W-S														Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R1	W-S	Fair-Poor	Fair-Poor	Fair-Poor					SL			ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R1	W-S	Fair	Fair-Poor	Fair								ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R2	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R2	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R2	N	Poor	Poor	Fair	CR			OV	SL			ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Ravenswood	R2	N	Poor	Poor	Poor								ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R2	N-W	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R2	N-W	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R2	N-W	Poor	Poor	Fair	CR			OV	SL			ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Ravenswood	R2	N-W	Poor	Poor	Poor								ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R2	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R2	S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R2	S	Fair-Poor	Fair-Poor	Fair-Poor					SL			ER	Moderate	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R2	S	Poor	Poor	Poor								ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R2	S-E	Poor	Poor	Poor			BR	OV				ER	Moderate			GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R2	S-E	Poor	Poor	Poor			BR	OV				ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R2	S-E	Fair	Poor	Poor					SL			ER	Severe	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R2	S-E	Poor	Poor	Poor								ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R2	W	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R2	W	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R2	W	Poor	Poor	Fair				OV	SL			ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Ravenswood	R2	W	Poor	Poor	Poor								ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R3	E-N-N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R3	E-N-N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R3	E-N-N	Fair-Poor	Fair-Poor	Fair-Poor								ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R3	E-N-N	Poor	Poor	Poor								ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R3	E-N-S	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R3	E-N-S	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R3	E-N-S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R3	E-N-S	Good	Fair-Poor	Good								ER	Intense	Fair-Poor	Vegetation	M&N 2005
Ravenswood	R3	E-N-S	Poor	Poor	Poor								ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R3	E-S	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R3	E-S	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R3	E-S	Fair	Fair-Poor	Poor	CR							ER	Severe	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)


**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA















Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:							Protection:			
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type	Source
Ravenswood	R3	E-S	Good	Fair-Poor	Good							ER	Intense	Fair-Poor	Vegetation	M&N 2005
Ravenswood	R3	E-S	Poor	Poor	Poor							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R3	N-E	Poor	Fair-Poor	Fair-Poor	CR			OV			ER	Severe	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R3	NW										ER	Slight		Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R3	NW										ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R3	NW	Poor	Poor	Poor							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R3	S-E	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R3	S-E	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R3	S-E	Fair-Poor	Fair-Poor	Poor				SL			ER	Severe	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R3	S-E	Good	Fair-Poor	Good							ER	Intense	Fair-Poor	Vegetation	M&N 2005
Ravenswood	R3	S-E	Poor	Poor	Poor							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R3	S-W										ER	Slight			GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R3	S-W										ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R3	S-W	Fair-Poor	Fair-Poor	Fair-Poor	CR						ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R3	S-W	Good	Poor	Fair							ER	Severe	Poor		M&N 2005
Ravenswood	R3	S-W	Good	Fair	Fair									Fair	Vegetation	USACE 1988, 1989
Ravenswood	R3	W													Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R3	W	Fair-Poor	Fair-Poor	Fair-Poor				OV							GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R3	W	Fair-Poor	Fair-Poor	Poor				OV			ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Ravenswood	R3	W	Poor	Poor	Poor							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R4	N	Fair-Poor	Fair-Poor	Fair-Poor							ER	Moderate		Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R4	N	Fair-Poor	Fair-Poor	Fair-Poor							ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R4	N	Fair	Poor	Poor							ER	Severe	Poor	Concrete	GMX 2006 (Field Reconnaissance)
Ravenswood	R4	N	Poor	Poor	Poor							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R4	N-E										ER	Moderate			GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R4	N-E										ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R4	N-E	Fair-Poor	Poor	Poor				SL			ER	Severe	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	R4	N-E	Poor	Poor	Poor							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R4	S	Fair-Poor	Fair-Poor	Fair-Poor							ER	Slight			GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R4	S	Fair-Poor	Fair-Poor	Fair-Poor							ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R4	S	Poor	Fair-Poor	Poor	CR						ER	Moderate	Poor	None	GMX 2006 (Field Reconnaissance)
Ravenswood	R4	S	Poor	Poor	Poor							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R4	S-E	Fair-Poor	Fair-Poor	Fair-Poor							ER	Slight			GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R4	S-E	Fair-Poor	Fair-Poor	Fair-Poor							ER	Slight			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R4	S-E	Poor	Good-Fair	Poor	CR						ER	Severe	Poor	None	GMX 2006 (Field Reconnaissance)
Ravenswood	R4	S-E	Poor	Poor	Poor							ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R4	W	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R4	W	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R4	W	Fair	Poor	Poor							ER	Slight	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R5	E	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R5	E	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R5	E	Fair	Poor	Poor							ER	Slight	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R5	N														GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	R5	N	Fair	Poor	Poor							ER	Slight	Poor	Vegetation	USACE 1988, 1989
Ravenswood	R5	SW	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	R5	SW	Fair-Poor	Fair-Poor	Fair-Poor											GMX 2006 (1999 Aerial Photo Interpretation)



**TABLE 3
LEVEE CONDITIONS**
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, CA

Complex	Pond ID	Orientation	Levee Condition:			Evidence of Distress:								Protection:			
			Crest	Slope	Toe	Cracking	Seepage	Breach	Overtopping	Slumping	Undercutting/ Gullyng	Erosion	Erosion Intensity	Protection Condition	Protection Type	Source	
Ravenswood	R5	SW	Fair	Poor	Poor								ER	Slight	Poor	Vegetation	USACE 1988, 1989
Ravenswood	RT1	E	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	RT1	E	Good	Fair	Fair										Fair	Vegetation	USACE 1988, 1989
Ravenswood	RT1	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	RT1	N	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	RT1	N	Fair	Poor	Poor								ER	Slight	Poor	Vegetation	USACE 1988, 1989
Ravenswood	RT1	S	Poor	Poor	Poor												GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	RT1	S	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	RT1	S	Poor	Poor	Poor								ER	Moderate	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	RT1	S	Good	Fair	Fair										Fair	Vegetation	USACE 1988, 1989
Ravenswood	RT2																GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	RT2		Fair	Poor	Poor								ER	Slight	Poor	Vegetation	USACE 1988, 1989
Ravenswood	S5	NE	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	S5	NE	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	S5	NE	Good	Fair-Poor	Fair								ER	Intense	Fair-Poor		M&N 2005
Ravenswood	S5	NE	Poor	Poor	Poor								ER	Intense	Poor	Vegetation	USACE 1988, 1989
Ravenswood	S5	S	Poor	Poor	Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	S5	S	Poor	Poor	Poor								ER	Moderate	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	S5	S	Good	Fair	Good								ER	Moderate	Fair		M&N 2005
Ravenswood	S5	S	Good	Fair	Fair										Fair	Vegetation	USACE 1988, 1989
Ravenswood	S5	W	Fair-Poor	Fair-Poor	Fair-Poor												GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	S5	W	Fair	Poor	Poor									Slight	Poor	Vegetation	USACE 1988, 1989
Ravenswood	SF2	E	Poor	Poor	Poor								ER	Moderate			GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	SF2	E	Poor	Poor	Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	SF2	E	Poor	Good-Fair	Fair								ER	Slight	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	SF2	E	Good	Fair	Fair										Fair	Vegetation	USACE 1988, 1989
Ravenswood	SF2	N-W															GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	SF2	N-W	Poor										ER	Slight	Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	SF2	S-E-C	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate		Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	SF2	S-E-C	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	SF2	S-E-C	Good	Good	Good										Good	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	SF2	S-E-C	Good	Fair	Fair										Fair	Vegetation	USACE 1988, 1989
Ravenswood	SF2	S-E-N	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate		Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	SF2	S-E-N	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	SF2	S-E-N	Good	Good-Fair	Good								ER	Slight	Good	Riprap	GMX 2006 (Field Reconnaissance)
Ravenswood	SF2	S-E-N	Good	Fair	Fair										Fair	Vegetation	USACE 1988, 1989
Ravenswood	SF2	S-E-S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate		Riprap	GMX 2006 (1989 Aerial Photo Interpretation)
Ravenswood	SF2	S-E-S	Fair-Poor	Fair-Poor	Fair-Poor								ER	Moderate			GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	SF2	S-E-S	Poor	Good-Fair	Fair								ER	Moderate	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	SF2	S-E-S	Good	Fair	Fair										Fair	Vegetation	USACE 1988, 1989
Ravenswood	SF2	S-W															GMX 2006 (1999 Aerial Photo Interpretation)
Ravenswood	SF2	S-W	Fair-Poor	Fair-Poor	Fair-Poor	CR				SL			ER	Intense	Fair-Poor	Vegetation	GMX 2006 (Field Reconnaissance)
Ravenswood	SF2	S-W	Good	Fair	Fair										Fair	Vegetation	USACE 1988, 1989

FIGURES



- Explanation
-  Project area
 -  Deep Bay
 -  Fully Tidal Bayland
 -  Shallow Bay
 -  Active Salt Pond
 -  Beach
 -  Diked Marsh
 -  Farmed Bayland or Grazed Bayland
 -  Tidal Marsh or Managed Marsh
 -  Inactive Salt Pond
 -  Lagoon
 -  Major Channel
 -  Ruderal
 -  Storage or Treatment Basin



SITE LOCATION MAP
 Levee Assessment
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, California


By: TM Date: 10/25/06 Project No. 9378.002




Figure 1

S:\19300\9378\gis\SBSP_Report_Figs\fig_01.mxd

S:\19300\9378\gis\SBSP_Report_Figs\fig_02.mxd



- Explanation
- Project boundary
 - 20 Bay mud isopach (in feet)
- Project pond
 - Deep Bay
 - Fully Tidal Bayland
 - Shallow Bay
- Liquefaction Susceptibility
- Very High
 - High
 - Moderate
 - Low
 - Very Low




BAY MUD THICKNESS AND BORINGS
 Levee Assessment
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, California

By: SB	Date: 10/25/06	Project No. 9378.002
--------	----------------	----------------------

S:\9300\9378\gis\SBSP_Report_Figs\fig_03a.mxd



- Explanation
- A22 Project pond
- Levee Conditions
- Good
 - Good to Fair
 - Fair
 - Fair to Poor
 - Poor
- Key to Location
- Crest of Levee
 - Slope of Levee
 - Toe of Levee





LEVEE ALIGNMENT CONDITION
ALVISO
Levee Assessment
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, California

By: SB	Date: 10/25/06	Project No. 9378.002
--------	----------------	----------------------



- Explanation
- B7 Project pond
- Levee Conditions
- Good
 - Good to Fair
 - Fair
 - Fair to Poor
 - Poor





<p>LEVEE ALIGNMENT CONDITION EDEN LANDING Levee Assessment South Bay Salt Ponds Restoration Project San Francisco Bay Area, California</p>		
By: SB	Date: 10/25/06	Project No. 9378.002
Geomatrix		Figure 3e

S:\9300\9378\gis\SBSP_Report_Figs\fig_03e.mxd




- Explanation**
- R1 Project pond
- Levee Conditions**
- Good
 - Good to Fair
 - Fair
 - Fair to Poor
 - Poor




<p>LEVEE ALIGNMENT CONDITION RAVENSWOOD Levee Assessment South Bay Salt Ponds Restoration Project San Francisco Bay Area, California</p>		
By: SB	Date: 10/25/06	Project No. 9378.002
Geomatrix		Figure 3r

S:\19300\9378\gis\SBSP_Report_Figs\fig_04a.mxd




- Explanation**
- A10 Project pond
- Protection Type**
- Broken Concrete
 - +++++ Rip-rap
 - Vegetation
- Protection Condition**
- Good
 - Good-Fair
 - Fair
 - Fair-Poor
 - Poor




LEVEE PROTECTION TYPE AND CONDITIONS
 ALVISO
 Levee Assessment
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, California


By: SB Date:10/25/06 Project No. 9378.002




- Explanation**
- BT1 Project pond
- Protection Type**
- Broken Concrete
 - ++++ Rip-rap
 - Vegetation
- Protection Condition**
- Good
 - Good-Fair
 - Fair
 - Fair-Poor
 - Poor



LEVEE PROTECTION TYPE AND CONDITIONS EDEN LANDING Levee Assessment South Bay Salt Ponds Restoration Project San Francisco Bay Area, California		
By: SB	Date: 10/25/06	Project No. 9378.002
Geomatrix		Figure 4e




- Explanation**
- R4 Project pond
- Protection Type**
- Broken Concrete
 - ++++ Rip-rap
 - Vegetation
- Protection Condition**
- Good
 - Good-Fair
 - Fair
 - Fair-Poor
 - Poor



LEVEE PROTECTION TYPE AND CONDITION RAVENSWOOD Levee Assessment South Bay Salt Ponds Restoration Project San Francisco Bay Area, California		
By: SB	Date: 10/25/06	Project No. 9378.003
Geomatrix		Figure 4r


S:\9300\9378\gis\SBSP_Report_Figs\fig_04r.mxd

S:\19300\9378\gis\SBSP_Report_Figs\fig_05a.mxd




- Explanation
- A14 Project ponds
 - Erosion Potential
 - Severe
 - Intense - Severe
 - Intense
 - Moderate - Intense
 - Moderate
 - Slight - Moderate
 - Slight

- Observed Distress
- SL** = Slump
 - ER** = Erosion
 - UN** = Uncutting
 - BR** = Breach
 - CR** = Cracking
 - OV** = Overtopping




OBSERVED LEVEE DISTRESS
ALVISO
Levee Assessment
South Bay Salt Ponds Restoration Project
San Francisco Bay Area, California

By: SB Date: 10/25/06 Project No. 9378.002




S:\9300\9378\gis\SBSP_Report_Figs_fig_05e.mxd

Explanation	
B4	Project ponds
SL	Observed Distress
ER	SL = Slump
UN	ER = Erosion
BR	UN = Uncutting
CR	BR = Breach
OV	CR = Cracking
OV	OV = Overtopping
Severe	
Intense - Severe	
Intense	
Moderate - Intense	
Moderate	
Slight - Moderate	
Slight	




OBSERVED LEVEE DISTRESS EDEN LANDING Levee Assessment South Bay Salt Ponds Restoration Project San Francisco Bay Area, California		
By: SB	Date: 10/25/06	Project No. 9378.002
Geomatrix		Figure 5e



S:\9300\9378\gis\SBSP_Report_Figs\fig_05r.mxd

Explanation




- | | | |
|---|--------------------|-------------------------|
| R4 | Project ponds | Observed Distress |
| | Severe | SL = Slump |
| | Intense - Severe | ER = Erosion |
| | Intense | UN = Uncutting |
| | Moderate - Intense | BR = Breach |
| | Moderate | CR = Cracking |
| | Slight - Moderate | OV = Overtopping |
| | Slight | |



<p>OBSERVED LEVEE DISTRESS RAVENSWOOD Levee Assessment</p> <p>South Bay Salt Ponds Restoration Project San Francisco Bay Area, California</p>		
By: SB	Date: 10/25/06	Project No. 9378.002
Geomatrix		Figure 5r

Alviso

	Total Number of Events	Total Linear Feet	Total Cubic Yards
Subsidence Repair	397	413179	3780
Erosion Repair	66	20970	13465
All Repairs	463	434149	17245






LEVEE MAINTENANCE SUMMARIES
 ALVISO
 Levee Assessment
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, California

By: TM Date:10/25/06 Project No. 9378.002

S:\19300\9378\gis\SBSP_Report_Figs\fig_06a.mxd

Eden Landing

	Total Number of Events	Total Linear Feet	Total Cubic Yards
Subsidence Repair	283	139165	5730
Erosion Repair	50	23756	19525
All Repairs	333	162921	25255






LEVEE MAINTENANCE SUMMARIES
EDEN LANDING
 Levee Assessment
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, California

By: SB	Date: 10/25/06	Project No. 9378.002
--------	----------------	----------------------

Geomatrix
Figure **6e**

S:\9300\9378\gis\SBSP_Report_Figs\fig_06e.mxd

Ravenswood			
	Total Number of Events	Total Linear Feet	Total Cubic Yards
Subsidence Repair	103	116723	1780
Erosion Repair	29	18988	12910
All Repairs	132	129333	21068




LEVEE MAINTENANCE SUMMARIES
RAVENSWOOD
 Levee Assessment
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, California

By: TM	Date: 10/25/06	Project No. 9378.002
		Figure 6r


S:\9300\9378\gis\SBSP_Report_Figs\fig_06r.mxd

S:\9300\9378\gis\SBSP_Report_Figs\Fig_07.mxd



Explanation

— Proposed Levees



PROPOSED LEVEE ALIGNMENTS
 Levee Assessment
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, California

By: TM	Date: 10/25/06	Project No. 9378.002
--------	----------------	----------------------



Figure **7**

PHOTOS



Photograph 1: Example of levee without slope protection (Pond R3 Northeast)



Photograph 2: Example of levee with vegetation slope protection (Pond B2 Northwest)



Photograph 3: Example of levee with broken concrete slope protection (Pond B10 West)



Photograph 4: Example of levee with engineered riprap slope protection (Pond SF2 Southeast)



Photograph 5: Example of levee with wood shoring slope protection (Pond B10 North)



Photograph 6: Example of cracking distress of levee crest (Pond A12 East)



Photograph 7: Example of previous breach and overtopping distress of levee with subsequent poor repair (Pond B2 West)



Photograph 8: Example of undercutting and severe erosion distress of levee slope (Pond BT1 Southwestern point)



Photograph 9: Example of gullying and severe erosion distress of unprotected levee slope (Pond B2 South)






Photograph 10: Example of severe erosion distress of levee slope and crest (Pond BT2 North)

PLATE

Alviso

Ravenswood

Eden Landing





Explanation

Existing geotechnical data locations

- EarthMax 2004
- Kleinfelder 2004
- Walter Associates 1992
- Woodward Clyde Consultants 1985
- Woodward Clyde Consultants 1983
- Woodward Clyde Consultants 1982
- Terratech 1978
- Woodward - Lundgren & Associates 1971
- John Lowrey & Associates 1969
- Giraldo, Jacobs, Jones and Associates 1963
- Woodward Clyde Consultants 1961

- Project boundary
- ▨ A1 Project pond
- Deep Bay
- Fully Tidal Bayland
- Shallow Bay



EXISTING AND PROPOSED
 GEOTECHNICAL EXPLORATIONS
 Levee Assessment
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, California

APPENDIX A

SUMMARY OF BORING LOGS

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T5S/R1W-26QB1	N/A	14.5	1	14.7	20	N/A	CL-CH	hard
T5S/R1W-29QB1	5	N/A	6	24	58	36-58	SM, GP	medium dense
T5S/R1W-31EB1	8	N/A	1	17	43.5	23-43.5	SM	medium dense
T5S/R1W-31FB1	8.6	N/A	5	26.5	44	34.5-44	CL, SC, SM	stiff
T5S/R1W-31LB1	7.9	N/A	2.5	27.5	49.5	36-49.5	CL, SM, SP	firm
T5S/R1W-31NB1	8.2	N/A	2.5	21	49.5	41-49.5	CL	very stiff
T5S/R1W-31RB1	7.9	N/A	N/A	20	47	36-47	CL, SC, GP	stiff, medium dense
T5S/R1W-33KB1	4.5	N/A	4.5	17	55	17-21, 43-48	CL	firm
T5S/R1W-33KB2	N/A	N/A	N/A	>12	12	N/A	N/A	N/A
T5S/R1W-33RB1	6	N/A	7	29	60	29-44	CL, SP	Firm, medium dense
T5S/R1W-35AB1	0	N/A	7	14.6	20	N/A	CL	stiff
T5S/R1W-35DB1	0	N/A	N/A	13	20	N/A	CL	stiff
T5S/R1W-35DB2	N/A	N/A	N/A	N/A	12	N/A	N/A	N/A
T5S/R1W-35FB1	N/A	N/A	N/A	N/A	10	N/A	N/A	N/A
T5S/R1W-35GB1	N/A	N/A	N/A	13	51.5	13-21	CL	stiff
T5S/R1W-35JB1	N/A	N/A	N/A	N/A	8.5	N/A	N/A	N/A
T5S/R1W-36E1	N/A	N/A	4	16	500	N/A	CL	N/A
T5S/R1W-36M1	N/A	N/A	4	17	408	N/A	CL	N/A
T5S/R1W-36E2	N/A	N/A	4	23	400	N/A	CL	N/A
T5S/R1W-36EB1	0	6	6	22	25	N/A	CL	stiff
T5S/R1W-36FB1	2	7	7	13.2	25	17.5-18.4	CL	stiff
T5S/R1W-36GB1	N/A	N/A	N/A	N/A	20.5	N/A	CL	very stiff
T5S/R1W-36GB2	N/A	N/A	N/A	N/A	15	N/A	CL	hard
T5S/R1W-36GB3	N/A	N/A	N/A	N/A	10	N/A	CL	hard
T5S/R1W-36GB4	N/A	N/A	N/A	N/A	15	N/A	CL	hard
T5S/R1W-36H1	N/A	N/A	N/A	N/A	368	N/A	CL	N/A
T5S/R1W-36J1	N/A	N/A	N/A	N/A	320	28-44, 57-60	CL	N/A
T5S/R1W-36LB1	N/A	N/A	1	14.5	51.5	6-9, 14.5-18.5	CL	very stiff

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T5S/R1W-36LB2	5	N/A	4.5	13	20	4.5-6.4	CL	stiff
T5S/R1W-36PB1	N/A	6	N/A	N/A	50	17-37	CL, ML	firm
T5S/R1W-36PB2	N/A	6	N/A	N/A	50	17-23	CL	firm
T5S/R1W-36PB3	N/A	N/A	11	21	32	0-11, 28-32	CL	firm
T5S/R1W-36QB4	N/A	N/A	7	36	40	0-7, 17-25	CL	firm
T5S/R1W-36PB4	N/A	7	N/A	N/A	43	0-8, 16-23, 29-32	CL	firm
T5S/R1W-36PB5	N/A	N/A	N/A	N/A	6.5	N/A	N/A	N/A
T5S/R1W-36QB6	N/A	N/A	N/A	N/A	15	N/A	N/A	N/A
T5S/R1W-36QB1	N/A	N/A	8	14	30	0-8	CL	firm
T5S/R1W-36QB2	N/A	N/A	8	18	31	0-8, 28-30	CL	firm
T5S/R1W-36QB3	N/A	N/A	9	17	40	0-9, 29-33	CL	firm
T5S/R1W-36QB5	N/A	N/A	7	N/A	42.5	0-7, 17-21	CL	firm
T5S/R1W-36R80	N/A	N/A	2	N/A	367	N/A	CL	N/A
T5S/R1W-36MB1	N/A	N/A	2	6	12	N/A	CL	N/A
T5S/R2W-21L1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
T5S/R2W-24B1	5	N/A	0	27	497	N/A	CL	N/A
T5S/R2W-24B2	5	N/A	0	27	497	N/A	CL	N/A
T5S/R2W-31HB1	N/A	4.5	4.5	13.5	80	24-31	CL, SP	stiff, medium dense
T5S/R2W-31J80	N/A	N/A	2	25	1040	25-40	SP, CL	N/A
T5S/R2W-31JB1	4	N/A	4	14	18	N/A	CL	N/A
T5S/R2W-31KB1	4	N/A	5	14	20	N/A	CL, SP	N/A
T5S/R2W-31LB1	N/A	9	5	14	27	N/A	CL	stiff, medium dense
T5S/R2W-31LB2	N/A	7	5	N/A	26.5	15.5-24	CL, SP	stiff, dense
T5S/R2W-31PB1	N/A	6.5	4	N/A	20	N/A	CL	firm, stiff
T5S/R2W-31PB2	N/A	6.5	3.5	N/A	36	N/A	CL	stiff
T5S/R2W-31PB3	N/A	6	6	N/A	36	20-34	CL, SP	stiff, dense
T5S/R2W-31QB1	5.5	N/A	4	9	20	N/A	CL	N/A
T5S/R2W-31QB2	7.5	N/A	7	9	19	N/A	CL	N/A

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T5S/R2W-32BB1	3	N/A	0	22	48	31-33	CL	stiff
T5S/R2W-32BB2	3	N/A	0	22	40	29-35	CL, SW	stiff, dense
T5S/R2W-32BB3	3	N/A	0	22.5	43	29-33	CL, SW	very stiff, dense
T5S/R2W-32BB4	3	N/A	0	22	40	39-40	CL	very stiff
T5S/R2W-32DB1	N/A	N/A	0	11	12	11-12	SP	dense
T5S/R2W-32DB2	N/A	2	0	>14	14	N/A	N/A	N/A
T5S/R2W-32EB1	N/A	7	1	14	80	N/A	CL	stiff
T5S/R2W-32EB2	N/A	4	3	14.5	133	26-32	CL, SM	stiff, dense
T5S/R2W-32EB3	N/A	3	0.5	>14	14	N/A	N/A	N/A
T5S/R2W-32EB4	N/A	3.5	0	9	10	9-10	GP	dense
T5S/R2W-32FB1	6	2.5	0	18.5	25	N/A	CL	stiff
T5S/R2W-32FB2	5.6	1	0	16.5	30	N/A	CL	stiff
T5S/R2W-32GB1	7.9	5	4	23	71	17-24	SP, CL	loose, soft
T5S/R2W-32HB1	2	4	1	15	19	N/A	CL	stiff
T5S/R2W-32JB1	2	4.5	1	16.5	19	N/A	CL	stiff
T5S/R2W-32M1	N/A	N/A	1	8	318	8-16	GP, CL	N/A
T5S/R2W-32MB1	N/A	4	16	N/A	60	34-48	CL, SP	stiff, dense
T5S/R2W-32MB2	N/A	4.5	5	11.5	25	11.5-15.5	GP, CL	medium dense, firm
T5S/R2W-32MB3	4	N/A	6	13	34	N/A	CL	N/A
T5S/R2W-32MB4	4	N/A	5	14	20	N/A	CL	N/A
T5S/R2W-32MB5	3.5	N/A	6	10	18	N/A	CL	N/A
T5S/R2W-32MB6	4	N/A	4	16	19	N/A	CL	N/A
T5S/R2W-32RB1	2	N/A	1	12.5	17	N/A	CL	stiff
T5S/R2W-33NB1	2	3.5	1.5	16	19	N/A	CL	stiff
T5S/R2W-34N1,2	3	2	0	31	60	N/A	CL	N/A
T5S/R2W-35R1,2	5	N/A	8	28	501.5	N/A	CL	N/A
T5S/R2W-36G80	N/A	N/A	9	20	150	N/A	CL	N/A
T5S/R2W-B1	-30	N/A	0	>2	2	N/A	N/A	N/A

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T5S/R2W-B10	-23	N/A	0	>9	9	N/A	N/A	N/A
T5S/R2W-B11	-24	N/A	0	>12	12	N/A	N/A	N/A
T5S/R2W-B12	-23	N/A	0	>9	9	N/A	N/A	N/A
T5S/R2W-B13	-22	N/A	0	>14	14	N/A	N/A	N/A
T5S/R2W-B14	-16	N/A	0	>20	20	N/A	N/A	N/A
T5S/R2W-B15	-10	N/A	0	23	27	N/A	CL	firm
T5S/R2W-B16	-10	N/A	0	15	21	N/A	CL	firm
T5S/R2W-B17	-6	N/A	0	13	25	N/A	CL	firm
T5S/R2W-B18	-8	N/A	0	9	21	N/A	CL	firm
T5S/R2W-B19	-7	N/A	0	8	28	N/A	CL	firm
T5S/R2W-B2	-11	N/A	0	9	23	N/A	CL	firm
T5S/R2W-B20	-8	N/A	0	10	26	N/A	CL	firm
T5S/R2W-B21	-22	N/A	0	7	14	N/A	CL	firm
T5S/R2W-B22	-19	N/A	0	5	18	N/A	CL	firm
T5S/R2W-B23	-22	N/A	0	2	9	N/A	CL	firm
T5S/R2W-B24	-29	N/A	0	2	5	N/A	CL	firm
T5S/R2W-B25	-21	N/A	0	8	12	N/A	CL	firm
T5S/R2W-B26	-21	N/A	0	11	12	N/A	CL	firm
T5S/R2W-B27	-30	N/A	0	4	6	N/A	CL	firm
T5S/R2W-B28	-29	N/A	0	4	8	N/A	CL	firm
T5S/R2W-B29	-24	N/A	0	1	11	N/A	CL	firm
T5S/R2W-B3	-9	N/A	0	10	27	N/A	CL	firm
T5S/R2W-B30	-11	N/A	0	9	24	N/A	CL	firm
T5S/R2W-B31	-12	N/A	0	6	24	N/A	CL	firm
T5S/R2W-B32	-21	N/A	0	2	17	N/A	CL	firm
T5S/R2W-B33	-21	N/A	0	1	16	N/A	CL	firm
T5S/R2W-B34	-20	N/A	0	1	16	N/A	CL	firm
T5S/R2W-B35	-11	N/A	0	8	23	N/A	CL	firm

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T5S/R2W-B36	-14	N/A	0	9	19	N/A	CL	firm
T5S/R2W-B37	-15	N/A	0	5	18	N/A	CL	firm
T5S/R2W-B38	-12	N/A	0	11	24	N/A	CL	firm
T5S/R2W-B39	-6	N/A	0	29	34	N/A	CL	firm
T5S/R2W-B4	-4	N/A	0	30	35	N/A	CL	firm
T5S/R2W-B40	-4	N/A	0	28	31	N/A	CL	firm
T5S/R2W-B41	-2	N/A	0	17	34	N/A	CL	firm
T5S/R2W-B42	-1	N/A	0	22	33	N/A	CL	firm
T5S/R2W-B43	-3	N/A	0	12	26	N/A	CL	firm
T5S/R2W-B44	-13	N/A	0	3	19	N/A	CL	firm
T5S/R2W-B45	-14	N/A	0	3	18	N/A	CL	firm
T5S/R2W-B46	-2	N/A	0	10	30	N/A	CL	firm
T5S/R2W-B47	0	N/A	0	12	33	N/A	CL	firm
T5S/R2W-B48	1	N/A	0	19	36	N/A	CL	firm
T5S/R2W-B49	2	N/A	0	13	37	N/A	CL	firm
T5S/R2W-B5	-11	N/A	0	5	23	N/A	CL	firm
T5S/R2W-B50	-2	N/A	0	11	32	N/A	CL	firm
T5S/R2W-B51	0	N/A	0	11	13	N/A	CL	firm
T5S/R2W-B52	1	N/A	0	15	17	N/A	CL	firm
T5S/R2W-B53	0	N/A	0	11	34	N/A	CL	firm
T5S/R2W-B54	1	N/A	0	15	17	N/A	CL	firm
T5S/R2W-B55	-2	N/A	0	16	36	N/A	CL	firm
T5S/R2W-B56	-11	N/A	0	10	24	N/A	CL	firm
T5S/R2W-B57	1	N/A	0	23	36	N/A	CL	firm
T5S/R2W-B58	1	N/A	0	14	35	N/A	CL	firm
T5S/R2W-B59	-5	N/A	0	10	32	N/A	CL	firm
T5S/R2W-B6	-11	N/A	0	5	26	N/A	CL	firm
T5S/R2W-B60	-8	N/A	0	2	29	N/A	CL	firm

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T5S/R2W-B61	0	N/A	0	13	35	N/A	CL	firm
T5S/R2W-B7	2	N/A	0	14	36	N/A	CL	firm
T5S/R2W-B8	0	N/A	0	13	34	N/A	CL	firm
T5S/R2W-B9	1	N/A	0	15	38	N/A	CL	firm
T6S/R1W-1B80	N/A	N/A	22	28	162	112-116	CL	N/A
T6S/R1W-1C80	N/A	14	16	20	150	14-16	CL	N/A
T6S/R1W-1CB1	12	6.8	8	12	20	6.8-8	CL	stiff
T6S/R1W-1CB2	10	6.5	11	12.5	20	6.5-11	CL	stiff
T6S/R1W-1MB1	13	N/A	13.6	>20	20	6-9.4	N/A	N/A
T6S/R1W-2AB1	N/A	N/A	5.5	7	11	N/A	CL	stiff
T6S/R1W-2BB1	N/A	N/A	3	4.5	5	N/A	CL	firm
T6S/R1W-2BB2	3	8	4	10	17	13-17	CL, SM	stiff, loose
T6S/R1W-2BB3	5	5	4	N/A	15	N/A	CL	stiff
T6S/R1W-2BB4	4	N/A	9	>10	10	5-9	N/A	N/A
T6S/R1W-2BB5	5	N/A	4	N/A	4	N/A	N/A	N/A
T6S/R1W-2CB1	3.6	2	23	27	30	27-30	SC, CL	N/A
T6S/R1W-2CB2	4.4	3.5	18	27	25	N/A	CL	N/A
T6S/R1W-2CB3	4.3	6.8	1	4	35	N/A	CL	firm
T6S/R1W-2DB1	3.1	2	30	>40	40	N/A	CL	N/A
T6S/R1W-2DB2	N/A	N/A	2.5	10.5	12.5	N/A	CL	firm, stiff
T6S/R1W-2EB1	3.2	2	0	0	40	N/A	CL	N/A
T6S/R1W-2EB2	N/A	N/A	6	>15	15	N/A	N/A	N/A
T6S/R1W-2FB1	4.6	3	3	3	33	13-33	SM, SP	medium dense
T6S/R1W-2FB2	4.5	3	3	7	49	7-10	CL	stiff
T6S/R1W-2FB3	5	15	1	N/A	16	14-16	CL, SP	stiff, loose
T6S/R1W-2HB1	N/A	N/A	3	>5	5	N/A	N/A	N/A
T6S/R1W-2LB1	N/A	N/A	1	2	9	N/A	CL	very stiff
T6S/R1W-2LB10	2.2	N/A	1	3	7	6-7	SC, CH	N/A

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T6S/R1W-2LB11	1.6	N/A	1	6	7	N/A	CL	N/A
T6S/R1W-2LB12	1.9	N/A	1	5.5	8	N/A	CL	N/A
T6S/R1W-2LB13	1.9	N/A	1	5	7	5-7	SC	N/A
T6S/R1W-2LB2	4.5	4	7	N/A	14	N/A	CL	stiff
T6S/R1W-2LB3	3.7	3	4	N/A	8	N/A	CL	stiff
T6S/R1W-2LB4	2.9	N/A	1	4	5	N/A	CL	firm
T6S/R1W-2LB5	2.5	N/A	0.5	7	8	N/A	CL	firm
T6S/R1W-2LB6	3	N/A	5	N/A	5	N/A	CL	N/A
T6S/R1W-2LB7	2.8	N/A	3	N/A	3	N/A	CL	N/A
T6S/R1W-2LB8	2.7	N/A	3	N/A	3	N/A	CL	N/A
T6S/R1W-2LB9	1.8	N/A	1	6	8	6-8	SC	N/A
T6S/R1W-2M81	N/A	N/A	7	15	20	N/A	CL	N/A
T6S/R1W-2M82	N/A	N/A	6	6	35	14-35	Cl, SP	N/A
T6S/R1W-2M83	N/A	N/A	2	3	20	3-8	SP, CL	N/A
T6S/R1W-2M84	N/A	N/A	2	8	20	N/A	CL	N/A
T6S/R1W-2M85	N/A	N/A	5	7	20	7-18	SP, CL	N/A
T6S/R1W-2MB1	N/A	N/A	7	N/A	7	N/A	SP	loose
T6S/R1W-2MB2	2.8	3	6	N/A	12	4-9	CL, SP	stiff, medium dense
T6S/R1W-2MB3	3.1	N/A	2	N/A	2	N/A	CL	N/A
T6S/R1W-2MB4	2.5	N/A	4	N/A	4	N/A	CL	N/A
T6S/R1W-2MB5	2	N/A	3	N/A	5	4-5	SC	N/A
T6S/R1W-2MB6	2.2	N/A	3	N/A	5	3.5-5	SC	N/A
T6S/R1W-2N80	N/A	N/A	3	14	692	14-16	SP, CL	N/A
T6S/R1W-2NB1	8.6	6	8	N/A	33	8-23	SP, CL	medium dense, stiff
T6S/R1W-2NB10	4	6.5	1.5	7	30	N/A	CL	firm
T6S/R1W-2NB11	5	5	8	14	25	14-17	SC, CL	loose, soft
T6S/R1W-2NB12	4.5	4.5	13.5	N/A	22	15-19.5	CL, SM	firm, loose
T6S/R1W-2NB13	5	5	14	N/A	18	6-14	CL	firm

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T6S/R1W-2NB14	6	5	10	N/A	17	10-17	SM	loose
T6S/R1W-2NB15	9.4	5	5	N/A	30	N/A	CL	stiff, very stiff
T6S/R1W-2NB2	10.2	5	4	4	36	N/A	CL	stiff
T6S/R1W-2NB3	N/A	15	5	11	20	N/A	CL	stiff
T6S/R1W-2NB4	N/A	N/A	11.5	>13	13	N/A	N/A	N/A
T6S/R1W-2NB7	3.5	4	10	N/A	50	N/A	CL, ML	stiff
T6S/R1W-2NB8	3	3	8	N/A	25	14-20	CL, SM	firm, dense
T6S/R1W-2NB9	3	4	11	21	25	N/A	CL	stiff
T6S/R1W-2PB1	6.2	5	4.5	N/A	31	N/A	CL	stiff
T6S/R1W-2PB10	5	6	10	N/A	21	9-21	SM	loose
T6S/R1W-2PB11	9.8	7	8	14	32	5-8	CL	stiff, very stiff
T6S/R1W-2PB12	4.6	0.5	0.5	7	32	9-14	CL, SC	stiff, medium dense
T6S/R1W-2PB13	6.5	2.5	6	N/A	31.5	8-18.5	SM, CL	medium dense, stiff
T6S/R1W-2PB2	3.5	5	2	N/A	51	39-48	CL, SP	firm, very dense
T6S/R1W-2PB3	4.5	4.5	2	N/A	31	11.5-19	CL, SM	firm, medium dense
T6S/R1W-2PB4	5	N/A	4	N/A	31	14-19	CL, SC	firm, dense
T6S/R1W-2PB5	5	3	3	N/A	25	3-25	SP, SM	loose
T6S/R1W-2PB6	5	7	3	N/A	25	7-10	SP, CL	dense, firm
T6S/R1W-2PB7	4.5	7	9	N/A	25	8-10	SC, ML	loose, firm
T6S/R1W-2PB8	5	6	8	N/A	25	7-9	SC, CL	loose, firm
T6S/R1W-2PB9	5	5	6	N/A	20	5-16	GM, CL	medium dense, firm
T6S/R1W-3FB1	N/A	N/A	0.5	4	8	7-8	CL, SC	N/A
T6S/R1W-3GB1	10	N/A	16	25	56	45-56	CL, SM	firm, dense
T6S/R1W-3NB1	N/A	N/A	0	0	4	N/A	CL	firm
T6S/R1W-3R80	N/A	N/A	9	13	20	N/A	CL	N/A
T6S/R1W-3RB1	6.7	4.5	5	13.5	47	13.5-19	SM, CL	medium dense, stiff
T6S/R1W-3RB3	6	5	4	N/A	24	10-23	SC, SP	dense
T6S/R1W-3RB4	5	5	6	N/A	25	N/A	CL	firm

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T6S/R1W-3RB5	7	6.5	4	N/A	25	N/A	CL	firm
T6S/R1W-3RB6	3	4	6	14	37	14-25	SM, CL	medium dense, stiff
T6S/R1W-4QB1	11	N/A	8	14	25	N/A	CL	N/A
T6S/R1W-5DB1	0.6	N/A	5.5	16.5	32	27.5-32	CL	firm, stiff
T6S/R1W-5EB1	1.2	N/A	4.5	16	45.5	N/A	CL	stiff, very stiff
T6S/R1W-5EB2	6.3	5.5	6	19	42	40-42	CL	stiff
T6S/R1W-5EB3	5	N/A	1	9	41	24-26	CL	stiff, very stiff
T6S/R1W-5FB1	1.9	N/A	4	23	37	N/A	CL	stiff, very stiff
T6S/R1W-5JB1	1	N/A	5	15.5	42	N/A	CL	stiff, very stiff
T6S/R1W-5KB1	1	N/A	0	9	45	36-40	CL, SM	stiff, loose
T6S/R1W-5KB2	6	N/A	0	11	46	27-33	CL, SM	stiff, very stiff, loose
T6S/R1W-5LB1	3.6	7.5	2	21.5	37	N/A	CL	stiff
T6S/R1W-5LB2	0.6	N/A	1	17	42	17-19, 38-40	CL, SM	stiff, very stiff, loose
T6S/R1W-5RB1	0.6	5.5	3.5	12	30	N/A	CL	firm, stiff
T6S/R1W-6AB1	8.6	N/A	3.5	33	47	33-47	SM	loose
T6S/R1W-6BB1	8.8	N/A	3	18	45.5	38-41.5	CL	stiff
T6S/R1W-6BB2	5	N/A	0	5.5	34	N/A	CL	stiff
T6S/R1W-7DB1	N/A	N/A	0	10	23	N/A	CL	firm
T6S/R1W-7EB1	N/A	N/A	0	5	20	8-20	SC, SM	dense
T6S/R1W-7FB1	N/A	N/A	3	11	26	11-14	SC, CL	dense, stiff
T6S/R1W-7FB2	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
T6S/R1W-7FB3	N/A	2.5	0	20	30	22-30	CL, SM	firm, dense
T6S/R1W-7FB4	N/A	4	0	23	35	25-35	CL, SM	stiff, dense
T6S/R1W-7LB1	N/A	N/A	0	3	22	8-11, 14-22	SM, SC	dense
T6S/R1W-7LB2	N/A	N/A	0	4	24	10-24	CL, SM	stiff, dense
T6S/R1W-7MB1	N/A	N/A	0	3	22	14-22	CL, SM	stiff, dense
T6S/R1W-7PB1	N/A	N/A	14	N/A	14	10-14	SM, SP	dense
T6S/R1W-7PB2	N/A	10	13	14	24	10-13, 18-24	CL, SC	firm, dense

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T6S/R1W-7PB3	N/A	N/A	0	3	4	N/A	CL	firm
T6S/R1W-7RB1	N/A	N/A	0	>2	2	N/A	N/A	N/A
T6S/R1W-9BB1	8	N/A	7	12	13	N/A	CL	N/A
T6S/R1W-9BB2	N/A	N/A	0	6	11	N/A	CL	firm
T6S/R1W-9BB3	N/A	N/A	0	N/A	2	N/A	N/A	N/A
T6S/R1W-9CB1	11	N/A	7	15	27	N/A	CL	N/A
T6S/R1W-9CB2	N/A	2	4	N/A	14	N/A	CL	medium stiff
T6S/R1W-9CB3	N/A	6	4	16.5	18.5	N/A	CL	stiff
T6S/R1W-9DB1	N/A	8	3	11	42	30-32, 36.5-39	CL, SM	soft, very stiff, loose
T6S/R1W-9DB2	5	1	3	17	45	N/A	CL	firm
T6S/R1W-9FB1	3.6	N/A	3	18	25	8-9, 23-25	CL, SM	very stiff, medium dense
T6S/R1W-9FB2	N/A	2	7	N/A	19	15-19	CL, SM	firm, dense
T6S/R1W-9G1	N/A	N/A	1	10	770	18-20, 34-55	CL, SP	N/A
T6S/R1W-9GB1	N/A	3	5	>8	8	N/A	N/A	N/A
T6S/R1W-9GB2	N/A	0.5	6.5	12	29	21-27	CL, SP	stiff, dense
T6S/R1W-9GB3	N/A	3	4	8	14	12-14	CL, SM	stiff, medium dense
T6S/R1W-9GB4	N/A	1	6	>8	8	N/A	N/A	N/A
T6S/R1W-9H1	N/A	21	8	21	560	21-90	SP	N/A
T6S/R1W-9J1	N/A	9	8	17	263	25-85	SP	N/A
T6S/R1W-9JB1	3.5	4	1	4	30	9-14	CL, SM	very stiff, medium dense
T6S/R1W-9KB1	N/A	2	5	10	42	26.5-42	CL, SP	very stiff, loose
T6S/R1W-9KB2	N/A	N/A	6.5	21	73	27-60	CL, SC	firm, loose
T6S/R1W-9KB3	N/A	N/A	10	25	54	41-46	CL, SM	firm, loose
T6S/R1W-9KB4	3.5	5.5	6	19	67	36-40	CL, SM	firm, medium dense
T6S/R1W-9KB5	N/A	N/A	3	11	30	N/A	CL	stiff
T6S/R1W-9KB6	N/A	N/A	8	15	47	20-31	CL, SM	stiff, loose
T6S/R1W-9KBX1	N/A	2	7	14.5	22	15-16	SP, CL	dense, stiff
T6S/R1W-9KBX2	N/A	3	6.5	10	22.5	N/A	CL	stiff

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T6S/R1W-9KBX3	N/A	N/A	5	25	32.5	25-29	SC, CL	loose, stiff
T6S/R1W-9KBX4	N/A	3.5	4.5	15	21.5	N/A	CL	stiff
T6S/R1W-9KBX5	N/A	8	2	17	21.5	20-21.5	CL, SP	very stiff, medium dense
T6S/R1W-9KBX6	N/A	4	8	15	19.5	16.5-18	CL, SM	stiff, medium dense
T6S/R1W-9LB1	2	5	8.5	19	44	19-22	SC, CL	stiff, medium dense
T6S/R1W-9LB2	2	5	7.5	14	40	19-22, 29-40	CL, SM	stiff, loose
T6S/R1W-9LB3	3	4	7	17	42	30-42	CL, SM	stiff, medium dense
T6S/R1W-9LB4	N/A	3	1.5	30	51	30-38	SP, CL	loose, stiff
T6S/R1W-9LB5	N/A	3	4.5	10	52	33-52	CL, SP	stiff, loose
T6S/R1W-9LB6	N/A	6	0.5	7.5	50	28-50	CL, SC	very stiff, medium dense
T6S/R1W-9LB7	N/A	N/A	2	5.5	7.5	N/A	CL	firm, very stiff
T6S/R1W-9NB1	N/A	9	11	19.5	21	N/A	CL	stiff, very stiff
T6S/R1W-9NB2	N/A	12	7.5	18.5	21	N/A	CL	very stiff
T6S/R1W-9PB1	N/A	9.5	6	18.5	21	N/A	CL	very stiff
T6S/R1W-9PB2	N/A	8.5	7.5	15	21	N/A	ML, CH	stiff, very stiff
T6S/R1W-9QB1	N/A	N/A	1.5	9	30	9-12	SM, CL	medium dense, stiff
T6S/R1W-9RB1	N/A	2.5	5	20	28	20-22.5	SP, CL	medium dense, very stiff
T6S/R1W-9RB2	N/A	N/A	2	5	8	N/A	CL	N/A
T6S/R1W-10E2	N/A	N/A	15	23	385	38-47	CL, SP	N/A
T6S/R1W-10K80	N/A	N/A	2	12	300	12-21	SP, CL	N/A
T6S/R1W-10NB1	0.6	N/A	2	11.5	31	11.5-16.5	SM, CL	medium dense, stiff
T6S/R1W-10NB2	N/A	N/A	1	15	28	15-28	SM, SP	loose, medium dense
T6S/R1W-10NB3	14	4	12	30	35	N/A	CL	N/A
T6S/R1W-10NB4	N/A	7	8	31	52	31-32, 40-52	CL, SM	firm, loose
T6S/R1W-10NB5	N/A	6	8	12	34	N/A	CL	stiff
T6S/R1W-10NB6	13	2	13	30	32	N/A	CL	N/A
T6S/R1W-10P2	N/A	8	8	16	368	16-24	SP, CL	N/A
T6S/R1W-10P80	N/A	6	3	5	85	8-12, 16-18	CL, SP	N/A

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T6S/R1W-10PB1	11	N/A	8	N/A	8	N/A	N/A	N/A
T6S/R1W-10QB1	7	4	6	>12	12	N/A	N/A	N/A
T6S/R1W-10RB1	7	N/A	5	N/A	5	N/A	N/A	N/A
T6S/R1W-10RB2	7	N/A	6	>15	15	N/A	N/A	N/A
T6S/R1W-11C80	N/A	7	3	7	415	7-34	SP	N/A
T6S/R1W-11CB1	7.5	5	4	6	31.5	6-23.5	SP, CL	medium dense, stiff
T6S/R1W-11CB2	3.5	5	8.5	N/A	50.5	32.5-45	CL, SC	firm, dense
T6S/R1W-11CB3	5	5	5	N/A	32	5-13	GW, CL	dense, stiff
T6S/R1W-11D80	N/A	N/A	6	11	555	19-22	CL, SP	N/A
T6S/R1W-11DB1	12	7	4	13	33	25-30	CL, SM	firm, medium dense
T6S/R1W-11DB10	8	7	2	N/A	47	18.5-22	CL	stiff
T6S/R1W-11DB4	3.5	4	2	N/A	51.5	14.5-24	CL, SM	soft, dense
T6S/R1W-11DB5	5	6	8	19	51	30-35	CL, SM	stiff, loose
T6S/R1W-11DB6	4.5	8	9	N/A	52	N/A	CL	soft
T6S/R1W-11DB7	12	12	3	14	47	N/A	CL	stiff
T6S/R1W-11DB8	12	9	5	N/A	46	29-44	CL, SP	stiff, medium dense
T6S/R1W-11DB9	8.5	6	3	N/A	46.5	N/A	CL	stiff, very stiff
T6S/R1W-11F80	N/A	N/A	8	N/A	315	N/A	CL	N/A
T6S/R1W-11N1	N/A	N/A	5	N/A	608	30-43	CL, SP	N/A
T6S/R1W-15A80	N/A	N/A	3	N/A	424	6-10	CL, SP	N/A
T6S/R1W-15B80	N/A	N/A	3	5	85	8-12, 16-18	CL, SP	N/A
T6S/R1W-15C80	N/A	N/A	4	N/A	371	N/A	CL	N/A
T6S/R1W-15DB1	7	8	4	12	35	22-30	CL, SM	stiff, loose
T6S/R1W-15DB2	1.5	6	13.5	25	30	25-26	CL	firm
T6S/R1W-15DB3	N/A	N/A	4	17	34	17-34	SM	loose, medium dense
T6S/R1W-15FB1	6.3	7	6	N/A	40	30-40	CL, SM	stiff, loose
T6S/R1W-15FB2	N/A	7	0	10.5	25	10.5-25	SM	medium dense
T6S/R1W-15H80	N/A	N/A	3	N/A	276	20-50	SP	N/A

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T6S/R1W-16A1	N/A	N/A	6.5	N/A	551	15-20	CL, SP	N/A
T6S/R1W-16AB1	N/A	N/A	0	3	3.5	N/A	CL	N/A
T6S/R1W-16B80	N/A	N/A	8	15	540	15-21	GW, CL	N/A
T6S/R1W-16CB1	N/A	10	8	18	21	18-21	SC	loose
T6S/R1W-16CB2	N/A	10.5	8.5	14.5	21	N/A	CL	very stiff
T6S/R1W-16CB3	N/A	N/A	0.5	>2.3	2.3	N/A	N/A	N/A
T6S/R1W-16CB4	N/A	N/A	1	>3	3	N/A	N/A	N/A
T6S/R1W-16E80	N/A	N/A	4	N/A	432	N/A	CL	N/A
T6S/R1W-16F1	N/A	N/A	5	N/A	435	5-25	SP, CL	N/A
T6S/R1W-16F80	N/A	N/A	11	N/A	538	11-18	SP, CL	N/A
T6S/R1W-16F81	N/A	14	4	N/A	432	N/A	CL	N/A
T6S/R1W-16FB1	N/A	11.5	4	12	21	17.5-19	CL, SC	stiff, loose
T6S/R1W-16FB2	N/A	11.5	10	14	21	14-16.5	SC, CL	medium dense, stiff
T6S/R1W-16H80	N/A	N/A	7	N/A	71	50-56	CL	N/A
T6S/R1W-16J1	N/A	N/A	4	N/A	675	13-17	CL	N/A
T6S/R1W-16N80	N/A	N/A	3	N/A	428	N/A	CL	N/A
T6S/R1W-17A80	N/A	5	N/A	N/A	369	N/A	CL	N/A
T6S/R1W-17AB1	N/A	N/A	2	2.5	3	N/A	CL	very stiff
T6S/R1W-17AB2	N/A	N/A	0	N/A	2	N/A	CL	very stiff
T6S/R1W-17BB1	N/A	N/A	1.5	>4	4	N/A	N/A	N/A
T6S/R1W-17H80	N/A	N/A	5	10	210	50-55	CL	N/A
T6S/R1W-17K1	N/A	N/A	4	N/A	583	N/A	CL	N/A
T6S/R1W-17K2	N/A	8	7	11	492	28-37	CL, SP	N/A
T6S/R1W-17KB1	N/A	5	0	2	14.5	7-11	CL, SC	stiff, loose
T6S/R1W-17R80	N/A	N/A	4	N/A	538	N/A	CL	N/A
T6S/R1W-17R81	N/A	N/A	4	N/A	495	31-37	CL, SP	N/A
T6S/R1W-18D1	N/A	9	5	N/A	894	N/A	CL	N/A
T6S/R1W-18E80	N/A	N/A	5	N/A	894	N/A	CL	N/A

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T6S/R2W-3MB1	6	N/A	5	13	25	N/A	CL	stiff
T6S/R2W-3NB1	14	12	17	19	25	N/A	CL	stiff
T6S/R2W-3NB2	10	10	12	18	25	24-25	CL, SM	stiff, dense
T6S/R2W-3NB3	N/A	N/A	0	7	9	7-9	SP	N/A
T6S/R2W-3PB1	15	N/A	17	21.5	31	29-31	CL, SC	stiff, dense
T6S/R2W-3PB2	14	11	11	19	25	24-25	CL	stiff
T6S/R2W-3PB3	N/A	N/A	2.5	6	6.5	6-6.5	SP	dense
T6S/R2W-3PB4	N/A	5	2.5	>10	10	N/A	N/A	N/A
T6S/R2W-3QB1	6	N/A	4	13	25	N/A	CL	firm
T6S/R2W-4DB1	2	4	1	15	16	N/A	CL	very stiff
T6S/R2W-4NB1	N/A	N/A	1.5	>4	4	N/A	N/A	N/A
T6S/R2W-4NB2	N/A	4	1	5	6	N/A	CL	stiff
T6S/R2W-4PB1	8	N/A	3	13.5	20	17-18.5	CL, SC	stiff, dense
T6S/R2W-4Q80	N/A	N/A	4	18	254	42-54	CL, SP	N/A
T6S/R2W-4QB1	8	N/A	5	14	25	22-25	CL, SP	stiff, dense
T6S/R2W-4QB2	6	N/A	1	14	20	N/A	CL	stiff
T6S/R2W-4QB3	N/A	N/A	2.5	>5	5	N/A	N/A	N/A
T6S/R2W-4RB1	N/A	N/A	7	11.5	15	N/A	CL	very stiff
T6S/R2W-4RB2	4	N/A	3.5	9	20	16-18	CL, SP	stiff, dense
T6S/R2W-4RB3	8	N/A	8	12	13.5	N/A	CL	stiff
T6S/R2W-4RB4	3.5	6	2.5	8	25	N/A	CL	stiff
T6S/R2W-4RB5	15	15.5	15.5	22	25	N/A	CL	stiff
T6S/R2W-4RB6	7	7.5	7	17	20	N/A	CL	stiff
T6S/R2W-4RB7	8	8	5	13.5	25	20-22	CL, SC	stiff, very dense
T6S/R2W-4RB8	3	2.5	2	9	25	14.5-20	CL, SW	stiff, dense
T6S/R2W-5AB1	2	4.5	0	13	15	N/A	CL	stiff
T6S/R2W-5CB1	N/A	N/A	2.5	>10.5	10.5	N/A	N/A	N/A
T6S/R2W-5D1	N/A	N/A	0	N/A	550	N/A	CL	N/A

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T6S/R2W-5D80	5	N/A	0	N/A	603	N/A	CL	N/A
T6S/R2W-5DB1	N/A	N/A	2	7.5	8	N/A	CL	very stiff
T6S/R2W-5EB1	3	N/A	1.5	N/A	5	N/A	CL	firm
T6S/R2W-5EB2	N/A	2	1	4	15	12-15	CL, SM	firm, medium dense
T6S/R2W-5FB1	N/A	2	1	4	31	11-13, 22.5-24	CL, SM	firm, dense
T6S/R2W-5FB2	N/A	2.5	0.5	5.5	15	N/A	CL	firm
T6S/R2W-5GB1	2	3	0	9	12	N/A	CL	stiff
T6S/R2W-5HB1	2	4	0	14	16	N/A	CL	stiff
T6S/R2W-5HB2	2	3	0	12	13	N/A	CL	stiff, firm
T6S/R2W-5JB1	2	4	0	9	14	N/A	CL	firm, stiff
T6S/R2W-5LB1	3	4	0	3.5	9	N/A	CL	firm, stiff
T6S/R2W-5LB2	N/A	2.5	4	N/A	15	N/A	CL	firm
T6S/R2W-5LB3	N/A	3.5	1.5	4	15	13-15	CL, SM	firm, dense
T6S/R2W-5PB1	3	8	0	6	12	N/A	CL	firm
T6S/R2W-5Q80	N/A	N/A	4	8	915	8-16, 34-38	SP, CL	N/A
T6S/R2W-5QB1	3	10	0	8	10	N/A	CL	firm
T6S/R2W-5RB1	N/A	N/A	6.5	10	20	17-19	CL, SC	stiff, medium dense
T6S/R2W-5RB2	6	N/A	3.5	11.5	20	N/A	CL	stiff
T6S/R2W-5RB3	N/A	6.5	6.5	11	20	17-19	CL, SP	very stiff, medium dense
T6S/R2W-6AB1	N/A	N/A	1	5	6	N/A	CL	stiff
T6S/R2W-8A80	N/A	N/A	5	13	376	N/A	CL	N/A
T6S/R2W-8A81	N/A	N/A	3	12	376	18-37	CL, SC	N/A
T6S/R2W-8B80	N/A	10	3	18	300	N/A	CL	N/A
T6S/R2W-8BB1	7.8	4.5	0	4.5	20	10.5-14	CL, SM	stiff, medium dense
T6S/R2W-8BB2	8.4	4.5	0	4	29	N/A	CL	stiff
T6S/R2W-8GB1	8.9	4	0	4	19	17-19	CL, SP	stiff, dense
T6S/R2W-8GB2	10	4.5	0	4.5	20	14-20	CL, SM	stiff, medium dense
T6S/R2W-8GB3	10	4.5	0	5	20	N/A	CL	stiff

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T6S/R2W-8GB4	10.7	5.5	0	5	20	N/A	CL	stiff, very stiff
T6S/R2W-8GB5	9.7	8.5	0	2.5	24	8.5-13.5	CL, SP	stiff, medium dense
T6S/R2W-8GB6	8.5	4.5	0	4	25	7.5-14	CL, SM	stiff, medium dense
T6S/R2W-8H1	N/A	N/A	3	12	80	15-18, 31-37	CL, SP	N/A
T6S/R2W-9AB1	N/A	9	8	>12.5	12.5	N/A	N/A	N/A
T6S/R2W-9AB2	N/A	6	9	N/A	14	N/A	CL	stiff
T6S/R2W-9AB3	10	10	16	N/A	25	N/A	CL	stiff
T6S/R2W-9AB4	12	11	17	18.5	25	N/A	CL	stiff
T6S/R2W-9AB5	10	12	16.5	N/A	25	N/A	CL	stiff
T6S/R2W-9AB6	6	4	10	N/A	25	21-25	CL, SC	stiff, medium dense
T6S/R2W-9B80	N/A	13	5	N/A	180	N/A	CL	N/A
T6S/R2W-9B82	5	N/A	11.5	N/A	25	11.5-20	SM, CL	medium dense, stiff
T6S/R2W-9B83	2	3	2.5	5.5	20	N/A	CL	stiff
T6S/R2W-9B84	12	7	8	11	25	23-25	CL, SM	stiff, medium dense
T6S/R2W-9B85	16	14	15	16	25	24-25	CL, SC	stiff, medium dense
T6S/R2W-9B86	7	6	6	N/A	25	10-19	SM, CL	medium dense, stiff
T6S/R2W-9EB1	6	6	3	N/A	25	19-25	CL, GM	very stiff, very dense
T6S/R2W-9FB1	8	5	2	5	22	N/A	CL	stiff
T6S/R2W-9FB2	5	N/A	0	3	25	19-25	CL, SM	stiff, medium dense
T6S/R2W-9FB3	7	N/A	2.5	N/A	25	2.5-10	SC, CL	medium dense, stiff
T6S/R2W-9GB1	7	7	5	N/A	20	8-14	SM, CL	medium dense, stiff
T6S/R2W-9H1	N/A	N/A	8	15	203	15-25	GW, CL	N/A
T6S/R2W-9H2	N/A	N/A	5	10	220	43-49	CL, SP	N/A
T6S/R2W-10AB1	N/A	N/A	2	>5.5	5.5	N/A	N/A	N/A
T6S/R2W-10AB2	N/A	N/A	5	>6	6	N/A	N/A	N/A
T6S/R2W-10AB3	N/A	3	2.5	5.5	30	23-29	CL, SC	stiff, dense
T6S/R2W-10AB4	N/A	3	0	6	28	22.5-28	CL, SC	stiff, dense
T6S/R2W-10AB5	N/A	2	0	3.5	30	8-11, 24-26.5	CL, SC	stiff, dense

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T6S/R2W-10B80	N/A	N/A	2	5	390	5-15, 33-39	SP, CL	N/A
T6S/R2W-10BB1	4	1	0	8.5	9	N/A	CL	firm
T6S/R2W-10BB2	N/A	N/A	2.5	>4	4	N/A	N/A	N/A
T6S/R2W-10CB1	4	N/A	4.5	7.5	16	9-10	CL, SC	firm, dense
T6S/R2W-10CB2	7	N/A	4.5	7.5	10	N/A	CL	stiff
T6S/R2W-10CB3	6	N/A	4.5	8	13.5	N/A	CL	stiff
T6S/R2W-10CB4	12.5	12	17.5	19	25	N/A	CL	stiff
T6S/R2W-10CB5	N/A	8	3	N/A	10.5	N/A	CL	firm
T6S/R2W-10DB2	6	11	5	9	25	24-25	CL	stiff, dense
T6S/R2W-10DB3	6	N/A	5	9	25	N/A	CL	stiff
T6S/R2W-10EB1	N/A	N/A	0	4	13.5	N/A	CL	stiff
T6S/R2W-10F80	N/A	N/A	0	3	24	9-11	CL, SP	N/A
T6S/R2W-10G80	N/A	8	4	N/A	620	8-14	CL, GW	N/A
T6S/R2W-10G81	N/A	N/A	3	5	332	N/A	CL	N/A
T6S/R2W-10G82	N/A	N/A	4	N/A	620	8-14	CL, GW	N/A
T6S/R2W-10GB1	N/A	N/A	2.5	N/A	3.5	N/A	CL	N/A
T6S/R2W-10J80	N/A	N/A	3	5	453	5-10, 32-34	CL, SP	N/A
T6S/R2W-10K80	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
T6S/R2W-10KB1	N/A	12	7	10	13	10-13	CL, SC	stiff, dense
T6S/R2W-11DB1	N/A	N/A	1.5	>6	6	N/A	N/A	N/A
T6S/R2W-11NB9	15.3	8	4	N/A	70	10-17, 27-39	CL, SC	firm, medium dense
T6S/R2W-11RB1	N/A	N/A	6	N/A	80	53-59	CL, SP	N/A
T6S/R2W-11RB2	N/A	N/A	5	N/A	101	59-66	CL, SP	N/A
T6S/R2W-12AB1	N/A	4	5	7	21	18.5-21	CL, SM	stiff, dense
T6S/R2W-12AB2	N/A	N/A	4	N/A	23	N/A	CL	stiff
T6S/R2W-12BB1	2	N/A	0.5	8	21	8-11	SC, CL	dense, stiff
T6S/R2W-12CB1	3	N/A	0	4.5	22	8-11	CL, SC	firm, dense
T6S/R2W-12FB1	N/A	0.5	3	4	5	N/A	CL	firm

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
T6S/R2W-12GB1	N/A	N/A	0	3.5	21	N/A	CL	stiff
T6S/R2W-12HB1	3.5	N/A	0	5	24	14-24	CL, SM	firm, dense
T6S/R2W-12JB1	3	N/A	0	4	21.5	15-21.5	CL, SM	stiff, dense
T6S/R2W-12JB2	N/A	N/A	4	5	10	N/A	CL, SC	stiff, dense
T6S/R2W-12KB1	N/A	N/A	1	N/A	1	N/A	CL	N/A
T6S/R2W-12NB1	N/A	N/A	4	N/A	100	14-18	CL, SP	N/A
T6S/R2W-12NB2	N/A	N/A	4	N/A	100	N/A	CL	N/A
T6S/R2W-13DB1	N/A	N/A	5	N/A	101	21-25, 39-43	CL, SP	N/A
T6S/R2W-13DB2	N/A	N/A	5	N/A	101	N/A	CL	N/A
T6S/R2W-13DB3	N/A	N/A	8	N/A	90	N/A	CL	N/A
T6S/R2W-13DB4	N/A	N/A	6	N/A	100	11-17, 41-44	CL, SP	N/A
WCC82-1	8.5	5	7.5	19.25	43	25.5-27, 33.25-36.75, 39.5-41.5	CH, CL	medium stiff to very stiff
WCC82-2	8.5	5.5	5.5	18	45	28-42	CH, CL	stiff to hard
WCC82-3	9	6.5	13	17	36.75	23-28	CL-CH	stiff, medium dense
WCC82-4	9	7	6.25	18.5	37	N/A	CL-CH	stiff to hard
WCC82-5	11	9.5	15	19	37	N/A	CL-CH	stiff to very stiff
WCC82-6	8	4.5	5.5	39.5	41.5	39.5-41.5	SP	dense
WCC82-7	10	5	7	32	41.5	32-35, 40-41.5	CL	stiff
WCC82-8	10.5	15	20.5	22	42	36-37.5	CL-CH, CL-ML	medium stiff to stiff
WCC82-9	7.5	8.5	11	11	14	N/A	CH	medium stiff
WCC82-10	8	9.5	12.25	12.25	18.5	N/A	CL-CH	very stiff
WCC82-11	-1	0.5	2	5.5	11.5	N/A	CL-CH	stiff
WCC82-12	-1	1	2	6	35	20-22.5	CL-CH	medium stiff to very stiff
WCC82-13	-1	4.5	1.5	2.5	42	18.5-20, 32-42	CL-CH, SC-SP	medium stiff to stiff
WCC82-14	11.5	6	15	>18.5	18.5	N/A	CL-CH	stiff
WCC83-15	N/A	3.25	3.5	9	16.5	N/A	CL	very stiff
WCC83-16	N/A	3	3	7	19	18.5-19	CH, CL-ML	medium stiff to stiff
WCC83-17	N/A	2.5	3.5	8	16.5	N/A	CL-CH	very stiff

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
WCC83-18	N/A	N/A	3	8	20	N/A	CL-CH, CL	stiff to very stiff
GJJ63-1	N/A	0.5	6.5	12	29	21-26.5	CL	soft, stiff
GJJ63-2	N/A	2	2	7	19	15-19	CL	medium stiff
GJJ63-3	N/A	2	1.75	4	14	N/A	CL	medium stiff
GJJ63-4	N/A	5	4	17	19	N/A	CL	stiff
GJJ63-5	N/A	2.5	2	>8	8	N/A	N/A	N/A
GJJ63-6	N/A	0.5	6	>8	8	N/A	N/A	N/A
GJJ63-7	N/A	3	3.5	8	14	11.5-14	CL	medium stiff
JLA69-1	N/A	2	6	14.5	22	14.5-15.5	CL	stiff
JLA69-2	N/A	3	5.25	10	21.5	N/A	CL	stiff to very stiff
JLA69-3	N/A	N/A	5.25	24.5	31.5	N/A	CL	stiff
JLA69-4	N/A	3.5	0.5	14.5	21.5	20.25-21.25	CL	stiff
JLA69-5	N/A	8	1.75	17	21.5	20-21.5	CL	very stiff
JLA69-6	N/A	4	8	15	19.5	16.25-19.5	CL	stiff
WCC61-1	4	2	5	10	42.5	26.5-42.5	CL	very stiff
WCC61-2	9.5	N/A	6.5	21	73	41-60, 63-73	SC, CL	loose, stiff
WCC61-3	8.5	N/A	10	25	54	41-54	CL	stiff
WCC61-4	8.1	5.5	5.5	19	67	40-67	CL, SC	stiff
WCC61-5	10.6	N/A	8	12	47	N/A	ML-CL, SM	loose, stiff
WCC61-6	2.4	N/A	1.5	9	30	9-12, 14-19.5	CL, ML	stiff
WCC61-7	6.1	N/A	3	10.5	30	N/A	CL-ML, CL	stiff
TT78-12	9	7.5	2	2	15.5	N/A	CL, SC	soft to stiff, dense
TT78-13	11	11	3.5	5	15.5	N/A	CL	stiff
TT78-14	11	11.2	4	13.5	19	N/A	CL	stiff
TT78-15	11	12.2	5	8	15.5	N/A	CL, SC	soft to stiff, medium dense
TT78-16	7	7	4	4	15.5	N/A	CL	stiff
TT78-17	9	10.5	2	8	20	12-20	CL	stiff
TT78-18	6	10.1	3	3	15.5	N/A	CL	stiff

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
TT78-19	6	6.1	4	4	25.5	11.5-15.5	CL	stiff to very stiff
TT78-20	8	N/A	6.5	9.5	15.5	N/A	CL	stiff to very stiff
TT78-21	8	N/A	5	12	15.5	N/A	CL	stiff
TT78-22	12	15.2	10	15	25.5	N/A	CL	stiff
TT78-23	11	N/A	2	4	10.5	N/A	CL, CH	very stiff
TT78-24	9	N/A	10	17.5	29	17.5-23	CL	stiff
TT78-25	11	N/A	7	>15.5	15.5	N/A	N/A	N/A
TT78-26	8	N/A	9.5	>10.5	10.5	N/A	N/A	N/A
TT78-27	10	10.2	4	18	42.5	34-42.5	CL	stiff
TT78-28	11	N/A	1.5	3	15.5	N/A	CL, CH	stiff
TT78-29	12	22.2	1.5	8.5	25.5	8.5-14, 23.5-25.5	CL	stiff to very stiff
TT78-37	6	4.5	6.5	6.5	31	N/A	CL	stiff
WCC85-1	2.5	N/A	N/A	7	30	7-19.5	SM, CL	N/A
WCC85-2	0	N/A	N/A	5.5	15.5	N/A	CH, CL	stiff to very stiff
WCC85-2A	9	N/A	9	>16.5	16.5	N/A	CL	stiff
WCC85-3	2.5	N/A	N/A	10.25	18.5	N/A	CH, CL	medium, very stiff
WCC85-3A	10	N/A	7.5	>19.5	19.5	N/A	CL	stiff
WCC85-4	2.5	N/A	N/A	9.5	17	N/A	CL	very stiff
WCC85-5	2.5	N/A	N/A	9	17	N/A	CH, CL	stiff, very stiff
WCC85-5A	9	6	6.75	>17.5	17.5	N/A	N/A	N/A
WCC85-6	1.5	N/A	N/A	8	16	N/A	CL	very stiff
WCC85-7	2.5	N/A	N/A	17	23.5	N/A	CL	very stiff
WCC85-8	13.5	12.5	17	N/A	20	N/A	N/A	N/A
WCC85-9	8	5.5	13	N/A	20	N/A	N/A	N/A
WCC85-10	13.5	12.5	15.5	N/A	21.5	N/A	N/A	N/A
WCC85-11	2	8	N/A	N/A	20	N/A	N/A	N/A
WCC85-12	13.5	12.5	11	N/A	20	N/A	N/A	N/A
WCC85-13	8	9	3	19	22	3-8, 19-22	ML	loose, stiff

APPENDIX A
BORING LOG DATABASE
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Boring Identifier	Ground Surface Elevation (ft)	Depth to Groundwater (ft)	Depth to Bottom of Fill (ft)	Depth to Bottom of Bay Mud, or Bay Mud Fill (ft)	Depth of Exploration (ft)	Depths of Potentially Liquefiable Layers (ft)	Predominant Unit below Bay Mud (USCS)	Consistency of Predominant Unit below Bay Mud
WCC85-14	4	4.5	N/A	18.5	20	N/A	CL	very stiff
WCC85-15	8	9.5	3.5	N/A	21.5	19.5-21	N/A	N/A
WCC85-16	10	10	N/A	N/A	25	5.5-6.5	N/A	N/A
WCC85-17	16	10	9.5	N/A	26.5	9.5-22	N/A	N/A
WCC85-P-1	8.6	8	N/A	17.5	25	8-8.5, 17.5-25	SW-SM	medium dense
WCC85-P-2	9.6	6	N/A	N/A	25	3-7	N/A	N/A
WA92-1	12.5	15	15.25	21	26	24-25.5	CL, SP	firm, very stiff, loose
WA92-2	12.8	16.1	15.25	22	26	22-25	SM, CL	loose, firm
WA92-3	13.3	17	15.25	18	26	N/A	CL	firm, very stiff
WA92-4	12.09	N/A	15.2	18	20	N/A	CL	very stiff
WA92-5	12.8	N/A	14	16	20	N/A	CL	hard
WA92-6	11	14	15	19	26	N/A	CL	stiff
WA92-13	-2.3	3	2.8	14.5	20	14.5-15.4	CL	firm, stiff
WA92-14	-2.3	3	N/A	14	21.5	14-16.4	CL	firm
WA92-15	2.4	7.2	4	9	21.5	N/A	CL	very stiff
WA92-16	-1.2	3	N/A	6	23	15-18	CL	very stiff, stiff
WA92-17	5	3	N/A	9	23	N/A	CL	very stiff to stiff
WA92-18	15.2	18	14	18.5	26	24-26	CL	very stiff, hard
WA92-19	15.5	23	9	16	26	N/A	CL	stiff
WA92-21	8.5	20	8.5	19	21.5	19-21.5	SM	loose
KL04-B1	0.4	3	N/A	16	60	27-60	SP, SM, SC	medium dense
KL04-B2	0.4	2	N/A	21	81.5	55-64	CH	stiff
KL04-B3	0.5	2.5	N/A	20	66.5	43-66.5	CL	stiff
KL04-B4	0	3	N/A	20	60	25-31, 55-60	SC, CL	medium dense, firm
KL04-B5	0.4	3	N/A	21	81.5	36-50.5	CH	very stiff
KL04-B6	0	2.5	N/A	26	71.5	30-49	SM, CH	very loose, very stiff
KL04-B7	0.3	2.5	N/A	21	71.5	43-65.5	SM	medium dense
EMC04-1	15	N/A	4	39.5	55.5	39.5-55.5	SP-SC	medium dense

APPENDIX B

**USACE 1988
LEVEE SURVEY SUMMARY**

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Alvisio	Alvisio	Alvisio	Alvisio	Alvisio
	Pond	A1	A1	A1	A1	A19
	Orientation	NE	S	SE	W	
	Reach ID	21	21	21	21	17
	Segment	101	100A	100B	102A	86C
	County	Santa Clara	Santa Clara	Santa Clara	Santa Clara	Santa Clara
	Survey By	M.W.	M.W.	M.W.	M.W.	G.O. & M.W.
	Date of Inspection	5/21/1984	5/21/1984	5/21/1984	5/21/1984	4/30/1984
	Ownership	Leslie Salt Co.	Santa Clara Valley Water Dist.	Leslie Salt Co.	Leslie Salt Co.	Santa Clara Valley Water Dist.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment		A	B		C
	Station From	Map sheet 19	Map sheet 19	Map sheet 19	Map sheet 19	See map sheet 22 & 18, 17
	Station To					
	Levee Type	Bay Shore - Ext	Slough/Creek - Int	Slough/Creek	Slough/Creek - Int	Salt Pond - Int
	Total Length	3200	1300	5400	2100	19300
	Length Good	0	0	0	0	0
	Length Fair	3200	1300	0	2100	0
Length Poor	0	0	5400	0	19300	
Function	Contains salt pond	Running path on land fill; no levee. See photo.	Divides salt ponds		Salt Pond Levee; composed of dredge spoils	
Alignment:	Crest Width	10	0	0	0	0
	Crest Condition	Fair				Poor
	Crest Elevation	7.6	10.1	8.2	8.2	6.6
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	15 O, 25 I				
	Slope Condition	Fair-Poor		Poor		Poor
	Toe Condition	Fair-Poor		Poor		Poor
Evidence of Failures:	Cracking	Yes		Yes		
	Seepage					
	Overtopping					
	Indications	Various				
Slope Protection:	Type	Vegetation	Vegetation	Vegetation		
	Location	Inboard	Inboard	Inboard		
	Extent	3200	1300	5400	0	0
	Condition	Fair	Good	Poor		
	Wave Erosion		Slight	Moderate		
	Undercutting	Yes				
	Soil Type	Clayey	Clayey	Clayey		Clayey
Condition of Slope Protection:	Type	Grass - brush	Grass	Grass - brush		None
	Extent	Outboard slope - Inboard slope	Outboard slope	Outboard slope - Inboard slope		
	Degree	Thick	Light	Light		
	Levee Use	Paved - Author Vehicle - Upgrading needed	Paved - Graded	Unpaved - Ungraded		Ungraded
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Alvisio	Alvisio	Alvisio	Alvisio	Alvisio
	Pond	A22	A22	A23	A23	A2E
	Orientation	S - SE	W - N - E	E - S - W	N - NW	E
	Reach ID	17	17	17	17	19
	Segment	88	88	86C	86C	94F
	County	Santa Clara	Santa Clara	Santa Clara	Santa Clara	Santa Clara
	Survey By	G.O. & M.W.	G.O. & M.W.	G.O. & M.W.	G.O. & M.W.	
	Date of Inspection	4/30/1984	4/30/1984	4/30/1984	4/30/1984	5/21/1984
	Ownership			Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	
	Method			Ground	Ground	Ground
	Levee Segment			C	C	F
	Station From	Map Sheet 17	Map Sheet 17	See map sheet 22 & 18, 17	See map sheet 22 & 18, 17	Map sheet 20, 21
	Station To					
	Levee Type	Slough/Creek - Int	Slough/Creek - Int	Salt Pond - Int	Salt Pond - Int	Slough/Creek - Int
	Total Length	11300	11300	19300	19300	6400
	Length Good	0	0	0	0	6400
	Length Fair	0	0	0	0	0
Length Poor	11300	11300	19300	19300	0	
Function	Salt Pond levee; composed of dredge spoils	Salt Pond levee; composed of dredge spoils	Salt Pond Levee; composed of dredge spoils	Salt Pond Levee; composed of dredge spoils	Protects Moffett Field, contains salt pond	
Alignment:	Crest Width	0	0	0	0	15
	Crest Condition	Poor	Poor	Poor	Poor	Fair
	Crest Elevation	6.6	6.6	6.6	6.6	6.2
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees					25 O, 25 I
	Slope Conditon	Poor	Poor	Poor	Poor	Good
	Toe Condition	Poor	Poor	Poor	Poor	Good
Evidence of Failures:	Cracking					
	Seepage					
	Overtopping					
	Indications					
Slope Protection:	Type					Vegetation
	Location					Inboard
	Extent	0	0	0	0	6400
	Condition					Fair
	Wave Erosion					Slight
	Undercutting					
	Soil Type	Clayey	Clayey	Clayey	Clayey	Clayey - Sandy
Condition of Slope Protection:	Type			None	None	Grass - Brush
	Extent					Inboard slope
	Degree					Light
	Levee Use	Unpaved - ungraded	Unpaved - ungraded	Ungraded	Ungraded	
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Alvisio	Alvisio	Alvisio	Alvisio	Alvisio
	Pond	A2E	A2E	A2E	A2W	A2W
	Orientation	N - NW	S - SW	W	E	N - NE
	Reach ID	19	19	19	20	20
	Segment	96A	96A	96A	97B	97A
	County	Santa Clara	Santa Clara	Santa Clara	Santa Clara	Santa Clara
	Survey By	M.W.	M.W.	M.W.	M.W.	M.W.
	Date of Inspection	5/16/1984	5/16/1984	5/16/1984	5/16/1984	5/16/1984
	Ownership	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	A	A	A	B	A
	Station From	Map sheet 20	Map sheet 20	Map sheet 20	Map sheet 19, 20	Map sheet 20, 19
	Station To					
	Levee Type	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int
	Total Length	4500	4500	4500	3800	4500
	Length Good	0	0	0	3800	0
	Length Fair	0	0	0	0	4500
Length Poor	4500	4500	4500	0	0	
Function	Contains Stevens Creek	Contains Stevens Creek	Contains Stevens Creek	Contains Stevens Creek	Contains Stevens Creek	
Alignment:	Crest Width	25	25	25	12	25
	Crest Condition	Poor	Poor	Poor	Good	Poor
	Crest Elevation	8.4	8.4	8.4	7.0	6.5
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	35 O, 25 I	35 O, 25 I	35 O, 25 I	30 O, 30 I	35 O, 25 I
	Slope Conditon	Poor	Poor	Poor	Good	Fair
	Toe Condition	Poor	Poor	Poor	Good	Fair
Evidence of Failures:	Cracking	Yes	Yes	Yes		Yes
	Seepage					
	Overtopping					
Slope Protection:	Indications	Outboard	Outboard	Outboard		Outboard
	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Inboard	Inboard	Inboard	Inboard	Inboard
	Extent	0	0	0	3800	4500
	Condition	Poor	Poor	Poor	Good	Fair
	Wave Erosion	Intense	Intense	Intense		Moderate
	Undercutting					
Condition of Slope Protection:	Soil Type	Clayey	Clayey	Clayey	Clayey - Sandy	Clayey
	Type	Grass	Grass	Grass	Grass	Grass
	Extent	Outboard slope	Outboard slope	Outboard slope	Outboard slope	Outboard slope
	Degree	Light	Light	Light	Light	Light
	Levee Use	Unpaved - Author Vehilce Graded - Upgrading needed	Unpaved - Author Vehilce Graded - Upgrading needed	Unpaved - Author Vehilce Graded - Upgrading needed	Unpaved - Author Vehicle graded	Unpaved - Author Vehicle graded
	Evaluation:	Very Good				3800
Adequate		0	0	0	0	0
Poor		0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Alvisio	Alvisio	Alvisio	Alvisio	Alvisio
	Pond	A2W	A2W	A5	A5	A5
	Orientation	NW	S	E	N	NE
	Reach ID	20	20	18	18	18
	Segment	99A	99A	93D	91B	91B
	County	Santa Clara	Santa Clara	Santa Clara	Santa Clara	Santa Clara
	Survey By	M.W.	M.W.	M.W.	G.O.	G.O.
	Date of Inspection	5/18/1984	5/18/1984	5/10/1984	5/8/1984	5/8/1984
	Ownership	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	A	A	A	B	B
	Station From	Map sheet 19	Map sheet 19	Map sheet 16, 20, 21	Map sheet 21, 24, 25	Map sheet 21, 24, 25
	Station To					
	Levee Type	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int
	Total Length	5800	5800	24600	12400	12400
	Length Good	0	0	0	12400	12400
	Length Fair	5800	5800	0	0	0
Length Poor	0	0	24600	0	0	
Function	Contains slough	Contains slough	Divides salt ponds	Protect residential and commercial areas	Protect residential and commercial areas	
Alignment:	Crest Width	12	12	17	12	12
	Crest Condition	Good	Good	Poor	Good	Good
	Crest Elevation	3.5	3.5	7.0	9.3	9.3
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	20 O, 20 I	20 O, 20 I	15 O, 15 I	25 O, 30 I	25 O, 30 I
	Slope Conditon	Fair	Fair	Poor	Good	Good
	Toe Condition	Fair	Fair	Poor		
Evidence of Failures:	Cracking			Yes		
	Seepage					
	Overtopping					
	Indications					
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Inboard	Inboard	Inboard	Inboard	Inboard
	Extent	5800	5800	24600	0	0
	Condition	Good	Good	Poor	Good	Good
	Wave Erosion	Slight	Slight	Intense	Slight	Slight
	Undercutting			Yes, various		
	Soil Type	Clayey	Clayey	Clayey	Gravelly Clay	Gravelly Clay
Condition of Slope Protection:	Type	Grass - brush	Grass - brush	Grass - Brush	Grass - Brush	Grass - Brush
	Extent	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Crest - Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope
	Degree	Light	Light	Light - Thick	Denser	Denser
	Levee Use	Unpaved - Author Vehicle graded	Unpaved - Author Vehicle graded	Unpaved, ungraded	Unpaved	Unpaved
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Alvisio	Alvisio	Alvisio	Alvisio	Alvisio
	Pond	A5	A6	A6	A6	A6
	Orientation	S - W - N	E	N	N - NE	NE
	Reach ID	18	18	18	18	18
	Segment	93D	91D	91D	92	92
	County	Santa Clara	Santa Clara	Santa Clara	Santa Clara	Santa Clara
	Survey By	M.W.	M.W.	M.W.	M.W.	M.W.
	Date of Inspection	5/10/1984	5/10/1984	5/10/1984	5/10/1984	5/10/1984
	Ownership	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	A	D	D		
	Station From	Map sheet 16, 20, 21	Map 16, 20, 21	Map 16, 20, 21	Map sheet 16	Map sheet 16
	Station To					
	Levee Type	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Ext	Slough/Creek - Ext
	Total Length	24600	19600	19600	5500	5500
	Length Good	0	0	0	0	0
	Length Fair	0	0	0	0	0
Length Poor	24600	19600	19600	5500	5500	
Function	Divides salt ponds	Contains Alvisio Slough	Contains Alvisio Slough			
Alignment:	Crest Width	17	0	0	0	0
	Crest Condition	Poor				
	Crest Elevation	7.0	8.1	8.1	8.2	8.2
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	15 O, 15 I				
	Slope Condition	Poor			Poor	Poor
	Toe Condition	Poor			Poor	Poor
Evidence of Failures:	Cracking	Yes			Yes	Yes
	Seepage					
	Overtopping					
	Indications					
Slope Protection:	Type	Vegetation				
	Location	Inboard				
	Extent	24600	0	0	0	0
	Condition	Poor				
	Wave Erosion	Intense	Moderate	Moderate		
	Undercutting	Yes, various				
	Soil Type	Clayey	Clayey	Clayey	Clayey	Clayey
Condition of Slope Protection:	Type	Grass - Brush			Riprap gravel	Riprap gravel
	Extent	Crest - Outboard slope - Inboard slope			Crest - Outboard slope - Inboard slope	Crest - Outboard slope - Inboard slope
	Degree	Light - Thick			Light	Light
	Levee Use					
		Unpaved, ungraded			Unpaved - Graded	Unpaved - Graded
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Alvisio	Alvisio	Alvisio	Alvisio	Alvisio
	Pond	A6	A6	A6	A6	A6
	Orientation	NW	S	S	S	SW
	Reach ID	18	18	18	18	18
	Segment	92	91D	91D	91B	92
	County	Santa Clara	Santa Clara	Santa Clara	Santa Clara	Santa Clara
	Survey By	M.W.	M.W.	M.W.	G.O.	M.W.
	Date of Inspection	5/10/1984	5/10/1984	5/10/1984	5/8/1984	5/10/1984
	Ownership	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment		D	D	B	
	Station From	Map sheet 16	Map 16, 20, 21	Map 16, 20, 21	Map sheet 21, 24, 25	Map sheet 16
	Station To					
	Levee Type	Slough/Creek - Ext	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Ext
	Total Length	5500	19600	19600	12400	5500
	Length Good	0	0	0	12400	0
	Length Fair	0	0	0	0	0
	Length Poor	5500	19600	19600	0	5500
	Function		Contains Alvisio Slough	Contains Alvisio Slough	Protect residential and commercial areas	
Alignment:	Crest Width	0	0	0	12	0
	Crest Condition				Good	
	Crest Elevation	8.2	8.1	8.1	9.3	8.2
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees				25 O, 30 I	
	Slope Condition	Poor			Good	Poor
	Toe Condition	Poor				Poor
Evidence of Failures:	Cracking	Yes				Yes
	Seepage					
	Overtopping					
	Indications					
Slope Protection:	Type				Vegetation	
	Location				Inboard	
	Extent	0	0	0	0	0
	Condition				Good	
	Wave Erosion		Moderate	Moderate	Slight	
	Undercutting					
	Soil Type	Clayey	Clayey	Clayey	Gravelly Clay	Clayey
Condition of Slope Protection:	Type	Riprap gravel			Grass - Brush	Riprap gravel
	Extent	Crest - Outboard slope - Inboard slope			Outboard slope - Inboard slope	Crest - Outboard slope - Inboard slope
	Degree	Light			Denser	Light
	Levee Use					
		Unpaved - Graded			Unpaved	Unpaved - Graded
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Alvisio	Alvisio	Alvisio	Alvisio	Alvisio
	Pond	A6	A6	A7	A7	A7
	Orientation	SW	SW - W	E	N - NE	SW
	Reach ID	18	18	18	18	18
	Segment	91B	93D	91D	91D	91B
	County	Santa Clara	Santa Clara	Santa Clara	Santa Clara	Santa Clara
	Survey By	G.O.	M.W.	M.W.	M.W.	G.O.
	Date of Inspection	5/8/1984	5/10/1984	5/10/1984	5/10/1984	5/8/1984
	Ownership	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	B	A	D	D	B
	Station From	Map sheet 21, 24, 25	Map sheet 16, 20, 21	Map 16, 20, 21	Map 16, 20, 21	Map sheet 21, 24, 25
	Station To					
	Levee Type	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int
	Total Length	12400	24600	19600	19600	12400
	Length Good	12400	0	0	0	12400
	Length Fair	0	0	0	0	0
Length Poor	0	24600	19600	19600	0	
Function	Protect residential and commercial areas	Divides salt ponds	Contains Alvisio Slough	Contains Alvisio Slough	Protect residential and commercial areas	
Alignment:	Crest Width	12	17	0	0	12
	Crest Condition	Good	Poor			Good
	Crest Elevation	9.3	7.0	8.1	8.1	9.3
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	25 O, 30 I	15 O, 15 I			25 O, 30 I
	Slope Conditon	Good	Poor			Good
	Toe Condition		Poor			
Evidence of Failures:	Cracking		Yes			
	Seepage					
	Overtopping					
	Indications					
Slope Protection:	Type	Vegetation	Vegetation			Vegetation
	Location	Inboard	Inboard			Inboard
	Extent	0	24600	0	0	0
	Condition	Good	Poor			Good
	Wave Erosion	Slight	Intense	Moderate	Moderate	Slight
	Undercutting		Yes, various			
	Soil Type	Gravelly Clay	Clayey	Clayey	Clayey	Gravelly Clay
Condition of Slope Protection:	Type	Grass - Brush	Grass - Brush			Grass - Brush
	Extent	Outboard slope - Inboard slope	Crest - Outboard slope - Inboard slope			Outboard slope - Inboard slope
	Degree	Denser	Light - Thick			Denser
	Levee Use	Unpaved	Unpaved, ungraded			Unpaved
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Alvisio	Alvisio	Alvisio	Alvisio	Alvisio
	Pond	A8N	A8N	A8N	A8S	A8S
	Orientation	NE	S	W	N	S
	Reach ID	18	18	18	18	18
	Segment	91D	91A	91A	93G	93G
	County	Santa Clara	Santa Clara	Santa Clara	Santa Clara	Santa Clara
	Survey By	M.W.	G.O.	G.O.	M.W.	M.W.
	Date of Inspection	5/10/1984	5/8/1984	5/8/1984	5/10/1984	5/10/1984
	Ownership	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	D	A	A	C	C
	Station From	Map 16, 20, 21	Map sheet 25	Map sheet 25	Map sheet 21	Map sheet 21
	Station To					
	Levee Type	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int
	Total Length	19600	4750	4750	3500	3500
	Length Good	0	4750	4750	0	0
	Length Fair	0	0	0	3500	3500
Length Poor	19600	0	0	0	0	
Function	Contains Alvisio Slough	Protect residential and commercial areas	Protect residential and commercial areas	Separates ponds and protect residential and commercial areas	Separates ponds and protect residential and commercial areas	
Alignment:	Crest Width	0	12	12	15	15
	Crest Condition		Good	Good	Fair	Fair
	Crest Elevation	8.1	10.0	10.0	8.5	8.5
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees		25 O, 25 I	25 O, 25 I	15 O, 25 I	15 O, 25 I
	Slope Conditon		Good	Good	Fair	Fair
	Toe Condition				Fair	Fair
Evidence of Failures:	Cracking				Yes	Yes
	Seepage					
	Overtopping					
	Indications				Various	Various
Slope Protection:	Type		Vegetation	Vegetation	Vegetation	Vegetation
	Location		Inboard	Inboard	Inboard	Inboard
	Extent	0	4750	4750	3500	3500
	Condition		Fair	Fair	Fair	Fair
	Wave Erosion	Moderate	Slight	Slight	Slight	Slight
	Undercutting					
	Soil Type	Clayey	Gravelly Clay	Gravelly Clay	Mixture	Mixture
Condition of Slope Protection:	Type		Grass - Brush	Grass - Brush	Grass - Brush	Grass - Brush
	Extent		Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope
	Degree		Thick	Thick	Thick	Thick
	Levee Use		Unpaved gravel	Unpaved gravel	Unpaved	Unpaved
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Alvisio	Alvisio	Alvisio	Alvisio	Alvisio
	Pond	A8S	A8S	AB1	AB2	AB2
	Orientation	S	W - N - E	W - NE	SE	W
	Reach ID	18	18	19	19	19
	Segment	93G	91A	96A	94F	94F
	County	Santa Clara	Santa Clara	Santa Clara	Santa Clara	Santa Clara
	Survey By	M.W.	G.O.	M.W.		
	Date of Inspection	5/10/1984	5/8/1984	5/16/1984	5/21/1984	5/21/1984
	Ownership	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.	Santa Clara Valley Water Dist.		
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	C	A	A	F	F
	Station From	Map sheet 21	Map sheet 25	Map sheet 20	Map sheet 20, 21	Map sheet 20, 21
	Station To					
	Levee Type	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int
	Total Length	3500	4750	4500	6400	6400
	Length Good	0	4750	0	6400	6400
	Length Fair	3500	0	0	0	0
Length Poor	0	0	4500	0	0	
Function	Separates ponds and protect residential and commercial areas	Protect residential and commercial areas	Contains Stevens Creek	Protects Moffett Field, contains salt pond	Protects Moffett Field, contains salt pond	
Alignment:	Crest Width	15	12	25	15	15
	Crest Condition	Fair	Good	Poor	Fair	Fair
	Crest Elevation	8.5	10.0	8.4	6.2	6.2
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	15 O, 25 I	25 O, 25 I	35 O, 25 I	25 O, 25 I	25 O, 25 I
	Slope Conditon	Fair	Good	Poor	Good	Good
	Toe Condition	Fair		Poor	Good	Good
Evidence of Failures:	Cracking	Yes		Yes		
	Seepage					
	Overtopping					
	Indications	Various		Outboard		
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Inboard	Inboard	Inboard	Inboard	Inboard
	Extent	3500	4750	0	6400	6400
	Condition	Fair	Fair	Poor	Fair	Fair
	Wave Erosion	Slight	Slight	Intense	Slight	Slight
	Undercutting					
Condition of Slope Protection:	Soil Type	Mixture	Gravelly Clay	Clayey	Clayey - Sandy	Clayey - Sandy
	Type	Grass - Brush	Grass - Brush	Grass	Grass - Brush	Grass - Brush
	Extent	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope	Inboard slope	Inboard slope
	Degree	Thick	Thick	Light	Light	Light
	Levee Use	Unpaved	Unpaved gravel	Unpaved - Author Vehilce Graded - Upgrading needed		
Evaluation:	Very Good					
	Adequate	0	0	0	0	
	Poor	0	0	0	0	

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Eden Landing	Eden Landing	Eden Landing	Eden Landing	Eden Landing
	Pond	B_temp1	B_temp1	B_temp1	B_temp1	B_temp2
	Orientation	NE	NE	SW	W	SE
	Reach ID	10	10	10	10	12
	Segment	45C	50	47	51	54B
	County	Alameda	Alameda	Alameda	Alameda	Alameda
	Survey By		M.W. & S.K.	M.W. & S.K.	M.W. & G.O.	M.W. & S.K.
	Date of Inspection	3/27/1984	3/27/1984	3/27/1984	3/27/1984	3/30/1984
	Ownership	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	C				B
	Station From	See map	End of Slough	S. Edge of Mt. Eden Creek	S. Edge of Union City Slough	See map
	Station To		S. Edge of Union City Slough	End of Creek	N. Edge of old Alameda Creek	
	Levee Type	Bay Shore	Slough/Creek - Int	Slough/Creek - Int	Bay Shore - Ext	Bay Shore - Ext
	Total Length	1100	6200	15000	1100	1900
	Length Good	0	0	0	0	0
	Length Fair	0	0	15000	0	1900
	Length Poor	1100	6200	0	1100	0
	Function	Protect Salt Pond	No levee only shoreline without protection	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond
Alignment:	Crest Width	13	0	0	12	0
	Crest Condition	Poor		Fair	Poor	Poor
	Crest Elevation	6.8	3.5	6.6	6.1	5.8
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees			Inside has heavy erosion vertical drop to 40 slope	10	11-13 IO
	Slope Condition	Poor		Fair	Poor	Poor
	Toe Condition	Poor		Fair	Poor	Poor
Evidence of Failures:	Cracking	No			No	No
	Seepage	No			No	Yes
	Overtopping	Yes		Yes	Yes	Yes
	Indications					Yes, numerous places
Slope Protection:	Type			Vegetation	Vegetation	Vegetation
	Location			Outboard	Inboard	Inboard
	Extent	0	0	15000	0	1900
	Condition	Poor		Fair	Poor	Poor
	Wave Erosion	Intense		Slight - Intense	Intense	Intense
	Undercutting					
	Soil Type	Mixture Mud		Clayey - Mixture Mud	Mixture Mud	Clayey - Mixture Mud
Condition of Slope Protection:	Type		Grass - Brush	Grass - Brush		Grass - Brush
	Extent		Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope		Outboard slope - Inboard slope
	Degree		Light	Thick		Thick
	Levee Use		Unpaved - Author Vehicle Upgrading Needed			
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	1100	15000	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Eden Landing	Eden Landing	Eden Landing	Eden Landing	Eden Landing
	Pond	B1	B1	B1	B10	B10
	Orientation	N	S	W	E - N	N - NW
	Reach ID	12	12	12	10	10
	Segment	54A	54A	54B	46A1	45A
	County	Alameda	Alameda	Alameda	Alameda	Alameda
	Survey By	G.O. & M.W.	G.O. & M.W.	M.W. & S.K.	M.W. & G.O.	M.W. & G.O.
	Date of Inspection	3/30/1984	3/30/1984	3/30/1984	3/27/1984	3/27/1984
	Ownership	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	A	A	B	A	A
	Station From	See map	See map	See map	See map	See map
	Station To					
	Levee Type	Bay Shore - Ext	Bay Shore - Ext	Bay Shore - Ext	Slough/Creek - Int	Bay Shore
	Total Length	3000	3000	1900	7000	1400
	Length Good	0	0	0	0	0
	Length Fair	3000	3000	1900	0	0
Length Poor	0	0	0	7000	1400	
Function	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	
Alignment:	Crest Width	16	16	0	14	13
	Crest Condition	Fair	Fair	Poor	Fair - Poor	Poor
	Crest Elevation	7.2	7.2	5.8	6.1	7.0
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	10-15 O, 25 I	10-15 O, 25 I	11-13 IO	9 - 15	11 - 14
	Slope Conditon	Fair	Fair	Poor	Fair - Poor	Poor
	Toe Condition			Poor	Fair - Poor	Poor
Evidence of Failures:	Cracking	No	No	No	No	No
	Seepage	No	No	Yes	No	No
	Overtopping			Yes	Yes	Yes
	Indications			Yes, numerous places		No
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	
	Location	Inboard	Inboard	Inboard	Outboard	
	Extent	3000	3000	1900	6500	0
	Condition	Fair	Fair	Poor	Poor	Poor
	Wave Erosion	Slight	Slight	Intense	Slight	
	Undercutting	No	No			
	Soil Type	Clayey	Clayey	Clayey - Mixture Mud	Sandy - Gravelly	Mixture Mud
Condition of Slope Protection:	Type	Grass	Grass	Grass - Brush	Grass - Brush	
	Extent	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope		
	Degree	Light	Light	Thick		
	Levee Use	Unpaved - Trail	Unpaved - Trail		Unpaved - Author Vehicle Graded	
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	0	0	0	1400

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Eden Landing	Eden Landing	Eden Landing	Eden Landing	Eden Landing
	Pond	B10	B10	B11	B11	B12
	Orientation	S - E	SW	N - E	W - S	S
	Reach ID	10	10	10	10	10
	Segment	45C	45A	46A1	46A1	46B
	County	Alameda	Alameda	Alameda	Alameda	Alameda
	Survey By		M.W. & G.O.	M.W. & G.O.	M.W. & G.O.	M.W. & S.K.
	Date of Inspection	3/27/1984	3/27/1984	3/27/1984	3/27/1984	3/27/1984
	Ownership	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	C	A	A	A	B
	Station From	See map	See map	See map	See map	See map
	Station To					
	Levee Type	Bay Shore	Bay Shore	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int
	Total Length	1100	1400	7000	7000	3000
	Length Good	0	0	0	0	0
	Length Fair	0	0	0	0	0
Length Poor	1100	1400	7000	7000	3000	
Function	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	
Alignment:	Crest Width	13	13	14	14	10
	Crest Condition	Poor	Poor	Fair - Poor	Fair - Poor	Fair - Poor
	Crest Elevation	6.8	7.0	6.1	6.1	6.6
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees		11 - 14	9 - 15	9 - 15	20
	Slope Conditon	Poor	Poor	Fair - Poor	Fair - Poor	Fair - Poor
	Toe Condition	Poor	Poor	Fair - Poor	Fair - Poor	Fair - Poor
Evidence of Failures:	Cracking	No	No	No	No	No
	Seepage	No	No	No	No	No
	Overtopping	Yes	Yes	Yes	Yes	No
	Indications		No			
Slope Protection:	Type			Vegetation	Vegetation	Vegetation
	Location			Outboard	Outboard	Inboard
	Extent	0	0	6500	6500	0
	Condition	Poor	Poor	Poor	Poor	Poor
	Wave Erosion	Intense		Slight	Slight	Slight
	Undercutting					
Condition of Slope Protection:	Type	Mixture Mud	Mixture Mud	Sandy - Gravelly	Sandy - Gravelly	Mixture Mud
	Extent			Grass - Brush	Grass - Brush	Grass - Brush
	Degree					Crest - Outboard slope - Inboard slope Thick
	Levee Use			Unpaved - Author Vehicle Graded	Unpaved - Author Vehicle Graded	
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	1400	0	0	3000

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Eden Landing	Eden Landing	Eden Landing	Eden Landing	Eden Landing
	Pond	B12	B12	B13	B14	B14
	Orientation	W - N	W - N - E	SE	E - S	N - N-W
	Reach ID	10	10	10	10	10
	Segment	46A2	46A2	46B	46C	46C
	County	Alameda	Alameda	Alameda	Alameda	Alameda
	Survey By	M.W. & S.K.	M.W. & S.K.	M.W. & S.K.	M.W. & G.O.	M.W. & G.O.
	Date of Inspection	3/27/1984	3/27/1984	3/27/1984	3/27/1984	3/27/1984
	Ownership	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	A	A	B	C	C
	Station From	See map	See map	See map	See map	See map
	Station To					
	Levee Type	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int
	Total Length	5300	5300	3000	8000	8000
	Length Good	0	0	0	0	0
	Length Fair	5300	5300	0	0	0
Length Poor	0	0	3000	8000	8000	
Function	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	
Alignment:	Crest Width	0	0	10	12	12
	Crest Condition	Fair	Fair	Fair - Poor	Fair	Fair
	Crest Elevation	5.4	5.4	6.6	5.8	5.8
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	9 - 15	9 - 15	20	16 - Inside has heavy erosion vertical drop to 40 slope	16 - Inside has heavy erosion vertical drop to 40 slope
	Slope Condition	Fair	Fair	Fair - Poor	Poor	Poor
	Toe Condition	Fair	Fair	Fair - Poor	Poor	Poor
Evidence of Failures:	Cracking	No	No	No	No	No
	Seepage	No	No	No	No	No
	Overtopping	Yes	Yes	No	Yes	Yes
	Indications					
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Outboard	Outboard	Inboard	Inboard	Inboard
	Extent	5300	5300	0	8000	8000
	Condition	Fair	Fair	Poor	Fair - Poor	Fair - Poor
	Wave Erosion	Slight - Intense	Slight - Intense	Slight	Intense	Intense
	Undercutting					
Condition of Slope Protection:	Type	Grass - Brush	Grass - Brush	Grass - Brush	Grass - Brush	Grass - Brush
	Extent	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope	Crest - Outboard slope - Inboard slope	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope
	Degree	Thick	Thick	Thick	Thick	Thick
	Levee Use	Unpaved - Author Vehicle Graded	Unpaved - Author Vehicle Graded		Unpaved - Author Vehicle Graded	Unpaved - Author Vehicle Graded
Evaluation:	Very Good					
	Adequate	5300	5300	0	0	0
	Poor	0	0	3000	8000	8000

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Eden Landing	Eden Landing	Eden Landing	Eden Landing	Eden Landing
	Pond	B14	B1C	B1C	B2	B2
	Orientation	S - W	E	W	E	N
	Reach ID	10	12	12	12	12
	Segment	50	57A	57A	56B	54A
	County	Alameda	Alameda	Alameda	Alameda	Alameda
	Survey By	M.W. & S.K.	G.O. & S.K.	G.O. & S.K.	M.W. & G.O.	G.O. & M.W.
	Date of Inspection	3/27/1984	4/9/1984	4/9/1984	4/17/1984	3/30/1984
	Ownership	Leslie Salt Co.	County of Alameda	County of Alameda	County of Alameda	Leslie Salt Co.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment		A	A		A
	Station From	End of Slough	See map	See map		See map
	Station To	S. Edge of Union City Slough				
	Levee Type	Slough/Creek - Int	Slough/Creek	Slough/Creek	int.	Bay Shore - Ext
	Total Length	6200	13000	13000	13000	3000
	Length Good	0	13000	13000	13000	0
	Length Fair	0	0	0	0	3000
Length Poor	6200	0	0	0	0	
Function	No levee only shoreline without protection	Buffer between Channel & low lying adjacent lands	Buffer between Channel & low lying adjacent lands		Protect Salt Pond	
Alignment:	Crest Width	0	16	16	12	16
	Crest Condition		Good	Good		Fair
	Crest Elevation	3.5	20.0	20.0	4.9	7.2
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees		25-30 IO	25-30 IO	15 O, 25 I	10-15 O, 25 I
	Slope Condition		Good	Good	Good	Fair
	Toe Condition		Good	Good	Good	
Evidence of Failures:	Cracking		No	No	No	No
	Seepage		No	No	No	No
	Overtopping		No	No	No	
	Indications		No	No		
Slope Protection:	Type		Vegetation	Vegetation	Vegetation	Vegetation
	Location		Inboard	Inboard	Inboard	Inboard
	Extent	0	13000	13000	0	3000
	Condition		Good	Good	Good	Fair
	Wave Erosion					Slight
	Undercutting				No	No
	Soil Type		Clayey	Clayey	Clayey - Sandy - Gravelly	Clayey
Condition of Slope Protection:	Type	Grass - Brush	Grass - Riprap	Grass - Riprap	Grass	Grass
	Extent	Outboard Slope - Inboard Slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope
	Degree	Light	Light	Light	Thick	Light
	Levee Use	Unpaved - Author Vehicle Upgrading Needed	Unpaved - Author Vehicle Trail	Unpaved - Author Vehicle Trail	Unpaved - Author Vehicle Graded	Unpaved - Trail
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	1100	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Eden Landing	Eden Landing	Eden Landing	Eden Landing	Eden Landing
	Pond	B2	B2	B2	B2C	B2C
	Orientation	NW - N	SE	SW	E	NW - SW
	Reach ID	12	12	12	12	12
	Segment	54B	56B	54C	57A	57A
	County	Alameda	Alameda	Alameda	Alameda	Alameda
	Survey By	M.W. & S.K.	M.W. & G.O.	M.W. & G.O.	G.O. & S.K.	G.O. & S.K.
	Date of Inspection	3/30/1984	4/17/1984	3/27/1984	4/9/1984	4/9/1984
	Ownership	Leslie Salt Co.	County of Alameda	Leslie Salt Co.	County of Alameda	County of Alameda
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	B		C	A	A
	Station From	See map		See map	See map	See map
	Station To					
	Levee Type	Bay Shore - Ext	int.	Bay Shore - Ext	Slough/Creek	Slough/Creek
	Total Length	1900	13000	2700	13000	13000
	Length Good	0	13000	0	13000	13000
	Length Fair	1900	0	0	0	0
Length Poor	0	0	2700	0	0	
Function	Protect Salt Pond		Protect Salt Pond	Buffer between Channel & low lying adjacent lands	Buffer between Channel & low lying adjacent lands	
Alignment:	Crest Width	0	12	0	16	16
	Crest Condition	Poor		Poor	Good	Good
	Crest Elevation	5.8	4.9	8.3	20.0	20.0
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	11-13 IO	15 O, 25 I		25-30 IO	25-30 IO
	Slope Conditon	Poor	Good	Poor	Good	Good
	Toe Condition	Poor	Good	Poor	Good	Good
Evidence of Failures:	Cracking	No	No	Yes	No	No
	Seepage	Yes	No		No	No
	Overtopping	Yes	No		No	No
	Indications	Yes, numerous places			No	No
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Inboard	Inboard	Inboard	Inboard	Inboard
	Extent	1900	0	2700	13000	13000
	Condition	Poor	Good	Poor	Good	Good
	Wave Erosion	Intense		Intense		
	Undercutting		No			
Condition of Slope Protection:	Soil Type	Clayey - Mixture Mud	Clayey - Sandy - Gravelly	Clayey - Mixture Mud	Clayey	Clayey
	Type	Grass - Brush	Grass		Grass - Riprap	Grass - Riprap
	Extent	Outboard slope - Inboard slope	Outboard slope - Inboard slope		Outboard slope - Inboard slope	Outboard slope - Inboard slope
	Degree	Thick	Thick		Light	Light
Levee Use		Unpaved - Author Vehicle Graded		Unpaved - Graded	Unpaved - Author Vehicle Trail	Unpaved - Author Vehicle Trail
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Eden Landing	Eden Landing	Eden Landing	Eden Landing	Eden Landing
	Pond	B4	B4	B4	B5	B5
	Orientation	N	SE - SW	W	NW - W	SE
	Reach ID	12	12	12	12	12
	Segment	56B	56B	56B	56A	56A
	County	Alameda	Alameda	Alameda	Alameda	Alameda
	Survey By	M.W. & G.O.	M.W. & G.O.	M.W. & G.O.	M.W. & G.O.	M.W. & G.O.
	Date of Inspection	4/17/1984	4/17/1984	4/17/1984	4/17/1984	4/17/1984
	Ownership	County of Alameda	County of Alameda	County of Alameda	County of Alameda	County of Alameda
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment				A	A
	Station From				See map	See map
	Station To					
	Levee Type	int.	int.	int.	Int.	Int.
	Total Length	13000	13000	13000	3000	3000
	Length Good	13000	13000	13000	3000	3000
	Length Fair	0	0	0	0	0
Length Poor	0	0	0	0	0	
Function				Protect wastewater Plant	Protect wastewater Plant	
Alignment:	Crest Width	12	12	12	10	10
	Crest Condition				Good	Good
	Crest Elevation	4.9	4.9	4.9	8.9	8.9
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	15 O, 25 I	15 O, 25 I	15 O, 25 I	25, southside gentle slope	25, southside gentle slope
	Slope Conditon	Good	Good	Good	Good	Good
	Toe Condition	Good	Good	Good	Good	Good
Evidence of Failures:	Cracking	No	No	No	No	No
	Seepage	No	No	No	No	No
	Overtopping	No	No	No	No	No
	Indications					
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Inboard	Inboard	Inboard	Inboard	Inboard
	Extent	0	0	0	3000	3000
	Condition	Good	Good	Good	Good	Good
	Wave Erosion					
	Undercutting	No	No	No		
Condition of Slope Protection:	Soil Type	Clayey - Sandy - Gravelly	Clayey - Sandy - Gravelly	Clayey - Sandy - Gravelly	Clayey - Sandy - Gravelly	Clayey - Sandy - Gravelly
	Type	Grass	Grass	Grass		
	Extent	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope		
	Degree	Thick	Thick	Thick		
Levee Use	Levee Use	Unpaved - Author Vehicle Graded	Unpaved - Author Vehicle Graded	Unpaved - Author Vehicle Graded	Unapvped - Author Vehicle Graded	Unapvped - Author Vehicle Graded
	Very Good					
	Adequate	0	0	0	0	0
Evaluation:	Poor	0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Eden Landing	Eden Landing	Eden Landing	Eden Landing	Eden Landing
	Pond	B5C	B5C	B6	B6	B6
	Orientation	SE	SW - NW	E	NW - N	SW
	Reach ID	12	12	12	12	12
	Segment	57A	57A	56A	56A	56A
	County	Alameda	Alameda	Alameda	Alameda	Alameda
	Survey By	G.O. & S.K.	G.O. & S.K.	M.W. & G.O.	M.W. & G.O.	M.W. & G.O.
	Date of Inspection	4/9/1984	4/9/1984	4/17/1984	4/17/1984	4/17/1984
	Ownership	County of Alameda	County of Alameda	County of Alameda	County of Alameda	County of Alameda
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	A	A	A	A	A
	Station From	See map	See map	See map	See map	See map
	Station To					
	Levee Type	Slough/Creek	Slough/Creek	Int.	Int.	Int.
	Total Length	13000	13000	3000	3000	3000
	Length Good	13000	13000	3000	3000	3000
	Length Fair	0	0	0	0	0
Length Poor	0	0	0	0	0	
Function	Buffer between Channel & low lying adjacent lands	Buffer between Channel & low lying adjacent lands	Protect wastewater Plant	Protect wastewater Plant	Protect wastewater Plant	
Alignment:	Crest Width	16	16	10	10	10
	Crest Condition	Good	Good	Good	Good	Good
	Crest Elevation	20.0	20.0	8.9	8.9	8.9
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	25-30 IO	25-30 IO	25, southside gentle slope	25, southside gentle slope	25, southside gentle slope
	Slope Conditon	Good	Good	Good	Good	Good
	Toe Condition	Good	Good	Good	Good	Good
Evidence of Failures:	Cracking	No	No	No	No	No
	Seepage	No	No	No	No	No
	Overtopping	No	No	No	No	No
	Indications	No	No			
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Inboard	Inboard	Inboard	Inboard	Inboard
	Extent	13000	13000	3000	3000	3000
	Condition	Good	Good	Good	Good	Good
	Wave Erosion					
	Undercutting					
Condition of Slope Protection:	Type	Clayey	Clayey	Clayey - Sandy - Gravelly	Clayey - Sandy - Gravelly	Clayey - Sandy - Gravelly
	Type	Grass - Riprap	Grass - Riprap			
	Extent	Outboard slope - Inboard slope	Outboard slope - Inboard slope			
	Degree	Light	Light			
	Levee Use	Unpaved - Author Vehicle Trail	Unpaved - Author Vehicle Trail	Unapvded - Author Vehicle Graded	Unapvded - Author Vehicle Graded	Unapvded - Author Vehicle Graded
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Eden Landing	Eden Landing	Eden Landing	Eden Landing	Eden Landing
	Pond	B6A	B6A	B6B	B6B	B6C
	Orientation	E - S	W - NW	N	W - SW	E - S - W
	Reach ID	10	10	10	10	12
	Segment	47	47	46C	46C	56B
	County	Alameda	Alameda	Alameda	Alameda	Alameda
	Survey By	M.W. & S.K.	M.W. & S.K.	M.W. & G.O.	M.W. & G.O.	M.W. & G.O.
	Date of Inspection	3/27/1984	3/27/1984	3/27/1984	3/27/1984	4/17/1984
	Ownership	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	County of Alameda
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment			C	C	
	Station From	S. Edge of Mt. Eden Creek	S. Edge of Mt. Eden Creek	See map	See map	
	Station To	End of Creek	End of Creek			
	Levee Type	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	int.
	Total Length	15000	15000	8000	8000	13000
	Length Good	0	0	0	0	13000
	Length Fair	15000	15000	0	0	0
Length Poor	0	0	8000	8000	0	
Function	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond		
Alignment:	Crest Width	0	0	12	12	12
	Crest Condition	Fair	Fair	Fair	Fair	
	Crest Elevation	6.6	6.6	5.8	5.8	4.9
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	Inside has heavy erosion verical drop to 40 slope	Inside has heavy erosion verical drop to 40 slope	16 - Inside has heavy erosion verical drop to 40 slope	16 - Inside has heavy erosion verical drop to 40 slope	15 O, 25 I
	Slope Conditon	Fair	Fair	Poor	Poor	Good
	Toe Condition	Fair	Fair	Poor	Poor	Good
Evidence of Failures:	Cracking			No	No	No
	Seepage			No	No	No
	Overtopping	Yes	Yes	Yes	Yes	No
	Indications					
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Outboard	Outboard	Inboard	Inboard	Inboard
	Extent	15000	15000	8000	8000	0
	Condition	Fair	Fair	Fair - Poor	Fair - Poor	Good
	Wave Erosion	Slight - Intense	Slight - Intense	Intense	Intense	
	Undercutting					No
	Soil Type	Clayey - Mixture Mud	Clayey - Mixture Mud	Clayey - Sandy	Clayey - Sandy	Clayey - Sandy - Gravelly
Condition of Slope Protection:	Type	Grass - Brush	Grass - Brush	Grass - Brush	Grass - Brush	Grass
	Extent	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope	Outboard slope - Inboard slope
	Degree	Thick	Thick	Thick	Thick	Thick
	Levee Use			Unpaved - Author Vehicle Graded	Unpaved - Author Vehicle Graded	Unpaved - Author Vehicle Graded
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	15000	15000	8000	8000	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Eden Landing	Eden Landing	Eden Landing	Eden Landing	Eden Landing
	Pond	B6C	B8	B8	B8	B8
	Orientation	NW	E - S	N	NE	S
	Reach ID	12	10	10	10	10
	Segment	56B	46C	46C	46C	47
	County	Alameda	Alameda	Alameda	Alameda	Alameda
	Survey By	M.W. & G.O.	M.W. & G.O.	M.W. & G.O.	M.W. & G.O.	M.W. & S.K.
	Date of Inspection	4/17/1984	3/27/1984	3/27/1984	3/27/1984	3/27/1984
	Ownership	County of Alameda	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment		C	C	C	
	Station From		See map	See map	See map	S. Edge of Mt. Eden Creek
	Station To					End of Creek
	Levee Type	int.	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int
	Total Length	13000	8000	8000	8000	15000
	Length Good	13000	0	0	0	0
	Length Fair	0	0	0	0	15000
Length Poor	0	8000	8000	8000	0	
Function		Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	
Alignment:	Crest Width	12	12	12	12	0
	Crest Condition		Fair	Fair	Fair	Fair
	Crest Elevation	4.9	5.8	5.8	5.8	6.6
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	15 O, 25 I	16 - Inside has heavy erosion verical drop to 40 slope	16 - Inside has heavy erosion verical drop to 40 slope	16 - Inside has heavy erosion verical drop to 40 slope	Inside has heavy erosion verical drop to 40 slope
	Slope Conditon	Good	Poor	Poor	Poor	Fair
	Toe Condition	Good	Poor	Poor	Poor	Fair
Evidence of Failures:	Cracking	No	No	No	No	
	Seepage	No	No	No	No	
	Overtopping	No	Yes	Yes	Yes	Yes
	Indications					
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Inboard	Inboard	Inboard	Inboard	Outboard
	Extent	0	8000	8000	8000	15000
	Condition	Good	Fair - Poor	Fair - Poor	Fair - Poor	Fair
	Wave Erosion		Intense	Intense	Intense	Slight - Intense
	Undercutting	No				
Condition of Slope Protection:	Soil Type	Clayey - Sandy - Gravelly	Clayey - Sandy	Clayey - Sandy	Clayey - Sandy	Clayey - Mixture Mud
	Type	Grass	Grass - Brush	Grass - Brush	Grass - Brush	Grass - Brush
	Extent	Outboard slope - Inboard slope	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope
	Degree	Thick	Thick	Thick	Thick	Thick
Evaluation:	Levee Use	Unpaved - Author Vehicle Graded	Unpaved - Author Vehicle Graded	Unpaved - Author Vehicle Graded	Unpaved - Author Vehicle Graded	
	Very Good					
	Adequate	0	0	0	0	0
Poor	0	8000	8000	8000	15000	

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Eden Landing	Eden Landing	Eden Landing	Eden Landing	Eden Landing
	Pond	B8	B8	B8A	B8A	B8A
	Orientation	W	W - NW	E - SE	S	W - NW
	Reach ID	10	10	10	10	10
	Segment	46C	46C	46C	47	46C
	County	Alameda	Alameda	Alameda	Alameda	Alameda
	Survey By	M.W. & G.O.	M.W. & G.O.	M.W. & G.O.	M.W. & S.K.	M.W. & G.O.
	Date of Inspection	3/27/1984	3/27/1984	3/27/1984	3/27/1984	3/27/1984
	Ownership	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	C	C	C		C
	Station From	See map	See map	See map	S. Edge of Mt. Eden Creek	See map
	Station To				End of Creek	
	Levee Type	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int
	Total Length	8000	8000	8000	15000	8000
	Length Good	0	0	0	0	0
	Length Fair	0	0	0	15000	0
	Length Poor	8000	8000	8000	0	8000
	Function	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond	Protect Salt Pond
	Alignment:	Crest Width	12	12	12	0
Crest Condition		Fair	Fair	Fair	Fair	Fair
Crest Elevation		5.8	5.8	5.8	6.6	5.8
Crest Datum		MSL	MSL	MSL	MSL	MSL
Side Slope Degrees		16 - Inside has heavy erosion vertical drop to 40 slope	16 - Inside has heavy erosion vertical drop to 40 slope	16 - Inside has heavy erosion vertical drop to 40 slope	Inside has heavy erosion vertical drop to 40 slope	16 - Inside has heavy erosion vertical drop to 40 slope
Slope Conditon		Poor	Poor	Poor	Fair	Poor
Toe Condition		Poor	Poor	Poor	Fair	Poor
Evidence of Failures:	Cracking	No	No	No		No
	Seepage	No	No	No		No
	Overtopping	Yes	Yes	Yes	Yes	Yes
	Indications					
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Inboard	Inboard	Inboard	Outboard	Inboard
	Extent	8000	8000	8000	15000	8000
	Condition	Fair - Poor	Fair - Poor	Fair - Poor	Fair	Fair - Poor
	Wave Erosion	Intense	Intense	Intense	Slight - Intense	Intense
	Undercutting					
	Soil Type	Clayey - Sandy	Clayey - Sandy	Clayey - Sandy	Clayey - Mixture Mud	Clayey - Sandy
Condition of Slope Protection:	Type	Grass - Brush	Grass - Brush	Grass - Brush	Grass - Brush	Grass - Brush
	Extent	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope
	Degree	Thick	Thick	Thick	Thick	Thick
	Levee Use	Unpaved - Author Vehicle Graded	Unpaved - Author Vehicle Graded	Unpaved - Author Vehicle Graded		Unpaved - Author Vehicle Graded
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	8000	8000	8000	15000	8000

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Eden Landing	Eden Landing	Eden Landing	Eden Landing	Eden Landing
	Pond	B9	B9	B9	B9	B9
	Orientation	E	N	N - E	SE	SW
	Reach ID	10	10	10	10	10
	Segment	46C	50	50	50	50
	County	Alameda	Alameda	Alameda	Alameda	Alameda
	Survey By	M.W. & G.O.	M.W. & S.K.	M.W. & S.K.	M.W. & S.K.	M.W. & S.K.
	Date of Inspection	3/27/1984	3/27/1984	3/27/1984	3/27/1984	3/27/1984
	Ownership	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment	C				
	Station From	See map	End of Slough	End of Slough	End of Slough	End of Slough
	Station To		S. Edge of Union City Slough	S. Edge of Union City Slough	S. Edge of Union City Slough	S. Edge of Union City Slough
	Levee Type	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int	Slough/Creek - Int
	Total Length	8000	6200	6200	6200	6200
	Length Good	0	0	0	0	0
	Length Fair	0	0	0	0	0
Length Poor	8000	6200	6200	6200	6200	
Function	Protect Salt Pond	No levee only shoreline without protection	No levee only shoreline without protection	No levee only shoreline without protection	No levee only shoreline without protection	
Alignment:	Crest Width	12	0	0	0	0
	Crest Condition	Fair				
	Crest Elevation	5.8	3.5	3.5	3.5	3.5
	Crest Datum	MSL	MSL	MSL	MSL	MSL
	Side Slope Degrees	16 - Inside has heavy erosion vertical drop to 40 slope				
	Slope Condition	Poor				
Evidence of Failures:	Toe Condition	Poor				
	Cracking	No				
	Seepage	No				
	Overtopping	Yes				
Slope Protection:	Indications					
	Type	Vegetation				
	Location	Inboard				
	Extent	8000	0	0	0	0
	Condition	Fair - Poor				
	Wave Erosion	Intense				
	Undercutting					
Condition of Slope Protection:	Soil Type	Clayey - Sandy				
	Type	Grass - Brush	Grass - Brush	Grass - Brush	Grass - Brush	Grass - Brush
	Extent	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope	Outboard Slope - Inboard Slope
	Degree	Thick	Light	Light	Light	Light
Evaluation:	Levee Use	Unpaved - Author Vehicle Graded	Unpaved - Author Vehicle Upgrading Needed	Unpaved - Author Vehicle Upgrading Needed	Unpaved - Author Vehicle Upgrading Needed	Unpaved - Author Vehicle Upgrading Needed
	Very Good					
	Adequate	0	0	0	0	0
Poor	8000	1100	1100	1100	1100	

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Ravenswood	Ravenswood	Ravenswood	Ravenswood	Ravenswood
	Pond	R_temp1	R_temp1	R_temp1	R_temp2	R1
	Orientation	E	N	SW		E
	Reach ID	25	25	25	25	25
	Segment	25.2	25.1	25.2	25.1	25.6
	County	San Mateo County	San Mateo County	San Mateo County	San Mateo County	San Mateo County
	Survey By		RPY		RPY	
	Date of Inspection	1/23/1985	1/23/1985	1/23/1985	1/23/1985	
	Ownership		San Mateo County		San Mateo County	Leslie Salt Co.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment					
	Station From					
	Station To					
	Levee Type	Int.	Slough/Creek	Int.	Slough/Creek	Bay Shore (some) - Slough Creek (most)
	Total Length	0	0	0	0	0
	Length Good	0	0	0	0	0
	Length Fair	8000	5750	8000	5750	0
Length Poor	0	0	0	0	19000	
Function	Adjacent to industry along freeway	No protection, surrounds landfill (for future dev.)	Adjacent to industry along freeway	No protection, surrounds landfill (for future dev.)	Salt ponds and sewage plant & sanitary landfill	
Alignment:	Crest Width	0	0	0	0	0
	Crest Condition	Good	Fair	Good	Fair	Poor
	Crest Elevation	0.0	0.0	0.0	0.0	0.0
	Crest Datum					
	Side Slope Degrees					
	Slope Conditon	Fair	Poor	Fair	Poor	Poor
	Toe Condition	Fair	Poor	Fair	Poor	Poor
Evidence of Failures:	Cracking					
	Seepage					
	Overtopping					
	Indications					
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Inboard - Outboard	Inboard - Outboard	Inboard - Outboard	Inboard - Outboard	Outboard
	Extent	0	0	0	0	0
	Condition	Fair	Poor	Fair	Poor	Poor
	Wave Erosion		Slight		Slight	Intense
	Undercutting					
	Soil Type					
Condition of Slope Protection:	Type	Grass - brush	Grass - brush	Grass - brush	Grass - brush	Grass - brush
	Extent	Outboard slope - Inboard slope	Outboard slope	Outboard slope - Inboard slope	Outboard slope	Outboard slope - Inboard slope
	Degree	Thick	Light	Thick	Light	Denser
	Levee Use	Paved	Unpaved - Author Vehicle Upgrade Need	Paved	Unpaved - Author Vehicle Upgrade Need	Unpaved - Author Vehicle Ungraded - Upgrade Need
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Ravenswood	Ravenswood	Ravenswood	Ravenswood	Ravenswood
	Pond	R1	R1	R2	R2	R2
	Orientation	S	S - SE	N - NW	SE	SW
	Reach ID	25	25	25	25	25
	Segment	25.6	25.6	25.6	25.6	25.6
	County	San Mateo County	San Mateo County	San Mateo County	San Mateo County	San Mateo County
	Survey By					
	Date of Inspection					
	Ownership	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment					
	Station From					
	Station To					
	Levee Type	Bay Shore (some) - Slough Creek (most)	Bay Shore (some) - Slough Creek (most)	Bay Shore (some) - Slough Creek (most)	Bay Shore (some) - Slough Creek (most)	Bay Shore (some) - Slough Creek (most)
	Total Length	0	0	0	0	0
	Length Good	0	0	0	0	0
	Length Fair	0	0	0	0	0
Length Poor	19000	19000	19000	19000	19000	
Function	Salt ponds and sewage plant & sanitary landfill	Salt ponds and sewage plant & sanitary landfill	Salt ponds and sewage plant & sanitary landfill	Salt ponds and sewage plant & sanitary landfill	Salt ponds and sewage plant & sanitary landfill	
Alignment:	Crest Width	0	0	0	0	0
	Crest Condition	Poor	Poor	Poor	Poor	Poor
	Crest Elevation	0.0	0.0	0.0	0.0	0.0
	Crest Datum					
	Side Slope Degrees					
	Slope Conditon	Poor	Poor	Poor	Poor	Poor
	Toe Condition	Poor	Poor	Poor	Poor	Poor
Evidence of Failures:	Cracking					
	Seepage					
	Overtopping					
	Indications					
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Outboard	Outboard	Outboard	Outboard	Outboard
	Extent	0	0	0	0	0
	Condition	Poor	Poor	Poor	Poor	Poor
	Wave Erosion	Intense	Intense	Intense	Intense	Intense
	Undercutting					
	Soil Type					
Condition of Slope Protection:	Type	Grass - brush	Grass - brush	Grass - brush	Grass - brush	Grass - brush
	Extent	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope
	Degree	Denser	Denser	Denser	Denser	Denser
	Levee Use	Unpaved - Author Vehicle Ungraded - Upgrade Need	Unpaved - Author Vehicle Ungraded - Upgrade Need	Unpaved - Author Vehicle Ungraded - Upgrade Need	Unpaved - Author Vehicle Ungraded - Upgrade Need	Unpaved - Author Vehicle Ungraded - Upgrade Need
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Ravenswood	Ravenswood	Ravenswood	Ravenswood	Ravenswood
	Pond	R2	R3	R3	R3	R3
	Orientation		E - S	NE - N	S	S - SE
	Reach ID	25	25	25	25	25
	Segment	25.6	25.6	25.6	25.2	25.4
	County	San Mateo County	San Mateo County	San Mateo County	San Mateo County	San Mateo County
	Survey By					
	Date of Inspection				1/23/1985	1/23/1985
	Ownership	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.		Leslie Salt Co.
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment					
	Station From					
	Station To					
	Levee Type	Bay Shore (some) - Slough Creek (most)	Bay Shore (some) - Slough Creek (most)	Bay Shore (some) - Slough Creek (most)	Int.	Int.
	Total Length	0	0	0	0	0
	Length Good	0	0	0	0	0
	Length Fair	0	0	0	8000	0
Length Poor	19000	19000	19000	0	3500	
Function	Salt ponds and sewage plant & sanitary landfill	Salt ponds and sewage plant & sanitary landfill	Salt ponds and sewage plant & sanitary landfill	Adjacent to industry along freeway	Sect #3 with soft inboard salt pond levee	
Alignment:	Crest Width	0	0	0	0	0
	Crest Condition	Poor	Poor	Poor	Good	Poor
	Crest Elevation	0.0	0.0	0.0	0.0	0.0
	Crest Datum					
	Side Slope Degrees					
	Slope Conditon	Poor	Poor	Poor	Fair	Poor
Evidence of Failures:	Toe Condition	Poor	Poor	Poor	Fair	Poor
	Cracking					
	Seepage					
	Overtopping Indications					
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Outboard	Outboard	Outboard	Inboard - Outboard	Inboard - Outboard
	Extent	0	0	0	0	0
	Condition	Poor	Poor	Poor	Fair	Poor
	Wave Erosion	Intense	Intense	Intense		Intense
	Undercutting					
Condition of Slope Protection:	Soil Type					
	Type	Grass - brush	Grass - brush	Grass - brush	Grass - brush	Grass - brush
	Extent	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope
	Degree	Denser	Denser	Denser	Thick	Thick
Evaluation:	Levee Use	Unpaved - Author Vehicle Ungraded - Upgrade Need	Unpaved - Author Vehicle Ungraded - Upgrade Need	Unpaved - Author Vehicle Ungraded - Upgrade Need	Paved	Unpaved - Author Vehicle Ungraded - Upgrade Need
	Very Good					
	Adequate	0	0	0	0	0
Poor	0	0	0	0	0	

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Ravenswood	Ravenswood	Ravenswood	Ravenswood	Ravenswood
	Pond	R3	R4	R4	R4	R4
	Orientation	W - SW	E	N	S - SE	W
	Reach ID	25	25	25	25	25
	Segment	25.4	25.6	25.6	25.4	25.1
	County	San Mateo County	San Mateo County	San Mateo County	San Mateo County	San Mateo County
	Survey By					RPY
	Date of Inspection	1/23/1985			1/23/1985	1/23/1985
	Ownership	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	Leslie Salt Co.	San Mateo County
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment					
	Station From					
	Station To					
	Levee Type	Int.	Bay Shore (some) - Slough Creek (most)	Bay Shore (some) - Slough Creek (most)	Int.	Slough/Creek
	Total Length	0	0	0	0	0
	Length Good	0	0	0	0	0
	Length Fair	0	0	0	0	5750
Length Poor	3500	19000	19000	3500	0	
Function	Sect #3 with soft inboard salt pond levee	Salt ponds and sewage plant & sanitary landfill	Salt ponds and sewage plant & sanitary landfill	Sect #3 with soft inboard salt pond levee	No protection, surrounds landfill (for future dev.)	
Alignment:	Crest Width	0	0	0	0	0
	Crest Condition	Poor	Poor	Poor	Poor	Fair
	Crest Elevation	0.0	0.0	0.0	0.0	0.0
	Crest Datum					
	Side Slope Degrees					
	Slope Conditon	Poor	Poor	Poor	Poor	Poor
Evidence of Failures:	Toe Condition	Poor	Poor	Poor	Poor	Poor
	Cracking					
	Seepage					
	Overtopping Indications					
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Inboard - Outboard	Outboard	Outboard	Inboard - Outboard	Inboard - Outboard
	Extent	0	0	0	0	0
	Condition	Poor	Poor	Poor	Poor	Poor
	Wave Erosion	Intense	Intense	Intense	Intense	Slight
	Undercutting					
Condition of Slope Protection:	Soil Type					
	Type	Grass - brush	Grass - brush	Grass - brush	Grass - brush	Grass - brush
	Extent	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope	Outboard slope
	Degree	Thick	Denser	Denser	Thick	Light
Evaluation:	Levee Use	Unpaved - Author Vehicle Ungraded - Upgrade Need	Unpaved - Author Vehicle Ungraded - Upgrade Need	Unpaved - Author Vehicle Ungraded - Upgrade Need	Unpaved - Author Vehicle Ungraded - Upgrade Need	Unpaved - Author Vehicle Upgrade Need
	Very Good					
	Adequate	0	0	0	0	0
Poor	0	0	0	0	0	

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Ravenswood	Ravenswood	Ravenswood	Ravenswood	Ravenswood
	Pond	R5	R5	R5	S5	S5
	Orientation	N	SW	W	NE	SW
	Reach ID	25	25	25	25	25
	Segment	25.1	25.1	25.1	25.4	25.2
	County	San Mateo County	San Mateo County	San Mateo County	San Mateo County	San Mateo County
	Survey By	RPY	RPY	RPY		
	Date of Inspection	1/23/1985	1/23/1985	1/23/1985	1/23/1985	1/23/1985
	Ownership	San Mateo County	San Mateo County	San Mateo County	Leslie Salt Co.	
	Method	Ground	Ground	Ground	Ground	Ground
	Levee Segment					
	Station From					
	Station To					
	Levee Type	Slough/Creek	Slough/Creek	Slough/Creek	Int.	Int.
	Total Length	0	0	0	0	0
	Length Good	0	0	0	0	0
	Length Fair	5750	5750	5750	0	8000
Length Poor	0	0	0	3500	0	
Function	No protection, surrounds landfill (for future dev.)	No protection, surrounds landfill (for future dev.)	No protection, surrounds landfill (for future dev.)	Sect #3 with soft inboard salt pond levee	Adjacent to industry along freeway	
Alignment:	Crest Width	0	0	0	0	0
	Crest Condition	Fair	Fair	Fair	Poor	Good
	Crest Elevation	0.0	0.0	0.0	0.0	0.0
	Crest Datum					
	Side Slope Degrees					
	Slope Condition	Poor	Poor	Poor	Poor	Fair
Evidence of Failures:	Toe Condition	Poor	Poor	Poor	Poor	Fair
	Cracking					
	Seepage					
	Overtopping					
Slope Protection:	Indications					
	Type	Vegetation	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Inboard - Outboard	Inboard - Outboard	Inboard - Outboard	Inboard - Outboard	Inboard - Outboard
	Extent	0	0	0	0	0
	Condition	Poor	Poor	Poor	Poor	Fair
	Wave Erosion	Slight	Slight	Slight	Intense	
	Undercutting					
Condition of Slope Protection:	Soil Type					
	Type	Grass - brush	Grass - brush	Grass - brush	Grass - brush	Grass - brush
	Extent	Outboard slope	Outboard slope	Outboard slope	Outboard slope - Inboard slope	Outboard slope - Inboard slope
	Degree	Light	Light	Light	Thick	Thick
	Levee Use	Unpaved - Author Vehicle Upgrade Need	Unpaved - Author Vehicle Upgrade Need	Unpaved - Author Vehicle Upgrade Need	Unpaved - Author Vehicle Ungraded - Upgrade Need	Paved
Evaluation:	Very Good					
	Adequate	0	0	0	0	0
	Poor	0	0	0	0	0

APPENDIX B
USACE 1984 LEVEE SURVEY SUMMARY
 South Bay Salt Pond Restoration Project
 San Francisco Bay Area, CA

General:	Complex	Ravenswood	Ravenswood	Ravenswood	Ravenswood
	Pond	S5	SF2	SF2	SF2
	Orientation	W	NE	SE	SW
	Reach ID	25	24	24	24
	Segment	25.1	24.6	24.6	24.6
	County	San Mateo County	San Mateo County	San Mateo County	San Mateo County
	Survey By	RPY	RPY	RPY	RPY
	Date of Inspection	1/23/1985	2/1/1985	2/1/1985	2/1/1985
	Ownership	San Mateo County	SPT Co.	SPT Co.	SPT Co.
	Method	Ground	Ground	Ground	Ground
	Levee Segment				
	Station From				
	Station To				
	Levee Type	Slough/Creek	Int.	Int.	Int.
	Total Length	0	0	0	0
	Length Good	0	0	0	0
	Length Fair	5750	5000	5000	5000
Length Poor	0	0	0	0	
Function	No protection, surrounds landfill (for future dev.)	RR embankment btwn salt ponds and developed areas	RR embankment btwn salt ponds and developed areas	RR embankment btwn salt ponds and developed areas	
Alignment:	Crest Width	0	0	0	0
	Crest Condition	Fair	Good	Good	Good
	Crest Elevation	0.0	0.0	0.0	0.0
	Crest Datum				
	Side Slope Degrees				
	Slope Conditon	Poor	Fair	Fair	Fair
	Toe Condition	Poor	Fair	Fair	Fair
Evidence of Failures:	Cracking				
	Seepage				
	Overtopping				
	Indications				
Slope Protection:	Type	Vegetation	Vegetation	Vegetation	Vegetation
	Location	Inboard - Outboard	Inboard - Outboard	Inboard - Outboard	Inboard - Outboard
	Extent	0	0	0	0
	Condition	Poor	Fair	Fair	Fair
	Wave Erosion	Slight			
	Undercutting				
Condition of Slope Protection:	Type	Grass - brush	Grass - brush	Grass - brush	Grass - brush
	Extent	Outboard slope			
	Degree	Light	Light	Light	Light
	Levee Use	Unpaved - Author Vehicle Upgrade Need			
Evaluation:	Very Good				
	Adequate	0	0	0	0
	Poor	0	0	0	0

APPENDIX C

MOFFAT & NICHOL ENGINEERS 2004 LEVEE SURVEY SUMMARY

APPENDIX C
MOFFAT AND NICHOL LEVEE SURVEY SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Date	Latitude	Longitude	Complex	Pond	Orientatio	Station from	Station to	Crest Width (ft)	Crest Condition	Pond Side Crest Height (ft)	Pond Side Slope Erosion	Pond Side Toe Condition	Land Side Crest Height (ft)	Land Side Slope Erosion	Land Side Toe Condition	Levee Material	Seepage
12/16/2003	37.434790	-122.085840	Alviso	A1	S												
12/16/2003	37.435060	-122.096830	Alviso	A1	S	6+00	10+00	16	paved	8	none	pond	16	none		clay	none
12/16/2003	37.435510	-122.092160	Alviso	A1	S	15+00	44+00	25	paved; Bay Trail	upper: 13; lower: 3	none	opnd	none, landfill	none, landfill	none, landfill	clay	none
12/16/2003	37.435840	-122.098690	Alviso	A1	W			16	paved	6	none	pond	13	none	pond	clay	none
11/20/2003	37.427529	-121.975382	Alviso	A12	E	North of Catherine St.	between Gold & State/Liberty		storm drain crosses here								
11/20/2003	37.429240	-121.980614	Alviso	A12	E	0+00											
11/20/2003	37.429621	-121.978502	Alviso	A12	E	8+00											
11/20/2003	37.432484	-121.970246	Alviso	A12	E		State & Pacific (N End)										
11/20/2003	37.432839	-121.966698	Alviso	A16	S	State at Spreckels	83+00		asphalt road		minimal						
11/20/2003	37.478225	-121.973122	Alviso	A22	W-S	0+00	13+00	15	3/8"-gravel	3	heavy (wind wave)	5 degrees to ditch	3	minimal	tidal slough at toe	Sandy Silt	none
11/20/2003	37.480591	-121.970668	Alviso	A22	N-W	13+00	25+00	20	3/8"-gravel	3	minimal	5 degrees, barren	2	minimal	ditch at toe	Sandy Silt	none
11/20/2003	37.481539	-121.969094	Alviso	A22	W-C	25+00	31+00	16	3/8"-gravel	3	moderate to heavy	Silty Sand, 5 degrees to ditch	3	minimal	ditch at toe	Sandy Silt	none
11/20/2003	37.482444	-121.965620	Alviso	A22	N-C												
11/20/2003	37.482461	-121.966869	Alviso	A22	N-C	32+00	45+00	15	3/8"-gravel	3	heavy	5 degrees to ditch	3	moderate w/6' scary	ditch at toe	no signs	
11/20/2003	37.484911	-121.964388	Alviso	A22	W-N	54+00	63+00			3							

APPENDIX C
MOFFAT AND NICHOL LEVEE SURVEY SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Date	Latitude	Longitude	Complex	Pond	Orientatio	Station from	Station to	Crest Width (ft)	Crest Condition	Pond Side Crest Height (ft)	Pond Side Slope Erosion	Pond Side Toe Condition	Land Side Crest Height (ft)	Land Side Slope Erosion	Land Side Toe Condition	Levee Material	Seepage
11/20/2003	37.487528	-121.964382	Alviso	A22	W-N	64+00	78+00	12	grasses	4	minimal	12' wide bench	5	minimal	ditch at toe	probable Bay Mud	none
11/20/2003	37.487784	-121.959286	Alviso	A22	N												
12/16/2003	37.434030	-122.063770	Alviso	A2E	S-W	0+00	17+00	35	clay, slick, low, cast-up	3	none	pickleweed, 10' wide, 20:1 slope (cast up from pond slope)	5	none	ponded	clay, slick, low, cast-up	none
12/16/2003	37.434310	-122.053260	Alviso	A2E	S-E			15	slick, clay	3	moderate	pond	4	none	mudflat	clay	none
12/16/2003	37.434600	-122.058380	Alviso	A2E	S-C	17+00	new station line	12	slick, clay	3	active	2' vertical to water	4	none visible	dessicated mud	clay	none
12/16/2003	37.435570	-122.076150	Alviso	A2W	S	0+00	37+00	30	paved upper, gravel lower	14	lower slope eroding	pond	landfill	landfill	landfill	clay/some debris	none
12/16/2003	37.435680	-122.071250	Alviso	A2W	S	38+00	48+00	30 at lower bench	gravel lower	bench: 2; berm: 5	active	pond	4	none	none/marsh	clay	none
12/16/2003	37.427300	-122.040050	Alviso	A3W	S	94+00	110+00	25	trail, compacted clay	4' scarp	active	pond	6	none/some	drainage channel	clay	
12/16/2003	37.427400	-122.044340	Alviso	A3W	S												
12/16/2003	37.427560	-122.042660	Alviso	A3W	S	70+00	94+00	30	trail, compacted clay	3	near vertical	pond at toe	5	none	2' vertical to water	clay	
12/16/2003	37.431670	-122.030530	Alviso	A3W	E			10	gravel	6.5	none - significant burrowing	20' to waterline, mudflat	4	riprap (concrete debris)	oxidation pond	unknown	

APPENDIX C
MOFFAT AND NICHOL LEVEE SURVEY SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Date	Latitude	Longitude	Complex	Pond	Orientatio	Station from	Station to	Crest Width (ft)	Crest Condition	Pond Side Crest Height (ft)	Pond Side Slope Erosion	Pond Side Toe Condition	Land Side Crest Height (ft)	Land Side Slope Erosion	Land Side Toe Condition	Levee Material	Seepage
11/20/2003	37.417048	-121.987065	Alviso	A8Ss	S	Pond #85	pe St. at San Tomas										
12/16/2003	37.488130	-122.142690	Ravenswood	R3	E-N-S			20'+berm 8' wide x 1' high	trail	4	active	12' wide mudflat to channel	4	none		clay	none
12/16/2003	37.482660	-122.160760	Ravenswood	R3	S-W			>50' (~55' to trail)		3	moderate	mudflat to channel, 20:1 slope	n/a	n/a	n/a	clay	none
12/16/2003	37.484150	-122.165980	Ravenswood	S5	NE			45	grass	2	active	mudflat, 20:1, 25' wide	2	moderate	mudflat (dried pond)	clay	none
12/16/2003	37.485400	-122.171950	Ravenswood	S5	S			berm, 1' high + 16' wide levee		3	severe, near vertical	salt pan/flat	crest, 4' water to bench	mild	F.C. channel	clay	none

APPENDIX D

**CARGILL 1995 to 2005
MAINTENANCE SUMMARY**

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Eden's Landing	A1	N/A	Grading	N/A	1995-1996		
Eden's Landing	A4-A18	N/A	Grading	N/A	1995-1996		
Eden's Landing	A7	N/A	Dredge	Sediment	1995-1996		
Eden's Landing	A5	Majority of the levee system	Grading	Build up	1995-1996	25,400	
Eden's Landing	A6	Inside	Maintain rip rap	Erosion	1995-1996	2,700	3500
Eden's Landing	A6	Outside	Grading	Build up	1995-1996	2,700	
Eden's Landing	A7	N/A	Discing	N/A	1995-1996		
Eden's Landing	A7	Majority of the levee system	Grading	Build up	1995-1996	16,500	
Eden's Landing	A8	Majority of the levee system	Grading	Build up	1995-1996	11,500	
Eden's Landing	A8	Inside	Grading	Build up	1995-1996		100
Eden's Landing	A8	Majority of the levee system	Construct new lock	N/A	1995-1996		2000
Eden's Landing	A9 - A12	Outside	Maintain rip rap	Erosion	1995-1996	3	21
Eden's Landing	A10	Inside	Grading	Build up	1995-1996	500	
Eden's Landing	A11	Inside	Grading	Build up	1995-1996		150
Eden's Landing	A12	Inside	Grading	Build up	1995-1996		150
Eden's Landing	A12	Spots along levee	Grading	Erosion	1995-1996	500	
Eden's Landing	A13	Spots along levee	Grading	Erosion	1995-1996	500	
Eden's Landing	A15	Spots along levee	Grading	Erosion	1995-1996	200	
Eden's Landing	A16	N/A	Maintain rip rap	Erosion	1995-1996	150	180
Eden's Landing	A22	N/A	Grading	N/A	1995-1996		
Eden's Landing	A23	N/A	Grading	N/A	1995-1996		
Eden's Landing	A2E	N/A	Discing	N/A	1995-1996		
Eden's Landing	A2E	N/A	Grading	N/A	1995-1996		
Eden's Landing	A2W	N/A	Grading	N/A	1995-1996		
Eden's Landing	A3N	N/A	Discing	N/A	1995-1996		
Eden's Landing	A3N	Outside	Maintain rip rap	Erosion	1995-1996	200	250

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Eden's Landing	A3N	N/A	Grading	N/A	1995-1996		
Eden's Landing	A3W	Outside	Grading	N/A	1995-1996		
Eden's Landing	A3W	N/A	Grading	Build up	1995-1996	2500	
Eden's Landing	A3W	N/A	Grading	N/A	1995-1996		
Eden's Landing	B1	N/A	Discing	N/A	1995-1996		
Eden's Landing	B1	N/A	Maintain rip rap	Erosion	1995-1996	150	180
Eden's Landing	B1	N/A	Grading	N/A	1995-1996		
Eden's Landing	B2	N/A	Discing	N/A	1995-1996		
Eden's Landing	B2	N/A	Grading	N/A	1995-1996		
Eden's Landing	1-14	N/A	Grading	N/A	1995-1996		
Eden's Landing	2	Outside	Dredge	N/A	1995-1996		
Eden's Landing	1	N/A	Grading	N/A	1995-1996	1800	
Eden's Landing	1	N/A	Levee Construction	Marsh Mitigation	1995-1996	2400	
Eden's Landing	1	Inside	Maintain rip rap	Erosion	1995-1996	25	30
Eden's Landing	2	?Inside?	Grading	Marsh Mitigation	1995-1996		
Eden's Landing	2	Outside	Maintain rip rap	Erosion	1995-1996	1150	1380
Eden's Landing	7	Inside	Grading	Build up	1995-1996		55
Eden's Landing	10	Outside	Maintain rip rap	Erosion	1995-1996	500	600
Eden's Landing	10	Inside	Grading	Build up	1995-1996		50
Eden's Landing	6A	N/A	Grading	N/A	1995-1996		
Eden's Landing	6A	Inside	Maintain rip rap		1995-1996	300	360
Eden's Landing	8A	N/A	Grading	N/A	1995-1996		
Eden's Landing	6B	N/A	Grading	N/A	1995-1996		
Eden's Landing	1C - 5C	N/A	Grading	N/A	1995-1996		

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Eden's Landing	1C	N/A	Dredge	N/A	1995-1996		400
Eden's Landing	3C	Inside	Maintain rip rap	Erosion	1995-1996	40	50
Eden's Landing	5C	Inside	Maintain rip rap	Erosion	1995-1996	1500	1700
Eden's Landing	6C	N/A	Grading	N/A	1995-1996		
Eden's Landing	1-14, 1C-5C, 6A, 6B, 6C, & 8A	N/A	Grading	N/A	1996-1997		
Eden's Landing	1	Inside	Maintain rip rap	Erosion	1996-1997	270	325
Eden's Landing	7	N/A	Discing	N/A	1996-1997		
Eden's Landing	10	?Outside?	Grading	Build up	1996-1997	700	
Eden's Landing	10	Outside	Maintain rip rap	Erosion	1996-1997	192	230
Eden's Landing	1-2, 4-8, 10-12, 14, 6A, 6B, 1C-6C	N/A	Grading	N/A	1997-1998		
Eden's Landing	1	Mitigation levee	Grading	Build up	1997-1998		
Eden's Landing	1	N/A	Discing	N/A	1997-1998		
Eden's Landing	1	Inside	Maintain rip rap	Erosion	1997-1998	1170	585
Eden's Landing	2	N/A	Maintain rip rap	Erosion	1997-1998	225	45
Eden's Landing	2	N/A	Discing	N/A	1997-1998		
Eden's Landing	3C	Inside	Maintain rip rap	Erosion	1997-1998	60	70
Eden's Landing	5C	N/A	Grading	Build up	1997-1998	3200	
Eden's Landing	5C	Inside	Maintain rip rap	Erosion	1997-1998	340	400
Eden's Landing	6A	Outside	Maintain rip rap	Erosion	1997-1998	30	60
Eden's Landing	10	N/A	Discing	N/A	1997-1998		
Eden's Landing	10	N/A	Grading	Build up	1997-1998	600	900
Eden's Landing	1	Inside	Grading	Erosion	1997-1998*	250	300
Eden's Landing	1	cross levee	Maintain rip rap	Erosion	1997-1998*	200	1000
Eden's Landing	1C	N/A	Grading	Settlement	1997-1998*	1500	

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Eden's Landing	1C	Inside	Grading	Settlement	1997-1998*	1500	
Eden's Landing	1C	Inside	Maintain rip rap	Erosion	1997-1998*	1500	1000
Eden's Landing	2	Inside	Maintain rip rap	Erosion	1997-1998*	1500	850
Eden's Landing	5C	N/A	Maintain rip rap	Erosion	1997-1998*	1500	1000
Eden's Landing	6A	N/A	Grading	Build up	1997-1998*		300
Eden's Landing	6A	Inside	Maintain rip rap	Erosion	1997-1998*	1000	550
Eden's Landing	6A	cross levee	Grading	Build up	1997-1998*	4200	
Eden's Landing	6B	N/A	Grading	Build up	1997-1998*	1700	
Eden's Landing	1-14, 1C-5C, 6A, 6B, 6C, & 8A	N/A	Grading	N/A	1998-1999		
Eden's Landing	1	Mitigation levee	Grading	Build up	1998-1999		
Eden's Landing	1	Inside	Maintain rip rap	Erosion	1998-1999	1280	225
Eden's Landing	2	N/A	Maintain rip rap	Erosion	1998-1999	215	250
Eden's Landing	2	Inside	Maintain rip rap	Erosion	1998-1999	420	70
Eden's Landing	1C, 2C	?cross levee?	Grading	Settlement	1998-1999		10
Eden's Landing	3C	Inside	Maintain rip rap	Erosion	1998-1999	60	70
Eden's Landing	5C	N/A	Grading	Build up	1998-1999	3200	
Eden's Landing	5C	Inside	Maintain rip rap	Erosion	1998-1999	485	60
Eden's Landing	6A	N/A	Grading	Build up			
Eden's Landing	6A	Inside	Maintain rip rap	Erosion	1998-1999	2150	955
Eden's Landing	10	N/A	Maintain rip rap	Erosion	1998-1999	235	155
Eden's Landing	10	N/A	Grading	?Erosion?	1998-1999*		85
Eden's Landing	8	N/A	Grading	?Erosion?	1998-1999*		10
Eden's Landing	8	N/A	Maintain rip rap	Erosion	1998-1999*	30	10
Eden's Landing	1C	Inside	Maintain rip rap	Erosion	1998-1999*	975	165

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Eden's Landing	1-14, 1C-5C, 6A, 6B, 6C, & 8A	N/A	Grading	N/A	1999-2000		
Eden's Landing	1	Mitigation levee	Grading	Build up	1999-2000	2200	
Eden's Landing	1	N/A	Grading	Build up	1999-2000	1200	
Eden's Landing	1	Inside	Grading	Erosion	1999-2000	250	300
Eden's Landing	1	cross levee	Grading	Build up	1999-2000	5400	
Eden's Landing	1	cross levee	Grading	Build up	1999-2000	1200	
Eden's Landing	1	cross levee	Maintain rip rap	Erosion	1999-2000	800	450
Eden's Landing	1C	Inside	Grading	Settlement	1999-2000	1500	
Eden's Landing	1C	N/A	Grading	Settlement	1999-2000	1500	
Eden's Landing	1C	N/A	Grading	N/A	1999-2000	80	30
Eden's Landing	1C, 2C	N/A	Grading	Settlement	1999-2000		10
Eden's Landing	2	N/A	Maintain rip rap	Erosion	1999-2000	500	150
Eden's Landing	2	cross levee	Grading	Build up	1999-2000	10200	
Eden's Landing	2	N/A	Grading	Build up	1999-2000		
Eden's Landing	2	Inside	Maintain rip rap	Erosion	1999-2000	1000	500
Eden's Landing	2	N/A	Grading	Build up	1999-2000	1200	
Eden's Landing	2	N/A	Piles and sheet piles placed	Erosion	1999-2000	500	
Eden's Landing	2	?Outside?	Grading	Build up	1999-2000	17000	
Eden's Landing	3C	Inside	Maintain rip rap	Erosion	1999-2000	60	70
Eden's Landing	4	cross levee	Grading	Build up	1999-2000	2750	
Eden's Landing	5	cross levee	Grading	Build up	1999-2000	3250	
Eden's Landing	5C	N/A	Grading	Build up	1999-2000	3200	
Eden's Landing	6	cross levee	Grading	Build up	1999-2000	3225	
Eden's Landing	6A	cross levee	Grading	Build up	1999-2000	4200	

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Eden's Landing	6B	N/A	Grading	Build up	1999-2000	1700	
Eden's Landing	7	cross levee	Grading	Build up	1999-2000	2400	
Eden's Landing	8	Inside	Maintain rip rap	Erosion	1999-2000	24	25
Eden's Landing	9	Inside	Grading	Build up	1999-2000	800	
Eden's Landing	9	Inside	Maintain rip rap	Erosion	1999-2000	70	115
Eden's Landing	10	N/A	Maintain rip rap	Erosion	1999-2000	20	30
Eden's Landing	12	Inside	Maintain rip rap	Erosion	1999-2000	120	205
Eden's Landing	12	Inside	Grading	Build up	1999-2000	1500	
Eden's Landing	1-14, 1C-5C, 6A, 6B, 6C, & 8A	N/A	Grading	N/A	2000-2001		
Eden's Landing	1	Inside	Grading	Erosion	2000-2001	250	300
Eden's Landing	1C	Inside	Grading	Settlement	2000-2001	1500	
Eden's Landing	1C	N/A	Grading	Settlement	2000-2001	1500	
Eden's Landing	1C	N/A	Grading	N/A	2000-2001	80	30
Eden's Landing	1C, 2C	N/A	Grading	Settlement	2000-2001		10
Eden's Landing	3C	Inside	Maintain rip rap	Erosion	2000-2001	60	70
Eden's Landing	5	cross levee	Maintain rip rap	Erosion	2000-2001	40	50
Eden's Landing	5C	N/A	Grading	Build up	2000-2001	3200	
Eden's Landing	6A	cross levee	Grading	Build up	2000-2001	4200	
Eden's Landing	6B	N/A	Grading	Build up	2000-2001	1700	
Eden's Landing	9	xinside cross levee	Maintain rip rap	Erosion	2000-2001	250	300
Eden's Landing	9	Inside	Grading	Build up	2000-2001	800	
Eden's Landing	10	N/A	Maintain rip rap	Erosion	2000-2001	250	300
Eden's Landing	12	Inside	Grading	Build up	2000-2001	1500	

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Eden's Landing	1-14, 1C-5C, 6A, 6B, 6C, & 8A	N/A	Grading	N/A	2001-2002		
Eden's Landing	1	Inside	Grading	Erosion	2001-2002	250	300
Eden's Landing	1C	Inside	Grading	Settlement	2001-2002	1500	
Eden's Landing	1C	N/A	Grading	Settlement	2001-2002	1500	
Eden's Landing	1C	N/A	Grading		2001-2002	80	30
Eden's Landing	1C, 2C	N/A	Grading	Settlement	2001-2002		10
Eden's Landing	3C	Inside	Maintain rip rap	Erosion	2001-2002	60	70
Eden's Landing	5	xinside cross levee	Maintain rip rap	Erosion	2001-2002	40	50
Eden's Landing	5C	N/A	Grading	Build up	2001-2002	3200	
Eden's Landing	6A	cross levee	Grading	Build up	2001-2002	4200	
Eden's Landing	6B	N/A	Grading	Build up	2001-2002	1700	
Eden's Landing	8A	cross levee	Levee Construction	N/A	2001-2002	3500	62000
Eden's Landing	9	xinside cross levee	Maintain rip rap	Erosion	2001-2002	250	300
Eden's Landing	9	Inside	Grading	Build up	2001-2002	800	
Eden's Landing	10	N/A	Dredge	N/A	2001-2002		
Eden's Landing	10	N/A	Levee Construction	N/A	2001-2002	5474	85200
Eden's Landing	10	N/A	Maintain rip rap	Erosion	2001-2002	250	300
Eden's Landing	12	Inside	Grading	Build up	2001-202	1500	
Eden's Landing	1-14, 1C-5C, 6A, 6B, 6C, & 8A	N/A	Grading	N/A	2002-2003		
Eden's Landing	1	Inside	Grading	Erosion	2002-2003	250	300
Eden's Landing	1C	Inside	Grading	Settlement	2002-2003	1500	
Eden's Landing	1C	N/A	Grading	Settlement	2002-2003	1500	
Eden's Landing	1C		Dredge	Sediment	2002-2003	2400	100
Eden's Landing	1C, 2C	N/A	Grading	Settlement	2002-2003		10

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Eden's Landing	3C	Inside	Maintain rip rap	Erosion	2002-2003	60	70
Eden's Landing	4	cross levee	Grading	Build up	2002-2003	2300	
Eden's Landing	5	?Inside?	Grading	Build up	2002-2003	2000	
Eden's Landing	5	cross levee	Maintain rip rap	Erosion	2002-2003	40	50
Eden's Landing	5C	N/A	Grading	Build up	2002-2003	3200	
Eden's Landing	6	?Inside?	Grading	Build up	2002-2003	2500	
Eden's Landing	6A	cross levee	Grading	Build up	2002-2003	4200	
Eden's Landing	6B	N/A	Grading	Build up	2002-2003	1700	
Eden's Landing	7	cross levee	Grading	Build up	2002-2003	3400	
Eden's Landing	8A	N/A	Levee Construction	N/A	2002-2003	3500	96000
Eden's Landing	8A	New Levee	Levee Construction	N/A	2002-2003		
Eden's Landing	9	cross levee	Maintain rip rap	Erosion	2002-2003		
Eden's Landing	9	Inside	Grading	Build up	2002-2003		
Eden's Landing	10	N/A	Dredge	Sediment	2002-2003		
Eden's Landing	10	New Levee	Levee Construction	N/A	2002-2003	5474	85200
Eden's Landing	10	N/A	Maintain rip rap	Erosion	2002-2003	250	300
Eden's Landing	12	Inside	Grading	Build up	2002-2003	1500	
Eden's Landing	1-14, 1C-5C, 6A, 6B, 6C, & 8A	N/A	Grading	N/A	2003-2004		
Eden's Landing	1	Inside	Grading	Erosion	2003-2004	250	300
Eden's Landing	1C	Inside	Grading	Settlement	2003-2004	1500	
Eden's Landing	1C	N/A	Grading	Settlement	2003-2004	1500	
Eden's Landing	1C	N/A	Dredge	Sediment	2003-2004	2400	100
Eden's Landing	2	N/A	Maintain rip rap	Erosion	2003-2004	500	1000
Eden's Landing	2	Inside	Maintain rip rap	Erosion	2003-2004	500	750
Eden's Landing	1C, 2C	N/A	Grading	Settlement	2003-2004		10

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Eden's Landing	3C	Inside	Maintain rip rap	Erosion	2003-2004	60	70
Eden's Landing	5	cross levee	Maintain rip rap	Erosion	2003-2004	40	50
Eden's Landing	5C	levee berm	Grading	Build up	2003-2004	3200	
Eden's Landing	8	Inside	Maintain rip rap	Erosion	2003-2004	100	200
Eden's Landing	8X	N/A	Grading	N/A	2003-2004	12	
Eden's Landing	9	Inside	Grading	Build up	2003-2004	800	
Eden's Landing	10	N/A	Maintain rip rap	Erosion	2003-2004	250	300
Eden's Landing	12	N/A	Grading	Build up	2003-2004	up to 1500	1500
Eden's Landing	13	cross levee	Grading	Settlement	2003-2004	750	
Eden's Landing	14	N/A	Grading	Build up	2003-2004	up to 2000	2000
Eden's Landing	1-14, 1C-5C, 6A, 6B, 6C, & 8A	N/A	Grading	N/A	2004-2005		
Eden's Landing	1	Inside	Grading	Erosion	2004-2005	250	300
Eden's Landing	1C	N/A	Dredge	Sediment	2004-2005	2400	100
Eden's Landing	2	N/A	Maintain rip rap	Erosion	2004-2005	500	1000
Eden's Landing	2	Inside	Maintain rip rap	Erosion	2004-2005	500	750
Eden's Landing	1C, 2C	N/A	Grading	Settlement	2004-2005		10
Eden's Landing	3C	Inside	Maintain rip rap	Erosion	2004-2005	60	70
Eden's Landing	5	cross levee	Maintain rip rap	Erosion	2004-2005	40	50
Eden's Landing	8	Inside	Maintain rip rap	Erosion	2004-2005	100	200
Eden's Landing	8X	cross levee	Grading	N/A	2004-2005	12	
Eden's Landing	10	N/A	Maintain rip rap	Erosion	2004-2005	250	300
Alviso	A1	N/A	Grading	N/A	1995-1996		
Alviso	A4-A18	N/A	Grading	N/A	1995-1996		
Alviso	A7	N/A	Dredge	Sediment	1995-1996		

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Alviso	A5	Majority of the levee system	Grading	Build up	1995-1996	25400	
Alviso	A6	Inside	Maintain rip rap	Erosion	1995-1996	2700	3500
Alviso	A6	Outside	Grading	Build up	1995-1996	2700	
Alviso	A7	N/A	Discing	N/A	1995-1996		
Alviso	A7	Majority of the levee system	Grading	Build up	1995-1996	16500	
Alviso	A8	Majority of the levee system	Grading	Build up	1995-1996	11500	
Alviso	A8	Inside	Grading	Build up	1995-1996		100
Alviso	A8	Majority of the levee system	Construct new lock	N/A	1995-1996		2000
Alviso	A9 - A12	Outside	Maintain rip rap	Erosion	1995-1996	2.5	21
Alviso	A10	Inside	Grading	Build up	1995-1996	500	
Alviso	A11	Inside	Grading	Build up	1995-1996		150
Alviso	A12	Inside	Grading	Build up	1995-1996		150
Alviso	A12	Spots along levee	Grading	Erosion	1995-1996	500	
Alviso	A13	Spots along levee	Grading	Erosion	1995-1996	500	
Alviso	A15	Spots along levee	Grading	Erosion	1995-1996	200	
Alviso	A16	N/A	Maintain rip rap	Erosion	1995-1996	150	180
Alviso	A22	N/A	Grading	N/A	1995-1996		
Alviso	A23	N/A	Grading	N/A	1995-1996		
Alviso	A2E	N/A	Discing	N/A	1995-1996		
Alviso	A2E	N/A	Grading	N/A	1995-1996		
Alviso	A2W	N/A	Grading	N/A	1995-1996		
Alviso	A3N	N/A	Discing	N/A	1995-1996		
Alviso	A3N	Outside	Maintain rip rap	Erosion	1995-1996	200	250
Alviso	A3N	N/A	Grading	N/A	1995-1996		
Alviso	A3W	Outside	Grading	N/A	1995-1996		

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Alviso	A3W	N/A	Grading	Build up	1995-1996	2500	
Alviso	A3W	N/A	Grading	N/A	1995-1996		
Alviso	B1	N/A	Discing	N/A	1995-1996		
Alviso	B1	N/A	Maintain rip rap	Erosion	1995-1996	150	180
Alviso	B1	N/A	Grading	N/A	1995-1996		
Alviso	B2	N/A	Discing	N/A	1995-1996		
Alviso	B2	N/A	Grading	N/A	1995-1996		
Alviso	A1-A23, AS2E, A2W, A3N, A3W, B1-B2	N/A	Grading	N/A	1996-1997		
Alviso	A1	N/A	Grading	Build up	1996-1997	1000	
Alviso	A2E	N/A	Discing	N/A	1996-1997		
Alviso	A2W	N/A	Grading	Build up	1996-1997	500	
Alviso	A2W	Outside	Maintain rip rap	Erosion	1996-1997	21	25
Alviso	A3N	Outside	Grading	Build up	1996-1997	1000	
Alviso	A8	N/A	Grading	Build up	1996-1997	2200	
Alviso	A9	N/A	Grading	Build up	1996-1997	1000	
Alviso	A9	Inside	Maintain rip rap	Build up	1996-1997	70	84
Alviso	A10	N/A	Grading	Build up	1996-1997	750	
Alviso	A10	Inside	Maintain rip rap	Erosion	1996-1997	70	84
Alviso	A11	Inside	Maintain rip rap	Erosion	1996-1997	70	84
Alviso	A16	N/A	Grading	Build up	1996-1997	8500	
Alviso	A16	Inside	Maintain rip rap	Erosion	1996-1997	75	90
Alviso	A17	Majority of the levee system	Grading	sedimentatio	1996-1997	9100	
Alviso	A19	N/A	Construct new lock	N/A	1996-1997		

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Alviso	A19	Majority of the levee system	Grading	Build up	1996-1997	12800	
Alviso	A23	N/A	Discing	N/A	1996-1997		
Alviso	A1, A4-A15	N/A	Grading	N/A	1997-1998		
Alviso	A1	N/A	Grading	Build up	1997-1998	1500	
Alviso	A2W	N/A	Grading	Settlement	1997-1998		
Alviso	A2W	N/A	Discing	N/A	1997-1998		
Alviso	A2W	N/A	Discing	N/A	1997-1998		
Alviso	A3W	Inside	Maintain rip rap	Erosion	1997-1998	10	12
Alviso	A3W	N/A	Grading	Build up	1997-1998	2500	
Alviso	A8	N/A	Grading	Build up	1997-1998	2200	
Alviso	A9	N/A	Discing	N/A	1997-1998		
Alviso	A10	N/A	Discing	N/A	1997-1998		
Alviso	A11	Inside	Maintain rip rap	Erosion	1997-1998	70	84
Alviso	A11, A12	N/A	Grading	Build up	1997-1998		150
Alviso	A12	Top	Discing	N/A	1997-1998		
Alviso	A12	N/A	Grading	Erosion	1997-1998	500	
Alviso	A13	Inside	Grading	Erosion	1997-1998	500	
Alviso	A15	Inside	Grading	Erosion	1997-1998	200	
Alviso	A16	Majority of the levee system	Grading	Build up	1997-1998	16800	
Alviso	A17	Majority of the levee system	Grading	Build up	1997-1998	10700	
Alviso	A17	N/A	Grading	Build up	1997-1998	250	
Alviso	A23	N/A	Discing	N/A	1997-1998		
Alviso	A23	N/A	Grading	Settlement	1997-1998	3000	
Alviso	B1	N/A	Discing	N/A	1997-1998		
Alviso	A3W	Inside	Maintain rip rap	Erosion	1997-1998*	100	150
Alviso	A5	Inside	Maintain rip rap	Erosion	1997-1998*	200	

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Alviso	A5	Road	Grading	Settlement	1997-1998*	200	
Alviso	A5	N/A	Grading	Settlement	1997-1998*	200	
Alviso	A7	N/A	Discing	N/A	1997-1998*		
Alviso	A10	N/A	Grading	Build up	1997-1998*	3100	
Alviso	A12	Inside	Maintain rip rap	Erosion	1997-1998*	465	285
Alviso	A12	Inside	Maintain rip rap	Erosion	1997-1998*	333	220
Alviso	A13	Inside	Maintain rip rap	Erosion	1997-1998*	333	220
Alviso	A13	N/A	Maintain rip rap	Erosion	1997-1998*	270	55
Alviso	A15	Inside	Maintain rip rap	Erosion	1997-1998*	330	65
Alviso	A15	Inside	Maintain rip rap	Erosion	1997-1998*	330	220
Alviso	A18	Majority of the levee system	Grading	Build up	1997-1998*	14200	
Alviso	A22	N/A	Grading	Erosion	1997-1998*	80	100
Alviso	A22	Inside	Grading	Build up	1997-1998*	1000	
Alviso	A22	Inside	Maintain rip rap	Erosion	1997-1998*	700	125
Alviso	A23	N/A	Grading	Erosion	1997-1998*	50	80
Alviso	B-1	N/A	Maintain rip rap	Erosion	1997-1998*	200	150
Alviso	A1-A23, A2E, A2W, A3N, A3W, B1-B2	N/A	Grading	N/A	1998-1999		
Alviso	A1	N/A	Grading	Build up	1998-1999	1500	
Alviso	A1	N/A	Grading	N/A	1998-1999	300	
Alviso	A2W	N/A	Grading	Settlement	1998-1999		
Alviso	A3W	Inside	Maintain rip rap	Erosion	1998-1999	230	45
Alviso	A3W	N/A	Grading	Build	1998-1999	2500	
Alviso	A7	N/A	Grading	Settlement	1998-1999	400	
Alviso	A8	N/A	Grading	Build up	1998-1999	2200	

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Alviso	A10	N/A	Grading	Erosion	1998-1999	750	
Alviso	A11	Inside	Maintain rip rap	Erosion	1998-1999	70	84
Alviso	A11, A12	N/A	Grading	Build up	1998-1999		150
Alviso	A12	N/A	Grading	Erosion	1998-1999	612	
Alviso	A12	Inside	Maintain rip rap	Erosion	1998-1999	125	150
Alviso	A13	Inside	Grading	Erosion	1998-1999	1010	
Alviso	A15	Inside	Grading	Erosion	1998-1999	547	
Alviso	A16	N/A	Discing	N/A	1998-1999		
Alviso	A17	N/A	Discing	N/A	1998-1999		
Alviso	A17	Spots along levee	Grading	Build up	1998-1999	650	
Alviso	A18	Majority of the levee system	Grading	Build up	1998-1999	14200	
Alviso	A18	N/A	Grading	Build up	1998-1999	13300	
Alviso	A19	Spots along levee	Grading	Build up	1998-1999	12800	
Alviso	A23	N/A	Grading	Settlement	1998-1999	3000	
Alviso	A23	N/A	Discing	N/A	1998-1999		
Alviso	A2W	N/A	Maintain rip rap	Erosion	1998-1999*	120	80
Alviso	A2W	Inside	Maintain rip rap	Erosion	1998-1999*	265	130
Alviso	A3N	N/A	Maintain rip rap	Erosion	1998-1999*	40	15
Alviso	B1	N/A	Maintain rip rap	Erosion	1998-1999*	155	135
Alviso	A5	N/A	Maintain rip rap	Erosion	1998-1999*	840	350
Alviso	A5	N/A	Grading	Build up	1998-1999*		100
Alviso	A7	N/A	Grading	Build up	1998-1999*		200
Alviso	A10	N/A	Grading	Levee Repair	1998-1999*	1500	
Alviso	A11	N/A	Grading	Levee Repair	1998-1999*	1800	

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Alviso	A1-A23, A2E, A2W, A3N, A3W, B1-B2	N/A	Grading	N/A	1999-2000		
Alviso	A1	Top	Grading	Build up	1999-2000	1500	
Alviso	A1	Cross levee	Grading	N/A	1999-2000	300	
Alviso	A2W	Spots along levee	Grading	Settlement	1999-2000		
Alviso	A2W	N/A	Maintain rip rap	Erosion	1999-2000	100	120
Alviso	A2W	Inside	Maintain rip rap	Erosion	1999-2000	500	300
Alviso	A3W	N/A	Grading	Build up	1999-2000	2500	
Alviso	A3N	N/A	Grading	Build up	1999-2000	1500	
Alviso	A5	N/A	Grading	settlement	1999-2000	1000	
Alviso	A7	N/A	Grading	N/A	1999-2000		
Alviso	A8	N/A	Grading	Build up	1999-2000	2200	
Alviso	A8	Top	Grading	Build up	1999-2000		
Alviso	A12	N/A	Grading	Erosion	1999-2000	500	
Alviso	A12	Inside	Maintain rip rap	Erosion	1999-2000	500	300
Alviso	A13	Inside	Grading	Erosion	1999-2000	500	
Alviso	A13	Inside	Maintain rip rap	Erosion	1999-2000	333	220
Alviso	A15	N/A	Grading	Build up	1999-2000		200
Alviso	A15	Inside	Grading	Erosion	1999-2000	200	
Alviso	A15	Inside	Maintain rip rap	Erosion	1999-2000	330	65
Alviso	A16	N/A	Grading	N/A	1999-2000	3000	160
Alviso	A17	N/A	Discing	N/A	1999-2000		
Alviso	A22	N/A	Grading	Erosion	1999-2000	800	
Alviso	A22	Cross levee	Grading	Build up	1999-2000	2500	
Alviso	A22	Inside	Maintain rip rap	Erosion	1999-2000	700	125

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Alviso	A23	N/A	Discing	N/A	1999-2000		
Alviso	B1	N/A	Maintain rip rap	Erosion	1999-2000	100	120
Alviso	B1	Cross levee	Discing	N/A	1999-2000		
Alviso	B2	Cross levee	Discing	N/A	1999-2000		
Alviso	A1-A23, A2E, A2W, A3N, A3W, B1-B2	N/A	Grading	N/A	2000-2001		
Alviso	A1	N/A	Grading	Build up	2000-2001	1500	
Alviso	A1	Cross levee	Grading	N/A	2000-2001	300	
Alviso	A2W	Spots along levee	Grading	Settlement	2000-2001		
Alviso	A2W	N/A	Maintain rip rap	Erosion	2000-2001	42	35
Alviso	A2W	Inside	Maintain rip rap	Erosion	2000-2001	500	300
Alviso	A3W	N/A	Grading	Build up	2000-2001	2500	
Alviso	A3N	N/A	Grading	Build up	2000-2001	580	
Alviso	A7	N/A	Discing	N/A	2000-2001		
Alviso	A8	N/A	Grading	Build up	2000-2001	2200	
Alviso	A8	Road	Grading	Build up	2000-2001		
Alviso	A10	N/A	Discing	N/A	2000-2001		
Alviso	A13	Inside	Grading	Erosion	2000-2001	500	
Alviso	A13	Inside	Maintain rip rap	Erosion	2000-2001	12	19
Alviso	A15	N/A	Grading	N/A	2000-2001		200
Alviso	A15	Inside	Grading	Erosion	2000-2001	200	
Alviso	A15	Inside	Maintain rip rap	Erosion	2000-2001	330	65
Alviso	A16	N/A	Grading	Build up	2000-2001	3000	160
Alviso	A16	N/A	Grading	N/A	2000-2001		

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Alviso	A1-A23, A2E, A2W, A3N, A3W, B1-B2	N/A	Grading	N/A	2001-2002		
Alviso	A1	N/A	Grading	Build up	2001-2002	1500	
Alviso	A2W	N/A	Grading	Settlement	2001-2002		
Alviso	A2W	N/A	Maintain rip rap	Erosion	2001-2002	100	120
Alviso	A2W	Inside	Maintain rip rap	Erosion	2001-2002	500	300
Alviso	A7	N/A	Discing	N/A	2001-2002		
Alviso	A8	N/A	Grading	Build up	2001-2002	2200	
Alviso	A8	Road	Grading	Build up	2001-2002		
Alviso	A10	Outside	Grading	Erosion	2001-2002	750	
Alviso	A13	Inside	Grading	Erosion	2001-2002	500	
Alviso	A13	Inside	Maintain rip rap	Erosion	2001-2002	333	220
Alviso	A15	N/A	Grading	N/A	2001-2002		200
Alviso	A15	Inside	Grading	Erosion	2001-2002	200	
Alviso	A15	Inside	Maintain rip rap	Erosion	2001-2002	330	65
Alviso	A16	Road	Grading	Build up	2001-2002	3000	160
Alviso	A16	Road	Grading	N/A	2001-2002		
Alviso	A17	N/A	Grading	N/A	2001-2002		
Alviso	A22	Cross levee	Grading	Build up	2001-2002	2500	
Alviso	A22	Inside	Maintain rip rap	Erosion	2001-2002	700	125
Alviso	A23	N/A	Discing	N/A	2001-2002		
Alviso	B1	Outside	Grading	Build up	2001-2002	3000	
Alviso	B1	N/A	Maintain rip rap	Erosion	2001-2002	100	120
Alviso	B1	Cross levee	Discing	N/A	2001-2002		
Alviso	B2	Cross levee	Discing	N/A	2001-2002		

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Alviso	A1-A23, A2E, A2W, A3N, A3W, B1-B2	N/A	Grading	N/A	2002-2003		
Alviso	A1	N/A	Grading	Build up	2002-2003	1500	
Alviso	A2W	N/A	Grading	Erosion	2002-2003	200	240
Alviso	A2W	N/A	Maintain rip rap	Erosion	2002-2003	100	120
Alviso	A2W	Inside	Maintain rip rap	Erosion	2002-2003	500	300
Alviso	A7	N/A	Discing	N/A	2002-2003		
Alviso	A8	N/A	Grading	Build up	2002-2003	2200	
Alviso	A8	Road	Grading	N/A	2002-2003	2000	
Alviso	A10	Cross levee	Grading	Build up	2002-2003	2600	
Alviso	A10	Outside	Grading	Erosion	2002-2003	750	
Alviso	A13	Inside	Grading	Erosion	2002-2003	500	
Alviso	A13	Inside	Maintain rip rap	Erosion	2002-2003	333	220
Alviso	A15	N/A	Grading	N/A	2002-2003		220
Alviso	A15	Inside	Grading	Erosion	2002-2003	200	
Alviso	A15	Inside	Maintain rip rap	Erosion	2002-2003	330	65
Alviso	A16	Road	Grading	N/A	2002-2003	3000	160
Alviso	A16	N/A	Grading	N/A	2002-2003		
Alviso	A17	Top	Grading	N/A	2002-2003		
Alviso	A22	Cross levee	Grading	Build up	2002-2003	2500	
Alviso	A22	Inside	Maintain rip rap	Erosion	2002-2003	700	125
Alviso	A23	N/A	Discing	N/A	2002-2003		
Alviso	B1	Outside	Grading	Build up	2002-2003	3000	
Alviso	B1	N/A	Maintain rip rap	Erosion	2002-2003	100	120
Alviso	B1	Cross levee	Discing	N/A	2002-2003		

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Alviso	B2	Cross levee	Discing	N/A	2002-2003		
Alviso	A1-A23, A2E, A2W, A3N, A3W, B1-B2	N/A	Grading	N/A	2003-2004		
Alviso	A2W	Spots along levee	Grading	Settlement	2003-2004	200	240
Alviso	A2W	N/A	Maintain rip rap	Erosion	2003-2004	100	120
Alviso	A2W	Inside	Maintain rip rap	Erosion	2003-2004	1000	900
Alviso	A3W	N/A	Grading	Build up	2003-2004	1500	
Alviso	A3W	Inside	Grading	Erosion	2003-2004	1000	
Alviso	A8	N/A	Grading	Build up	2003-2004	2200	
Alviso	A8	Road	Grading	Build up	2003-2004	2000	
Alviso	A9	Cross levee	Grading	Build up	2003-2004	4600	
Alviso	A9	Cross levee	Grading	Build up	2003-2004	3400	
Alviso	A10	Outside	Grading	Erosion	2003-2004	750	
Alviso	A10	Cross levee	Grading	Build up	2003-2004	31000	
Alviso	A10	N/A	Grading	Erosion	2003-2004	1500	
Alviso	A11	Cross levee	Grading	Build up	2003-2004	11000	
Alviso	A11	Cross levee	Grading	Build up	2003-2004	1400	
Alviso	A12	Cross levee	Grading	Build up	2003-2004	3400	
Alviso	A12	?Inside?	Grading	Erosion	2003-2004	2300	
Alviso	A13	Inside	Grading	Erosion	2003-2004	500	
Alviso	A13	Cross levee	Grading	Build up	2003-2004	2600	
Alviso	A13	?Inside?	Grading	Erosion	2003-2004	3200	
Alviso	A13	Cross levee	Grading	Build up	2003-2004	4200	
Alviso	A13	Inside	Maintain rip rap	Erosion	2003-2004	333	220
Alviso	A14	Cross levee	Grading	Build up	2003-2004	5000	

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Alviso	A15	N/A	Grading	build up	2003-2004		200
Alviso	A15	Inside	Grading	Erosion	2003-2004	200	
Alviso	A15	?Inside?	Grading	Erosion	2003-2004	2400	
Alviso	A15	Inside	Maintain rip rap	Erosion	2003-2004	330	65
Alviso	A16	Road	Grading	build up	2003-2004	3000	160
Alviso	A16	N/A	Grading	N/A	2003-2004		
Alviso	A17	N/A	Grading	N/A	2003-2004		
Alviso	A22	Cross levee	Grading	Build up	2003-2004	2500	
Alviso	A22	Inside	Maintain rip rap	Erosion	2003-2004	700	125
Alviso	B1	Top	Grading	Build up	2003-2004	3000	
Alviso	B1	N/A	Maintain rip rap	Erosion	2003-2004	100	120
Alviso	B1	Cross levee	Discing	N/A	2003-2004		
Alviso	B2	Cross levee	Discing	N/A	2003-2004		
Alviso	A1-A23, A2E, A2W, A3N, A3W, B1-B2	N/A	Grading	N/A	2004-2005		
Alviso	A2W	Inside	Maintain rip rap	Erosion	2004-2005	1000	900
Alviso	A9	Cross levee	Grading	Build up	2004-2005	4600	
Alviso	A9	Cross levee	Grading	Build up	2004-2005	3400	
Alviso	A9	N/A	Grading	Build up	2004-2005	3000	
Alviso	A10	Outside	Grading	Erosion	2004-2005	750	
Alviso	A10	Cross levee	Grading	Build up	2004-2005	31000	
Alviso	N/A	Inside	Grading	Erosion	2004-2005	1500	
Alviso	A10	N/A	Grading	Erosion	2004-2005	4000	
Alviso	A11	Cross levee	Grading	Build up	2004-2005	11000	
Alviso	A11	Cross levee	Grading	Build up	2004-2005	1400	

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Alviso	A11	N/A	Grading	Erosion	2004-2005	3000	
Alviso	A12	Cross levee	Grading	Build up	2004-2005	3400	
Alviso	A12	?Inside?	Grading	Erosion	2004-2005	2300	
Alviso	A13	Inside	Grading	Erosion	2004-2005	500	
Alviso	A13	Cross levee	Grading	Build up	2004-2005	2600	
Alviso	A13	N/A	Grading	Erosion	2004-2005	3200	
Alviso	A13	Cross levee	Grading	Build up	2004-2005	4200	
Alviso	A14	Cross levee	Grading	Build up	2004-2005	5000	
Alviso	A15	Inside	Grading	Erosion	2004-2005	200	
Alviso	A15	Inside	Grading	Erosion	2004-2005	2400	
Alviso	A15	Inside	Maintain rip rap	Erosion	2004-2005	330	65
Alviso	A16	N/A	Grading	N/A	2004-2005		
Alviso	A17	N/A	Grading	N/A	2004-2005		
Alviso	A22	Cross levee	Grading	Repair	2004-2005	2500	
Alviso	A22	Inside	Maintain rip rap	Erosion	2004-2005	700	125
Alviso	B1	?Outside?	Grading	Build up	2004-2005	3000	
Alviso	B1	N/A	Maintain rip rap	Erosion	2004-2005	100	120
Ravenswood	R1	N/A	Grading	Build up	1995-1996		
Ravenswood	R2	N/A	Grading	Build up	1995-1996		
Ravenswood	R3	N/A	Grading	Build up	1995-1996		
Ravenswood	R4	N/A	Grading	Build up	1995-1996		
Ravenswood	R5	N/A	Grading	Build up	1995-1996		
Ravenswood	R1	N/A	Grading	Build up	1995-1996	10000	
Ravenswood	R1	Outside	Riprap	Erosion	1995-1996	800	960
Ravenswood	R1	Inside	Grading	Build up	1995-1996		120
Ravenswood	R1	N/A	Grading	Build up	1995-1996		

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Ravenswood	R2	N/A	Grading	Build up	1995-1996		
Ravenswood	R4	Outside	Riprap	Erosion	1995-1996	30	40
Ravenswood	R4	Inside	Grading	Build up	1995-1996		90
Ravenswood	SF2	Inside	Riprap	Erosion	1995-1996	100	120
Ravenswood	SF2	N/A	Grading	Build up	1995-1996		
Ravenswood	S5	N/A	Grading	Build up	1995-1996		
Ravenswood	S5	N/A	Grading	Build up	1995-1996		240
Ravenswood	R1	N/A	Grading	Build up	1996-1997		
Ravenswood	R4	N/A	Grading	Build up	1996-1997		
Ravenswood	R1	N/A	Grading	Build up	1996-1997	5000	
Ravenswood	R1	Outside	Riprap	Erosion	1996-1997	400	500
Ravenswood	R1	N/A	Grading	Build up	1996-1997		
Ravenswood	R1	N/A	Grading	Build up	1996-1997	210	
Ravenswood	R4	N/A	Grading	Build up	1996-1997		
Ravenswood	R4	N/A	Grading	Build up	1996-1997	2000	
Ravenswood	R1	N/A	Grading	Build up	1997-1998		
Ravenswood	R2	N/A	Grading	Build up	1997-1998		
Ravenswood	R3	N/A	Grading	Build up	1997-1998		
Ravenswood	R4	N/A	Grading	Build up	1997-1998		
Ravenswood	R5	N/A	Grading	Build up	1997-1998		
Ravenswood	S5	N/A	Grading	Build up	1997-1998		
Ravenswood	SF2	N/A	Grading	Build up	1997-1998		
Ravenswood	R1	N/A	Grading	Build up	1997-1998		210
Ravenswood	R2	N/A	Grading	Build up	1997-1998		210
Ravenswood	R4	N/A	Grading	Build up	1997-1998		210
Ravenswood	S5	N/A	Grading	Build up	1997-1998		210

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Ravenswood	R1	N/A	Discing	N/A	1997-1998		
Ravenswood	R1	N/A	Grading	Build up	1997-1998	1900	
Ravenswood	R1	N/A	Grading	Build up	1997-1998	900	
Ravenswood	R1	Outside	Riprap	Erosion	1997-1998	400	500
Ravenswood	R2	Inside	Riprap	Erosion	1997-1998	25	30
Ravenswood	S5	N/A	Grading	Build up	1997-1998	2800	
Ravenswood	S5	N/A	Grading	Build up	1997-1998	1300	
Ravenswood	SF2	N/A	Grading	Build up	1997-1998	2800	
Ravenswood	SF2	Inside	Riprap	Erosion	1997-1998	100	120
Ravenswood	R2	N/A	Grading	Build up	1997-1998		
Ravenswood	R4	Outside	Riprap	Erosion	1997-1998	20	35
Ravenswood	R4	N/A	Riprap	Erosion	1997-1998	100	160
Ravenswood	R1	N/A	Grading	Build up	1998-1999		
Ravenswood	R2	N/A	Grading	Build up	1998-1999		
Ravenswood	R3	N/A	Grading	Build up	1998-1999		
Ravenswood	R4	N/A	Grading	Build up	1998-1999		
Ravenswood	R5	N/A	Grading	Build up	1998-1999		
Ravenswood	SF2	N/A	Grading	Build up	1998-1999		
Ravenswood	R1	N/A	Grading	Build up	1998-1999		180
Ravenswood	R2	N/A	Grading	Build up	1998-1999		180
Ravenswood	R1	N/A	Discing	N/A	1998-1999		
Ravenswood	R1	N/A	Grading	Build up	1998-1999	1020	
Ravenswood	R1	N/A	Grading	Build up	1998-1999	615	
Ravenswood	R1	N/A	Riprap	Erosion	1998-1999	2268	1295
Ravenswood	R1	N/A	Grading	Build up	1998-1999	6800	
Ravenswood	R2	Inside	Riprap	Erosion	1998-1999	25	30

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Ravenswood	R3	N/A	Grading	Build up	1998-1999	14800	
Ravenswood	R4	N/A	Grading	Build up	1998-1999	9400	
Ravenswood	R5	N/A	Grading	Build up	1998-1999	3400	
Ravenswood	S5	N/A	Grading	Build up	1998-1999	4000	
Ravenswood	SF2	N/A	Grading	Build up	1998-1999	5000	
Ravenswood	SF2	Inside	Riprap	Erosion	1998-1999	100	120
Ravenswood	R2	N/A	Grading	Build up	1998-1999	3450	
Ravenswood	R3	N/A	Grading	Build up	1998-1999	1758	
Ravenswood	R5	N/A	Grading	Build up	1998-1999	639	
Ravenswood	S5	N/A	Grading	Build up	1998-1999	531	
Ravenswood	R1	N/A	Grading	Build up	1999-2000		
Ravenswood	R2	N/A	Grading	Build up	1999-2000		
Ravenswood	R3	N/A	Grading	Build up	1999-2000		
Ravenswood	R4	N/A	Grading	Build up	1999-2000		
Ravenswood	R5	N/A	Grading	Build up	1999-2000		
Ravenswood	SF2	N/A	Grading	Build up	1999-2000		
Ravenswood	R1	N/A	Discing	N/A	1999-2000		
Ravenswood	R1	N/A	Riprap	Erosion	1999-2000	2270	1300
Ravenswood	R1	N/A	Grading	Build up	1999-2000	6800	
Ravenswood	R3	N/A	Grading	Build up	1999-2000	14800	
Ravenswood	R4	N/A	Grading	Build up	1999-2000	9400	
Ravenswood	R5	N/A	Grading	Build up	1999-2000	3400	
Ravenswood	S5	N/A	Grading	Build up	1999-2000	4000	
Ravenswood	SF2	N/A	Discing	N/A	1999-2000		
Ravenswood	SF2	N/A	Dreging	Sediment	1999-2000	800	
Ravenswood	SF2	Inside	Riprap	Erosion	1999-2000	100	120

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Ravenswood	R1	N/A	Grading	Build up	2000-2001		
Ravenswood	R2	N/A	Grading	Build up	2000-2001		
Ravenswood	R3	N/A	Grading	Build up	2000-2001		
Ravenswood	R4	N/A	Grading	Build up	2000-2001		
Ravenswood	R5	N/A	Grading	Build up	2000-2001		
Ravenswood	SF2	N/A	Grading	Build up	2000-2001		
Ravenswood	R1	N/A	Discing	N/A	2000-2001		
Ravenswood	R1	N/A	Riprap	Erosion	2000-2001	2270	1300
Ravenswood	R4	N/A	Riprap	Erosion	2000-2001		
Ravenswood	R4	N/A	Discing	N/A	2000-2001		
Ravenswood	R5	N/A	Discing	N/A	2000-2001		
Ravenswood	S5	N/A	Discing	N/A	2000-2001		
Ravenswood	SF2	N/A	Dreging	Sediment	2000-2001		800
Ravenswood	SF2	Inside	Riprap	Erosion	2000-2001	100	120
Ravenswood	R1	N/A	Grading	Build up	2001-2002		
Ravenswood	R2	N/A	Grading	Build up	2001-2002		
Ravenswood	R3	N/A	Grading	Build up	2001-2002		
Ravenswood	R4	N/A	Grading	Build up	2001-2002		
Ravenswood	R5	N/A	Grading	Build up	2001-2002		
Ravenswood	SF2	N/A	Grading	Build up	2001-2002		
Ravenswood	R1	N/A	Riprap	Erosion	2001-2002	2270	1300
Ravenswood	R2	N/A	Grading	Build up	2001-2002		130
Ravenswood	R3	N/A	Grading	Build up	2001-2002		
Ravenswood	R4	N/A	Discing	N/A	2001-2002		
Ravenswood	R4	N/A	Riprap	Erosion	2001-2002	100	120
Ravenswood	R5	N/A	Discing	N/A	2001-2002		

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Ravenswood	R5	N/A	Grading	Build up	2001-2002		
Ravenswood	S5	N/A	Discing	N/A	2001-2002		
Ravenswood	S5	N/A	Grading	Build up	2001-2002		
Ravenswood	SF2	Inside	Riprap	Erosion	2001-2002	100	120
Ravenswood	R1	N/A	Grading	Build up	2002-2003		
Ravenswood	R2	N/A	Grading	Build up	2002-2003		
Ravenswood	R3	N/A	Grading	Build up	2002-2003		
Ravenswood	R4	N/A	Grading	Build up	2002-2003		
Ravenswood	R5	N/A	Grading	Build up	2002-2003		
Ravenswood	SF2	N/A	Grading	Build up	2002-2003		
Ravenswood	R1	N/A	Riprap	Erosion	2002-2003	2270	1300
Ravenswood	R4	N/A	Discing	N/A	2002-2003		
Ravenswood	R4	N/A	Riprap	Erosion	2002-2003	100	120
Ravenswood	R5	N/A	Discing	N/A	2002-2003		
Ravenswood	S5	N/A	Levee Construction	Marsh Mitigation	2002-2003	1200	2600
Ravenswood	S5	N/A	Discing	N/A	2002-2003		
Ravenswood	SF2	Inside	Riprap	Erosion	2002-2003	100	120
Ravenswood	R1	N/A	Grading	Build up	2003-2004		
Ravenswood	R2	N/A	Grading	Build up	2003-2004		
Ravenswood	R3	N/A	Grading	Build up	2003-2004		
Ravenswood	R4	N/A	Grading	Build up	2003-2004		
Ravenswood	R5	N/A	Grading	Build up	2003-2004		
Ravenswood	SF2	N/A	Grading	Build up	2003-2004		
Ravenswood	R1	N/A	Grading	Build up	2003-2004		
Ravenswood	R2	N/A	Riprap	Erosion	2003-2004	2270	1300

APPENDIX D
CARGILL LEVEE MAINTENANCE SUMMARY
 South Bay Salt Ponds Restoration Project
 San Francisco Bay Area, CA

Unit	Pond	Location on Levee	Type of repair	Issue	Year	Size (l.f.)	Size (c.y.)
Ravenswood	R4	N/A	Discing	N/A	2003-2004		
Ravenswood	R4	N/A	Riprap	Erosion	2003-2004	100	120
Ravenswood	R5	N/A	Discing	N/A	2003-2004		
Ravenswood	S5	N/A	Levee Construction	Marsh Mitigation	2003-2004	1200	2600
Ravenswood	S5	N/A	Discing	N/A	2003-2004		
Ravenswood	SF2	Inside	Riprap	Erosion	2003-2004	100	120
Ravenswood	R1	N/A	Grading	Build up	2004-2005		
Ravenswood	R2	N/A	Grading	Build up	2004-2005		
Ravenswood	R3	N/A	Grading	Build up	2004-2005		
Ravenswood	R4	N/A	Grading	Build up	2004-2005		
Ravenswood	R5	N/A	Grading	Build up	2004-2005		
Ravenswood	SF2	N/A	Grading	Build up	2004-2005		
Ravenswood	R1	N/A	Riprap	Erosion	2004-2005	2270	1300
Ravenswood	R4	N/A	Discing	N/A	2004-2005		
Ravenswood	R4	N/A	Riprap	Erosion	2004-2005	100	120
Ravenswood	R5	N/A	Discing	N/A	2004-2005		
Ravenswood	S5	N/A	Discing	N/A	2004-2005		
Ravenswood	SF2	Inside	Riprap	Erosion	2004-2005	100	120