






**Legend**

-  Project Boundary
-  Historic Survey (1856)
-  Historic sloughs visible in contemporary aerial photos



Source: Orthophotos of Napa County, April, 2004; US Coastal Survey, 1856



Napa Plant Site  
Restoration Project  
26815044

Project Area with  
Historic Survey (1856)

Figure  
1-2

URS Corporation L:\Projects\Napa\_Plant\_Site\_26815044\MXD\Current Working Documents\Draft\ER\Figure\_1-2\Project\_Area\_with\_Historic\_Survey.mxd Date/Time: 1/13/2006 1:14:10 PM Name: dhwright0